

C 20

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No. F.6/DFS/MS/School/2024/SZ/ 911

Dated: 19/09/2024

FIRE SAFETY CERTIFICATE

Certified that the **B.V.M World School** is running at ground plus one upper floor only, a building comprised of basement, ground plus two upper floors located at Aggarwal Dharamshala Road, Opp. Police Station, Prem Nagar, Najafgarh, New Delhi-110043, owned/occupied by B.V.M Public School was issued Fire Safety Certificate by this department vide letter No F6/DFS/MS/School/2021/SZ/646 dated 24/08/2021. The school building was re- inspected by the officer concerned of this department on 09.09.2024 in the presence of Sh. Ajay Sharma (Manager) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 issued by the Director of Education and that the building/ premises (**ground and first floor only**) is fit for occupancy class "**Educational Building**" w.e.f. 19/09/24 for a period of three years, subject to compliance of the conditions printed as under.

Issued on 19/09/2024 at New Delhi by.


(Atul Garg)
Director
Delhi Fire Service

Copy to:-

1. The Manager, B.V.M World School located at Aggarwal Dharamshala Road, Opp. Police Station, Prem Nagar, Najafgarh, New Delhi-110043.
2. Director of Education, GNCT of NCT of Delhi, Old Secretariat, New Delhi- 110054.
3. Executive Engineer (Bldg.), Zonal Office MCD, Dhansa Stand, Najafgarh, New Delhi-110043. : - for information regarding use of basement.

Conditions for the validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

M/1~

INSPECTION REPORT

1. Name & address of the building : B.V.M World School, Aggarwal Dharamshala Road, Opp. Police Station, Prem Nagar, Najafgarh, New Delhi-110043
2. Building is comprised of : B, G+2 upper floors but school running at Ground and first floor only.
3. Type of Occupancy : Educational
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/School/2021/SZ/646 dated 24/08/2021
6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011
7. Date of inspection : 09.09.2024
8. Name of Inspecting Officer : A.D.O. R.K. Yadav
9. Name and designation of officers
From the building side : Sh. Ajay Sharma (Manager)
10. Year of Construction : 2013
11. Applicant's letter No. : Online email ID bvmworldschool@gmail.com dated 13.08.2024

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Requirement | Provided at site | Remarks MR/NMR |
|--------|--|---|---|---|
| 1. | Access to building | | | |
| | <ul style="list-style-type: none"> • Road width • Gate width • Width of internal road | Accessible 06 m 4.5 m N/A | 6.4 m Directly accessible from road N/A | MR M/R N/A |
| 2. | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | | | |
| | • Upper Floors | 01 no. | 02 no.'s | MR |
| | • Basements | N/A | N/A | Basement closed |
| | b. Width of staircases | | | |
| | • Upper Floor | 1.50m | 1.50 & 1.20 m | MR |
| | • Basements | N/A | N/A | Basement closed |
| | c. Protection of exits | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Pressurization | N/A | N/A | N/A |
| | d. No. of continuous staircases to terrace | Required | One | N/A |
| | e. Width of Corridor | 1.50 m | 2.05m | MR |
| | f. Door Size | 1.0 m | 1.10m | MR, students less than 45 in each class |
| 3. | Compartmentation | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Sealing of electrical shafts | N/A | N/A | N/A |
| | • Fire Rating of shaft door | N/A | N/A | N/A |
| | • Water Curtain | N/A | N/A | N/A |
| | • Fire Dampers | N/A | N/A | N/A |
| 4. | Smoke Management System | | | |
| | • Basements | Required | Provided | MR |
| | • Upper floors | Required | Natural Ventilation provided | MR |
| 5. | Fire Extinguishers | | | |
| | • Total numbers | 08 No's ABC/CO ₂ type ISI marked | Provided | MR |
| | • Types | | Provided | MR |
| | • IS marking | | ISI marked | MR |

15

h

N/14

| | | | | |
|-----|---|-----|-----|-----|
| 16. | Provision of Lifts. | | | |
| | <ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 17. | Standby power supply | N/A | N/A | N/A |
| 18. | Refuge Area. | | | |
| | <ul style="list-style-type: none"> ➤ Total Area ➤ Location | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 19. | Fire Control Room | | | |
| | <ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/School/2021/SZ/646 dated 24/08/2021, renewal under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

Note: - As per undertaking given by school management (placed at C-16) the school building comprised of basement, ground plus two upper floors but school running at ground and first floor only. Basement and second floor of school is closed and not usable (photo enclosed with undertaking).

R.K. Yadav
11/9/2024

Signature of Inspecting Officer
Name: - R.K. Yadav
Designation: - ADO (JKP)

D.O. (South West)

[Signature]
11/9/24

CFO (SZ)
[Signature]
11/9/2024

Director
[Signature]
11/9/24

ADP/SM