



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7-
आजमती
अमृत महोत्सव

No. F6/DFS/MS/WZ/EH/2024/ 303

Dated:- 18/09/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s. Echoes (A Unit of Hadhpalatable Foods Pvt. Ltd.), Located at, Property No. 3, First Floor, Block-J, Reserve Bank Enclave, Paschim Vihar, Delhi-110063 is running at First Floor only in a building comprised of Basement + Stilt + Upper Ground Floor + 03 Upper Floors owned/occupied by M/s. Echoes (A Unit of Hadhpalatable Foods Pvt. Ltd.) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on 03/09/2024 in the presence Sh. Harshit Mehta (Owner) and that the premises is fit for occupancy class "Assembly" Group D (Restaurant) for First Floor only with effect from 18/09/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 18/09/2024 at New Delhi by.

(Atul Garg)
Director
Tel No. 011-23414000

Copy to:-

1. The Joint Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi
2. The Dy. Health Officer, Keshav Puram Zone, NDMC, Public Health Department, A-1 Block Keshav Puram Zone, Delhi.
3. Sh. Harshit Mehta, M/s. Echoes (A Unit of Hadhpalatable Foods Pvt. Ltd.), Property No. 3, First Floor, Block-J, Reserve Bank Enclave, Paschim Vihar, Delhi-110063.

Following fire safety directives must be adhered to:-

1. This FSC is valid for restaurant area's First Floor only.
2. All the means of escape shall be kept free of all type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
7. All comments / directions of licensing Department shall always be permitted and followed.
8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
10. The basement shall be used as per BBL.

INSPECTION REPORT

1. Name & address of the building : M/s. Echoes (A Unit of Hadhpalatable Foods Private Limited, located at First Floor, Plot No. 3, Block-J, Reserve Bank Enclave, Paschim Vihar, Delhi-110063.
2. Type of Occupancy : Assembly, (Restaurant at First Floor)
3. Type of Case : New
4. Details of previous NOC : Nil
5. Fire Safety directives letter No : As per UBBL/NBC (Part-IV)
6. Date of inspection : 03/09/2024
7. Name of the Inspecting Officers : Aman Kumar Lathar, ADO (JWP)
8. Name and designation of officers from the building side : Sh. Harshit Mehta (Owner)
9. Year of Construction : 2019 (as per details upload on MHA portal)
10. Applicant's Online ID- : 2024081712822 dated 20/08/2024 & 2024082413113 dated 24/08/2024

| | |
|-----------------------------------|---------------------|
| Basement | : Vacant |
| Stilt | : Parking |
| UGF | : Restaurant |
| 1 st floor | : <u>Restaurant</u> |
| 2 nd & 3 rd | : Residence |

The said restaurant is running at First Floor in a building comprised of Basement, Stilt, Upper Ground Floor Plus Three Upper Floors only.

| S. No | Minimum Standards on fire prevention and fire safety U/R 33 | UBBL/NBC-IV requirements | Provided at site | Remarks MR/NMR |
|-------|---|--------------------------|---|----------------|
| 1 | Access to building | | | |
| | • Road width | 06 m | Provided | MR |
| | • Gate width | 4.5 m | Direct accessible from road | MR |
| | • Width of internal road | N/A | N/A | N/A |
| 2 | Number, Width, Type & Arrangement of Exits | | | |
| | a. Number of staircases | ----- | ----- | ----- |
| | • Upper Floors | 02 | 03 | MR |
| | • Basements | N/A | N/A | N/A |
| | b. Width of staircases | ----- | ----- | ----- |
| | • Upper Floors | 1.5 m each | 1.5 m x 1 (B to 1 st floor) 1.5 m x 1 (Stilt to 1 st , Iron made) 01 m x 1 (B to Terrace) | MR |
| | • Basements | N/A | 01 m x 1 & 1.5 m x 1 | N/A |
| | c. Protection of exits | ----- | ----- | ----- |
| | • Fire check door | Required | Provided | MR |
| | • Pressurization | N/A | N/A | N/A |
| | e. No. of continuous staircases to terrace | 02 | 01 (* Residence at 2 nd & 3 rd floor) | MR |
| | g. Width of Corridor | N/A | N/A | N/A |
| | h. Door Size | 1.5 m x 2 | Provided | MR |
| 3 | Compartmentation. | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Sealing of electrical shafts | N/A | N/A | N/A |
| | • Fire Rating of shaft door | N/A | N/A | N/A |
| | • Water Curtain | N/A | N/A | N/A |
| | • Fire Dampers | N/A | N/A | N/A |

| | | | | |
|----|---|---------------------------|---------------------|-------|
| 4 | Smoke Management System. | | | |
| | • Basements | NA | N/A | N/A |
| | • Upper floors | Required | Natural ventilation | MR |
| 5 | Fire Extinguishers | | | |
| | • Total numbers | 04 Nos. | Provided | MR |
| | • Types | ABC, CO ₂ type | Provided | MR |
| | • IS marking | ISI marked | Provided | MR |
| 6 | First-Aid Hose Reels. | | | |
| | • Total numbers on each floor | 01 | Provided | MR |
| | • Length of hose reel hose | 30 m | Provided | MR |
| | • Nozzle diameter | 5 mm | Provided | MR |
| 7 | Automatic fire detection and alarming system | | | |
| | • Type of detectors | N/A | Provided | N/A |
| | • Location of Main Panel | N/A | NA | N/A |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | • Alternate source of power | N/A | N/A | N/A |
| | • Hooters' Location | N/A | N/A | N/A |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System. | N/A | N/A | N/A |
| 10 | Automatic Sprinkler System | | | |
| | • Basement | N/A | N/A | N/A |
| | • Upper floors | N/A | Provided | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants | | | |
| | • Size of riser/down-comer | 100 mm | Provided | MR |
| | • Number of hydrants per floor | Required | Provided | MR |
| | • Hose Box | Required | Provided | MR |
| 12 | Yard Hydrants. | | | |
| | • Total number of hydrants | N/A | N/A | N/A |
| | • Hose Box | N/A | N/A | N/A |
| 13 | Pumping Arrangements | | | |
| | • Ground Level | --- | ----- | ----- |
| | ➤ Discharge of main Pump | N/A | N/A | N/A |
| | ➤ Head of Main pump | N/A | N/A | N/A |
| | ➤ Number of main pumps | N/A | N/A | N/A |
| | ➤ Jockey Pump out put | N/A | N/A | N/A |
| | ➤ Jockey pump head | N/A | N/A | N/A |
| | ➤ Standby Pump out put | N/A | N/A | N/A |
| | ➤ Standby Pump Head | N/A | N/A | N/A |
| | ➤ Auto Starting/ Manual stopping | N/A | N/A | N/A |
| | ➤ Pump House Access | N/A | N/A | N/A |
| | • Terrace level | ---- | ----- | ----- |
| | ➤ Discharge of pump | 450 LPM | Provided | MR |
| | ➤ Head of the pump | 40 mts | Provided | MR |

| | | | | |
|--|--|--------------|----------|-----|
| | ➤ Power Supply | Required | Provided | MR |
| | ➤ Auto Starting of pump | Required | Provided | MR |
| Captive Water Storage for fire fighting | | | | |
| | • Underground tank capacity | N/A | N/A | N/A |
| | ➤ Draw-off connection | N/A | N/A | N/A |
| | ➤ Fire service inlet | N/A | N/A | N/A |
| | ➤ Access to tank | N/A | N/A | N/A |
| | • Overhead Tank capacity | 20,000 ltrs. | Provided | MR |
| 15 | Exit Signage. | Required | Provided | MR |
| 16 | Provision of Lifts. | | | |
| | • Pressurization of Lift Shaft | N/A | N/A | N/A |
| | • Pressurization of Lift lobby | N/A | N/A | N/A |
| | • Communication In lift Car | N/A | N/A | N/A |
| | • Fireman's Grounding Switch | N/A | N/A | N/A |
| | • Lift Signage | N/A | N/A | MR |
| 17 | Standby power supply | Required | Provided | MR |
| 18 | Refuge Area. | | | |
| | ➤ Total Area | N/A | N/A | N/A |
| | ➤ Location | N/A | N/A | N/A |
| 19 | Fire Control Room | | | |
| | • Detector System Panel | N/A | N/A | N/A |
| | • Flow Switch Panel | N/A | N/A | N/A |
| | • PA System Panel | N/A | N/A | N/A |
| | • Batter backup | N/A | N/A | N/A |
| | • Building Floor Plans | N/A | N/A | N/A |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any: | N/A | N/A | N/A |

* Residence is located at 2nd & 3rd floor and not falls under the purview of DFS Act & Rules, Hence FSC of residential floors are not required. And this department has already issued FSC to Upper Ground Floor for Eating House vide letter no. F6/DFS/MS/WZ/EH/2023/269 dated 30/08/2023. If agreed, then shortcoming of two continuous staircase to terrace is not mandatory & be omitted.

The fire protection systems provided in the building were checked and found functional at the time of inspection. Shortcoming issued vide letter no. F6/DFS/MS/WZ/2024/270 dated 26/06/2024 found rectified.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety requirement under the rules, grant of Fire Safety Certificate is recommended under rule 35 of the Delhi Fire Service Rules, 2010 under the DFS Act, 2009.

Accordingly DFA is prepared & put up for approval please.

DCFO (W2)
11/9/2022

Aman Kumar Lathar
Asst. Divisional Officer (Jwalapuri)

300 MHA CFO 11/9/2022 Director