

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No F 6/DFS/MS/2024/School/WZ/ 918

Dated: 19 / 09/2024

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School, Samaipur, Delhi-110042 (School Id-1310045), comprised of Two blocks, Ground + One upper floor owned/occupied by Govt. School was granted FSC by this department vide letter No. F.6/DFS/MS/2021/School/WZ/830 dated 07.10.2021. The premises was re-inspected by the officer concerned of this department on 06.09.2024 in the presence of Mr. Suresh Kumar (Estate Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from 19 09 2029 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on 19 09 2024 at New Delhi

Ph; 011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi - 54.

OUL 2. The Principal, Govt. Girls Sr. Sec. School, Samaipur, Delhi-110042. (School Id-1310045) Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building: Govt. Girls Sr. Sec. School, Samaipur, Delhi-110042. 2. Type of Occupancy

: Educational 3. Type of Case

: Renewal (02 Blocks, Ground + One upper floor) 4. Details of Previous NOC : F.6/DFS/MS/2021/School/WZ/830 dated 07.10.2021 5. Fire Safety directives letter No : Director of Education Cir. dated 27.09.2021

6. Date of inspection : 06.09.2024.

7. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)

8. Name and designation of officers

From the building side : Mr. Suresh Kumar (Estate Manager)

9. Year of Construction 10. Applicant's letter No.

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Dir. Of Educational | Provided at site | Remarks | | | |
|-----------|---|------------------------|----------------------|---------|--|--|--|
| 1. | Access to building Educational MR/NMR | | | | | | |
| | Road width | Accessible | Accessible | MR | | | |
| | Gate width | Accessible | 4.5m | MR | | | |
| - | Width of internal road | NA | NA | NA | | | |
| 2. | Number, Width, Type & Arrangement of Exits | | | | | | |
| | d. Number of staircases | | | | | | |
| | Upper Floors | 04nos. | 06nos. | MR | | | |
| | Basements | NA | NA | NA | | | |
| | e. Width of staircases | | | | | | |
| | Upper Floor | 1.5m | Blk-I-2x 1.5m | MR | | | |
| | Basements | | Blk-II-3 x 1.5 & 1 x | | | | |
| | f. Protection of exits | NA | 1.43 | 274 | | | |
| | Fire check door | INA | NA | - NA | | | |
| | Pressurization | NA | D.T.A. | ļ | | | |
| | d. No. of continuous staircases to terrace | | NA | NA | | | |
| | e. Width of Corridor | NA NA | NA | NA | | | |
| | f. Door Size | NA NA | NA NA | NA | | | |
| | | NA | NA | NA | | | |
| 3. | Compartmentation | INA | NA | NA | | | |
| | Fire check door | | 120 | | | | |
| | Sealing of electrical shafts | NA | NA | NA | | | |
| | • Fire Rating of shaft door | NA | NA | NA | | | |
| | Water Curtain | NA | NA | NA | | | |
| | • Fire Dampers | NA NA | NA | NA | | | |
| 4. | | NA | NA | NA | | | |
| 4. | Smoke Management System | | | | | | |
| | Basements | 30 a/c per hour | NA | NA | | | |
| | Upper floors | 12 a/c per hour | Natural ventilated | | | | |
| 5. | Fire Extinguishers 12 a/c per nour Natural ventilated MR | | | | | | |
| | • Total numbers | | | | | | |
| | • Types | | 28nos. | MR | | | |
| | IS marking | ABC/CO2 | ABC-06/CO2-22 | MR | | | |
| 5. | First-Aid Hose Reels | ISI marked | Yes | MR | | | |
| | Total numbers on each floor | NTA | | | | | |
| | • Length of hose reel hose | NA NA | NA | NA | | | |
| | Nozzle diameter | NA NA | NA | NA | | | |
| '. | Automatic fire detection and alarming syst | NA NA | NA | , NA | | | |
| h | Type of detectors | NA | | | | | |
| | Location of Main Panel | | NA | NA | | | |
| | Location of Repeater Panel | NA | NA | NA | | | |
| | Control (in A Control of Control | NA | NA | NA | | | |

4/25

| | 340 | | | 1 2 | | |
|-----|--|-------|-----------|----------|--|--|
| | Alternate source of power | NA | NA | - | | |
| 8. | Hooters' Location | NA | NA | 1 | | |
| 9. | MOEFA | NA | NA NA | 1 | | |
| 10. | Public Address System | NA | NA NA | N | | |
| 10. | Automatic Sprinkler System | | | | | |
| | Basement | NA | NA | | | |
| | Ground & Upper Floors | NA | NA NA | N | | |
| 11 | Sprinkler above false ceiling | NA | | N | | |
| 11. | Internal Hydrants | 11/1 | NA | N. | | |
| | Size of riser/down-comer | NA |) NA | | | |
| | Number of hydrants per floor | NA | NA NA | N/ | | |
| 10 | Hose Box | NA | NA NA | N/ | | |
| 12. | Yard Hydrants | | I NA | N/ | | |
| | Total number of hydrants | NA | 274 | | | |
| 10 | Hose Box | NA | NA | NA NA | | |
| 13. | Pumping Arrangements | 11/1 | NA | NA | | |
| | Ground Level | NA | 274 | | | |
| | Discharge of main Pump | NA NA | NA | NA | | |
| | > Head of Main pump | | NA | NA | | |
| | Number of main pumps | NA | NA | NA | | |
| | ➤ Jockey Pump out put | NA | NA | NA | | |
| | > Jockey pump head | NA | NA | NA | | |
| | Standby Pump out put | NA | NA | NA | | |
| | Standby Pump Head | NA | NA | NA | | |
| | Auto Starting / Account of | NA | NA | NA | | |
| | ➤ Auto Starting/Manual Stopping ➤ Pump House Access | NA | NA | NA | | |
| | - amp House Access | NA | NA | NA | | |
| | Terrace level Discharge 6 | ų. | V 199-1-1 | NA | | |
| | Discharge of pumpHead of the pump | NA | NA | NA | | |
| | > Power Supply | NA | NA | NA NA | | |
| | Auto Starting of pump | NA | NA | NA | | |
| | | NA | NA | NA | | |
| 14. | Captive Water Storage for fire fighting | | | | | |
| | Underground tank capacity | NA | N/A | - I | | |
| | Draw-off connection | NA NA | NA NA | NA | | |
| * | Fire service inlet | NA NA | NA | NA | | |
| | Access to tank | NA | NA NA | NA | | |
| | Overhead Tank capacity | NA | NA NA | NA | | |
| 5. | Exit Signage. | NA | NA NA | NA NA | | |
| | Provision of Lifts. | | IVA | NA | | |
| | Pressurization of Lift Shaft | NA | | 11.4 | | |
| | Pressurization of Lift lobby | NA NA | NA NA | NA | | |
| | Communication In lift Car | NA NA | NA NA | NA NA | | |
| | Fireman's Grounding Switch | NA | NA NA | | | |
| | Lift Signage | NA | NA NA | NA | | |
| 7. | Standby power supply | NA NA | | NA | | |
| 18. | Refuge Area. | 147 | NA] | NA | | |
| | > Total Area | NA | 274 | 72020 | | |
| | > Location | NA NA | NA NA | NA | | |
| 19. | Fire Control Room | .141 | NA | NA | | |
| | Detector System Panel | NA | NA | | | |
| | Flow Switch Panel | NA | NA NA | NA NA | | |
| | PA System Panel | NA | NA | NA NA | | |
| | | NA | NA | NA | | |

(P



NA NA NA Battery backup **Building Floor Plans** · NA NA Special Fire Protection System for NA Protection of special Risks, if any: The fire protection systems provided in the building were test checked and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures required stipulated in Director of Education Circular, the FSC issued vide letter no. F.6/DFS/MS/2021/School/WZ/830 dated 07.10.2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010. Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini) AT letter is port up for kind peursal and Signature Dease