## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/Institutional/2024/SZ/570

Dated: 20/99.../2024

## FIRE SAFETY CERTIFICATE

Certified that the Nursing Home located at Plot No- J-4, Green Park, Extension, New Delhi 110020 comprised of Basement, Stilt, Ground plus Three Upper Floor owner/ occupied by Mr. Joginder Kumar Goyal & Mrs. Punam Goyal have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on 10/09/2024 in the presence of Mr. Avinash and found that the said building / premises is fit for occupancy class "Institutional Building" with effect from 20/09/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 20.09./2024 at New Delhi by

Copy to:

The Executive Engineer (Bldg-1) Municipal Corporation of Delhi Building Department,-I, Green Park Zone, New Delhi 110016.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.


4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of

UBBL- 2016), if any.

The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.






		Cille	आज़ादी <sub>न</sub> अमृत म	नहोत्सव	
1	Name & Address Cd T	ON REPORT		~	
	Name & Address of the Building	Nursing Home	e located at Plot No- J-4 w Delhi.		
2	Type of Occupancy	Institutional Building (Nursing Home)			
3	Building Comprised of	Basement, Stilt, Ground plus Three Upper Floors			
4	Type of Case	New Case			
/5	Details of Previous NOC	Nil ATOM S			
6	Fire Safety Directives Letter No	F6/DFS/MS/2024/BP/136 dated 03/05/2024			
7	Date of Inspection	10/09/2024	A rationary enumeral.	.01	
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Avinash			
10	Year of construction	2023	attention the last print	11	
11	Applicant letter No.	Outdoor Diary no 5549 dated 22/08/2024			
. No	Minimum standards on Fire Prevention	UBBL-2016	Provided at Site	Remark MR/NM	
. 110	and Fire Safety U/R 33	requirement	and south a	MIK/NIVI	
1	Access to Building.		The state of the state of	MR	
	Road width	09 mtr	24 mtr	0.554.556	
YI.	Gate width	06 mtr	06 mtr	MR	
	Width of internal road	N/A	Iname and N/A and ment	N/A	
	Number, width, type & arrangement of exits		Filed Transfer *		
2		A Brown	nui lo agraduatsi >		
	a. Number of Staircase	02 No's	02 No's	MR	
	Upper floors Basement floor	02 No's	02 No's	MR	
			andrini savesi		
	b. Width of Staircase	1.50 m & 2m	1.50 m & 2m	MR	
	Upper floors	1.50 m & 2m	1.50 m & 2m	MR	
	Basement floor	1.50 m & 2m	TOTAL VIOLENCE WHI		
	c. Protection of exits	Souther was street	an August Lauren An	MR	
	Fire check door	Required	Provided	MR	
	Pressurization	Required	Provided	MR	
	d. No. of continuous staircase to terrace	02 Nos	Provided		
	e. Width of corridor	2.40 mtr	Provided	MR	
		2m & 1.25 m	Provided -	MR	
	f. Door size	जुनातिका गरी न	Lagrante sommer simple?	M	
3	Compartmentation.	Required	Provided	MR	
1	Fire check door.	Required	Provided	MR	
	• Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.				
4.	Smoke Management system.  Basement	12 ACPH	Exhaust fan Provided	MR	
	Upper floors	12 ACPH	Exhaust fan Provided	MR	
	Extinguishers		110 Nos	MR	
5.	Total numbers	95 Nos	Provided	MR	
	Types ISI Marking	ABC / Co2 ISI Marked	Provided	MR	
L	VI Vice Reels.		Parities against the land	MR	
6.	First Aid Hose Reels.  Total numbers on each floor.	02 at each floor	Provided	MR	
	Length of hose-reel hose.	30 m	Provided		
	Nozzle Diameter  Automatic Fire Detection & Alarming Systems  Automatic Fire Fire Fire Fire Fire Fire Fire Fire	5 mm	Provided	MR	
			Artes A review A real		

 $\sim$ 

dayti	Type of detectors	Smoke / heat	आज़ाकी अमृत मे	
	Location of Main Panel	Required	Provided	MR
	Location of Repeater Panel	N/A	N/A	MR
		Required	Provided Provided	N/A
	Hooter's location	Required	Provided	MR
	MOEFA	Required	Provided	MR
8.				MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		31112	
	Basement  Still Good	Required	Provided	MR
	Suit Hoor	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.		07-1000 (Ponte)	
71	Size of Riser / Down-comer	Required	Provided	MR
Ronne	Number of Hydrant per floor	Required	Provided	MR
	Hose box.	Required	Provided	MR
12.	Yard Hydrants.	27/4	NT/A	****
71.2	Total number of hydrants.	N/A	N/A	N/A
MAU.	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.	alla Vallanta et al	Number with have been	
	Ground Level	1620 LPM	Provided	MR
	Discharge of main pump.	70m	Provided	MR
15	➤ Head of main pump.	02 No	Provided	MR
M	Number of main pumps.	180 LPM	Provided	MR
	> Jockey Pump output.	70m	Provided	MR
16/	<ul> <li>Jockey Pump head.</li> <li>Standby Pump output.</li> </ul>	1620 LPM	Provided	MR
	> Standby Pump output. > Standby Pump head.	70m	Provided	MR
14	> Auto Starting / Manual Stopping.		Provided	MR
	> Pump House Access	Required	Descrided	MR
M	Regulard Provided	Required	100f A Provided	IVIIC
	Terrace Level	N/A	N/A	N/A
W	Discharge of pump.	N/A	N/A	N/A
M	<ul><li>➤ Head of pump.</li><li>➤ Power supply.</li></ul>	N/A	N/A	N/A
	<ul><li>Power supply.</li><li>Auto starting of pump.</li></ul>	N/A	N/A tool? .7	N/A
14.	Captive water storage for fire fighting.	1411	Companies alama.	8.
14.	Underground tank capacity.	75,000 ltrs	Provided	MR
NX.	> Draw-off connection.	Required	Provided	MR
IV.	D Fire Service Inlet	Required	Provided	MR
M.	Access to tank.	Required	Provided	MR
7	Overhead tank capacity.	10,000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		Highty Edit A. 18	
3	Pressurization of lift shaft.	Required	Provided •	MR
590	Pressurization of lift lobby.	Required	Provided	MR
(4)	Communication in lift car.	Required	Provided	MR
7	Fireman's switch.	Required	Provided	MR
· ·	Lift signage.	Required	Provided	MR
17	Standby Power Supply		Provided (DG set)	MR
18.	Refuge Area	Required	and and the Total	
10.		AVA P T Date	N/A	N/A
0	Total area     Location	N/A	N/A N/A	N/A
	Fire Control Room.	N/A	N/A	TANY

N

1



N/A	N/A
N/A	N/A
N/A	N/A

20.	Special Fire Protection System for the Protection of special Risk, if any.	Required	Provided	MR
	PA system Panel.     Battery backup     Building floor plan	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	<ul> <li>Detector System Panel.</li> <li>Flow Switch Panel.</li> </ul>	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 458 dated 19/08/2024.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

As approved, F.t. Letter in for your symature 01