

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/GH/2024/SZ/376 No.

Dated: 1.8./.09./2024

FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style of M/s The R Blues located at A-79, NH-8, Mahipalpur Extn. New Delhi- 110037 comprised of Basement, ground plus two upper floors and a staff room at terrace (Total- 13 Guest Room) owner/occupied by Unit of Hotel The R Blues was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2021/SZ/439 dated 29/09/2021. The premise was reinspected by the officer concerned of this department on 11/09/2024 in the presence of Mr. Vinod Sehrawat (Partner) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (Guest House with 13 Guest rooms) and Validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

18 | 09/2024 at New Delhi by

DIRECTOR DELHÍ FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID No 2024060708963 dated 02/08/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





1	Name & Address of the Building	ON REPORT M/s The R Blues Guest House (A Unit of hotel The R Blues) at A-79, NH-8, Mahipalpur Extn. New Delhi- 110037			
2	Type of Occupancy				
3	Building Comprised of	Residential, "Group-A" (Guest House) Basement, Ground + 02 upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/GH/2021/SZ/439 dated 29/09/2021			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	11/09/2024			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Vinod Sehrawat			
10	Year of construction	2003 Total 13 Guest room			
11	Applicant letter No.	MHA Portal ID No 2024060708963 dated 02/08/2024			
. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Provided at Site Remarks		Remarks MR/NMR	
1	Access to Building.		wint op to a		
	Road width	Required	06 mtr	MR	
	Gate width	-NA-	Directly accessible form road	-NA-	
1.50	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.	Gent	Figure of memory		
4	a) Number of Staircase	ALDERIA N	sovite remain 4		
1 10	➤ Upper floors.	Required	Ol Nos	MR	
1 3	➤ Basement floor.	Required	02 Nos	MR	
dut-	b) Width of Staircase	attilities	SSET PERMIT		
ATY	➤ Upper floors	Required	1.03 mtr	MR	
2.7	➤ Basement floor	Required	1.03 & 0.87 mtr	MR	
	c) Protection of exits	As per clause 7.31 of UBBL 2016			
	➤ Fire check door	Required	Provided	MR	
	➤ Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	Required	01 Provided	MR	
	e) Width of corridor	-NA-	-NA-	-NA-	
	f) Door size	1m	1.60 mtr (Final Exit)	-NA-	
3	Compartmentation.	- white the	1 1.00 min (1 min EXIL)	IVIK	
	Fire check door.	-NA-	-NA-	-NA-	
AY	Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
T.	Water curtain	-NA-	-NA-	-NA-	
\$103	Fire dampers	-NA-	-NA-	-NA-	
4	Smoke Management system.	- Arthury	7.31 of UBBL 2016	-1474-	
	Basement	30 ACPH	Exhaust fan provided	i MR	
	Upper floors	12 APCH			
5	Fire Extinguishers.	in Cit	Exhaust fan provided	MR.	
	Total numbers	12 Nos			
	Types	ABC / CO2	Provided	MR	
	ISI Marking	ISI marked		MR	
6	First Aid Hose Reels.	151 marked	Provided	MR	
	Total numbers on each floor				
17		One	Provided	MR	
	Length of hose-reel hose.	30 mtr	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
7	Automatic fire detection & alarming system		7.31 of UBBL 2016	IVIR	

Pay

1

		M24	आज़ाद अमृत	ो _{का} न महोत्सव
				MR
	Type of detectors	CO. Mo. type	Provided	MR
70 7	Location of Main Panel	Required	Provided	-NA-
mari na su		-NA-	-NA-	MR
is a requ	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power		Provided	MR
	Hooter's location	Required	Provided	The second secon
8 M	IOEFA	Required	Provided	MR
	ublic Address System	Required	and more afficient of the	1 100
	utomatic Sprinkler System		Provided	MR
10 11	Basement	Required	-NA-	-NA-
	Upper floors.	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	Peter Spie V	6
		- puultON	-NA-	-NA-
11 I	nternal Hydrants.	-NA-	-NA-	-NA-
	Size of Riser/Down-comer	-NA-		-NA-
	Number of Hydrant per floor	-NA-	-NA-	Total by
C ROWER	Hose box.	mallo per enten	The management	-NA-
12 3	Yard Hydrants.	-NA-	-NA-	-NA-
1. 18 8	Total number of hydrants.	-NA-	-NA-	1
	Hose box.	TWA	Martin a.	
13 I	Pumping arrangements.		110107-77-17	-NA-
13 4	Ground Level	-NA-	-NA-	-NA-
1.17	Discharge of main pump.		-NA-	
D11	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	▶ Tockey Pump output.	-NA-	-NA-	-NA-
AM.	▶ Iockey Pump head.	-NA-	-NA- 14- 1	-NA-
20-7	Standby Pump output.	-NA-	-NA-	-NA-
	Grandhy Dump head.	-NA-	-NA-	-NA-
5124	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
3917	> Pump house access.	-NA-	C 20 18 74 18	
	Terrace Level		450 LPM	MR
RISO C	Discharge of pump.	450 LPM	35 m	MR
Ail		35 m	Provided	MR
and T	Head of pump.Power supply.	Provided	Provided	MR
	Auto starting of pump.	Provided	Flovided	
70.74	C. Aire water storage for fire fighting.		NA	-NA-
14	Underground tank capacity.	-NA-	The A. Charles and Co.	-NA-
766	> Draw-off connection.	-NA-	-NA-	MR
g.	Fire Service Inlet.	Required	Provided	-NA-
7 - 1	Access to tank.	-NA-	-NA-	
5-1-1	Overhead tank capacity.	5,000 ltrs	5,000 ltrs	MR
		Required	Provided	MR
15	Exit Signage.		talke Jaff 3	
16	Provision of Lifts.	-NA-	-NA-	-NA-
911	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
30%	Communication in lift car.	-NA-	-NA-	-NA-
553.0	Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.	Required	Provided	
17	Standby Power Supply	required	TIOVIGE	MR
18	Refuge Area	-NA-	-NA-	1 371
100	• Iotal area			-NA-
7 914	Location	-NA-	-NA-	-NA-
19	Fire Control Room.	- 11	- W. W. W. W. W.	
	 Detector system panel. 	-NA-	-NA-	-NA-





	374	-NA-	-NA-
miitah nanal	-NA-	-NA-	
PA system panel. Battery backup. Partition floor plan.	-NA-	-NA-	-NA-
		-NA-	-NA-
		-NA-	-NA-
			-NA-
	Battery backup. Battery backup. Battery backup.	PA system panel. PA system panel. Battery backup. Partition floor plan. -NANANA-	PA system panel. Battery backup. -NANANANANANANAN

The fire protection system provided in the building were randomly checked and found functional at the time of inspection. The fire safety arrangement is already provided in the basement

as per the requirement of incidental storage of the building.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/439 dated 29/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Pilicer Name: Sh. Manoj Kumar Shampa

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

'n

d

20 It o e, '8 D

CFO (HQ)

Dirch

As appoored, Fit letter in portry

seemed approve