

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

F.6/DFS/MS/EH/2024/SZ/ 312

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s 6 Ballygunje Place located at Unit nos G7R3 and G8R, Ground Floor, Eldeco Centre, Malviya Nagar, New Delhi 110017 comprised of 03 Tiers Basement, Ground plus Three Upper Floors owned/occupied by Unit of Savourites Hospitality Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 19/09/2024 in the presence of Mr. Anshuman Dutta and that the premise is fit for occupancy class Group-D Assembly Building (Restaurant at Ground floor only) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 25/09/2024 at New Delhi by

Copy to: -

1. The Addl. Commissioner of Police Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049 (Ref MHA Portal ID 2024083113445 dated 31/08/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of BBL /NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBLof 2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



1	Dichecom	ON DEDODE		3. Ps.		
1	Name & Address of the Building	M/s 6 Ballygunje Place (Unit of Savourites Hospitality Pvt Ltd) Unit nos G7R3 and G8R, GF, Eldeco Centre Malviya Nagar, New Delhi 110017				
2	Type of Occupancy	Restaurant at Ground Floor only				
3	Building Comprised of	03 Basement, Ground plus Three Upper Floor				
4	Type of Case	New Case				
5	Details of Previous NOC	Nil				
6	Fire Safety Directives Letter No	F.6/MS/DFS/BP/2022/58 dated 18-02-2022				
7	Date of Inspection	19/09/2024				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers	Mr. Anshuman Dutta				
10	from the building side	2023	mat/498/7 *			
10	Year of construction	MHA Portal ID 2024083113445 dated 31/08/2024				
11	Applicant letter online ID.	Directive Provided at Site Remarks				
S. No.	Minimum standards on Fire Prevention			MR/NMR		
THE STATE OF	and Fire Safety U/R 33	Building FS	C F6/DFS/MS/Mixed/2	023/8Z/68		
1	Access to Building.	-	dated 08/02/2023			
- 12	Road width	18 mtr	Provided	MR		
	Gate width	6 mtr	Provided	MR		
	Width of internal road	6 mtr	Provided	MR		
214	Number, width, type & arrangement of ex	cits.	A STATE OF THE PARTY OF THE PAR	ng g, .:		
2116	a) Number of Staircase	Provided ar	nd maintained by MR7	Sistation		
	> Upper floors.	NA	Provided	NA		
	Required between	NA	Provided	NA		
	➤ Basement floor.	IM	PANT T STATE OF SA			
300	b) Width of Staircase	.01	T 15 - 0 0 - 1 2	NA		
72	➤ Upper floors	NA	1.5m x 2, 2 mtr x 2 1.5 m x 2 & ramp 4.50	1770		
2	AM AM	NA	m each	NA		
	> Basement floor		in Cacii			
period 200	c) Protection of exits	Dominal	Provided	MR		
SIE	> Fire check door	Required Required	Provided	MR		
62.7.7	> Pressurization	04 Nos	Provided	MR		
	d) No. of continuous staircase to terrace	1 D#10#11#100m3#1	Provided	MR		
2164	e) Width of corridor	Required	1.50 mtr each	MR		
-	f) Door size	1.50 mtr each		13000000000		
3	Compartmentation.	Provided and maintained by MRTS Station				
More	Fire check door.	Required	Provided	MR		
Real Property	 Sealing of electrical shafts. 	Required	Provided	MR		
800	Fire rating of shaft door.	Required	Provided	MR		
gh/	Water curtain	N/A	N/A	N/A		
3812	Fire dampers.	N/A	N/A	N/A		
4	Smoke Management system.	Provided ar	nd maintained by MR?	FS Station		
1,11	Basement	N/A	N/A	N/A		
	Upper floors	12 ACPH	Exhaust fan provided	MR		
5	Fire Extinguishers.		Jacob and	58 6		
3	Total numbers		05 Nos	MR		
-751	Total numbers Types	ISI marked	W. CO ₂ , DCP & CO ₂	MR		
	ISI Marking	101 Hilliand	Provided	MR		
(1.01.6)	First Aid Hose Reels.	Drovidad as	nd maintained by MR			
6		I TOVIDEU AL	Near restaurant	MR		
201-	Total numbers on each floor.	779353 5 0001				
1124	Length of hose-reel hose.	Hose Reel	30m	MR		
707	Nozzle Diameter		5mm	MR		
7	Automatic fire detection & alarming system.	nd maintained by MR				
	Type of detectors	Required	Provided	MR		
21	Location of Main Panel	Required	Provided	MR		
	Location of Repeater Panel	N/A	N/A	N/A		
	Totation of repeater Failer			100		
-	Alternate source of power	Required	Provided	MR		
		Required All floor	Provided Provided	MR MR		

	413		आज़ात अमृ	त्रका त महोत्स	
9	Public Address System	Required	Provided	MR	
10 0	Automatic Sprinkler System	Provided and maintained by MRTS Station			
	Basement	Required	Provided	MR	
	Upper floors	Required	Provided	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants.		d maintained by MR	S Station	
	Size of Riser/Down-comer	150 mm	Provided	MR	
	Number of Hydrant per floor	06 Nos	Provided	MR	
	Hose box.	06 Nos	Provided	MR	
12	Yard Hydrants.	W0001012 (11110-07)	d maintained by MR7		
	Total number of hydrants.	Required	07 Nos Provided	MR	
	Hose box.			MR	
13	Pumping arrangements.	Required	07 Nos Provided	MIK	
12817	Ground Level	Dronidad	d maintained by 1 mg	C Cassin	
ø'n.	Discharge of main nump	2850 LPM	d maintained by MR	S Station MR	
9/28	> Head of main pump.	70m	Provided Provided	MR	
JD7	Number of main pumps.	Two	Provided	MR	
	Jockey Pump output.	180 LPM	Provided	MR	
	> Jockey Pump head.	70m	Provided	MR	
	 Standby Pump output. Standby Pump head. 	2850 LPM	Provided	MR	
(GL)	> Auto Starting/Manual Stopping.	70m	Provided	MR	
12	> Pump house access.	Required	Provided	MR	
	Terrace Level	Required	Provided	MR	
	Discharge of pump.	N/A	7000 to 10 10 5	27/4	
	> Head of pump.	N/A	N/A	N/A N/A	
102	Power supply.	N/A	N/A	N/A N/A	
	➤ Auto starting of pump.	N/A	N/A	N/A	
14	Captive water storage for fire fighting.	Provided ar	d maintained by MR'		
807	Underground tank capacity.	2,00,000 Ltrs	Provided	MR	
	> Draw-off connection.	Required	Provided	MR	
301	Fire Service Inlet.	Required	Provided	MR	
	Access to tank.	Required	Provided	MR	
	Overhead tank capacity. P. 't S'	30,000 Ltr	Provided	MR	
15 16	Exit Signage. Provision of Lifts.	Required Provided or	Provided nd maintained by MR'	MR CC Station	
10	and a second control of the second control o	Required	MR		
guz	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Required	Provided Provided	MR	
	Pressurization of lift lobby.	Required	Provided	MR	
	Communication in lift car.		Provided	MR	
		Required	MARKET AND MARKET STREET		
ATT	Lift signage.	Required	Provided	MR	
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area	NT/A	N/A	N/A	
	Total area	N/A N/A	N/A	N/A	
511	• Location W Les Part 281		nd maintained by MR		
19	Fire Control Room.	Required	Provided Provided	MR	
	Detector system panel.	Required	Provided	MR	
SW.	Flow switch panel.	Required	Provided	MR	
	PA system panel.	Required	Provided	MR	
MY.	Battery backup.	Day of the same of the same	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MR	
		Required	Provided		
20	Special Fire Protection System for the Protection of special Risk, if any.	CO ₂ type fire for HT / LT	extinguishers provided panel & Transformer	MR	

blow in the same of



The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of Inspection Officer Name: Sh. Manoj Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

sprowed, F.T. letter is pullip