

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6/DFS/MS/GH/2024/SZ/ 383

Dated: 25/09./2024

## FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style of M/s Hotel Star Inn located at A-206, Street No-9, Road No 4, Mahipalpur New Delhi 110037 comprised of Lower ground, Ground plus three upper floors (LG Parking), Ground floor - Rec. & 03 Guest room, 1st floor to 3rd floor (08 guest room each) total 27 guest room owner/occupied by Mr. Jai Singh was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2021/SZ/406 dated 22/09/2021. The premise was re-inspected by the officer concerned of this department on 11/09/2024 in the presence of Mr. Ashish (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" and Validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the doniditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 25 09 /2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic/Branch), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024082813267 dated 28/08/2024)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



-	Name & Address of the Building	Hotel Star Inn A	206 00		
2	Type of Occupancy	Mahinalour No	-206, Street No 9, Ro	oad No 4,	
3	Building Comprised of	Mahipalpur, New Delhi- 110037  Residential, "Group-A" (Guest House)			
4	Type of Case	Lower Ground Co	p-A" (Guest House)		
5	Details of Previous NOC	Renewal	ound +03 upper floors	18 8	
6	Fire Safety Disasti		001/07/405 1 1555	0	
7	Fire Safety Directives Letter No Date of Inspection	Nil	021/SZ/406 dated 22/0	9/2021	
8	Name of the I	11/09/2024			
9	Name of the Inspecting Officers				
	Traile & Designation of Occ	DO (South) & ADO (BCP) Mr. Ashish (Manger)			
10	from the building side	Mi. Ashish (Manger)			
11	Year of construction	2002 Total 2	7 Guard source		
S. No.	Applicant letter No.	Total 27 Oucst 100111			
S. 140.	Minimum standards on Fire Prevention	MHA Portal ID 2024082813267 dated 28/08/20 Old NOC Provided at Site Rem			
1	and Fire Safety U/R 33	requirements	Provided at Site	Remarks	
2757	Access to Building.	CHAPTY?	The new market of the	MR/NMF	
	Road width	6 mtr	6 mtr	MR	
	Gate width	-NA-	-NA-	-NA-	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits	A Squirang each	-110-	-IVA-	
	a) Number of Staircase	14 min	or a second for the second second		
14.14	Upper floors.	01	Provided	MR	
- 17	▶ Basement floor.	-NA-	THE STREET STREET		
- 36	b) Width of Staircase	-INA-	demonstration of	-NA-	
	> Upper floors	1.25 mtr	County trifliantie St.	1 10	
	> Basement floor	I WASTERVACORE -	1:31 mtr 🤸	MR	
- 4	c) Protection of exits	NA-	-NA-	-NA-	
X87.14	Fire check door	As per clause 7.31 of UBBL 2016			
	> Pressurization	Required	Provided	MR	
58977		-NA-	ug to sum-NA-!	-NA-	
	d) No. of continuous staircase to terrace	Required	One	MR	
603	e) Width of corridor	-NA-	-NA-	-NA-	
-	f) Door size	lm group	1.53 m (final exit)	MR	
3	Compartmentation.	P. Though and	AGE EXPENDED PERMIT NEED	ga J	
1,40	Fire check door.	-NA-	-NA-	-NA-	
-	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
100.0	Water curtain     Fine demonstration	-NA-	-NA-	-NA-	
-	• Fire dampers.		-NA-	-NA-	
4	Smoke Management system.  Basement		As per clause 7.31 of UBBL 2016		
		Required	Provided	MR	
	Upper floors	12 ACPH	Provided	MR	
5	Fire Extinguishers.	S S H44 (	Promoning Story		
1	Total numbers	12 Nos	Provided	MR	
1	Types	ABC / CO2	ABC & CO2	MR	
	ISI Marking	ISI marked	Provided	MR	
6			object Security and	cond 1	
	Total numbers on each floor.	One	Provided	MR	
	Length of hose-reel hose.	30 mtr	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
7	Automatic fire detection & alarming system.				
-	Type of detectors	Co. Mo type	Provided	MR	



	Location of Main Panel	Required	Provided	MR
1	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
8	MOEFA	Required	Provided	MR
9	The state of the s	-NA-	-NA-	-NA-
10			The American	
	Basement	-NA-	NA	-NA-
	Upper floors.	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants.	774		
	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor		-NA-	-NA-
- 1	Hose box.	-NA-	-NA-	-NA-
12		NA I	65 4 4	
	<ul> <li>Total number of hydrants.</li> </ul>	-NA-	-NA-	-NA-
(1)	Hose box.	-NA-	-NA-	-NA-
13				147-
	Ground Level	NTA T	150 m 15 /6 /4	
	Discharge of main pump.	-NA-	-NA-	-NA-
	<ul> <li>Head of main pump.</li> <li>Number of main pumps.</li> </ul>	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
		-NA-	-NA-	
10	➤ Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	> Pump house access.	-NA-	-NA-	
27/		-NA-	-NA-	-NA-
,	Discharge of pump.		Natifical policy of the last	-NA-
	N 11-1 C	450 LPM	Provided	1
	Power supply.	40m	Provided	MR
0.3	Auto starting of pump.	Provided	Provided	MR
14	Captive water storage for fire fighting.	Provided	Provided	MR
	Indescript to lead to		it and a reserve	MR
	<ul> <li>Underground tank capacity:</li> <li>Draw-off connection.</li> </ul>	-NA-	-NA-	
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	THE RESERVE OF THE PERSON OF T	-NA-
		-NA-	NA-	-NA-
	Overhead tank capacity.	10,000 ltrs	-NA-	-NA-
5	Exit Signage.		Provided	MR
6	Provision of Lifts.	Required	Provided	MR
112	Pressurization of lift shaft.		70	
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
Ď	• Communication in lift car.	-NA-	-NA-	
14	• Fireman's switch.	-NA-	-NA-	-NA-
,	• Lift signage.	-NA-	-NA-	-NA-
7	Standby Power Supply	Required		-NA-
201)	Refuge Area	- required	Provided	MR
¥ ]	Total area	-NA-	NA.	2.5.0
	• Location		-NA-	-NA-
	Fire Control D	-NA-	-NA-	-NA-
		the Feerman L.	on also fore districted of	144
	Detector system panel.	-NA-	-NA-	-NA-



Flow switch panel.	-NA-	-NA-	-NA-
• PA system panel.	-NA-	-NA-	-NA-
Battery backup.	-NA-	-NA-	-NA-
Building floor plan.	-NA-	-NA-	-NA-
ecial Fire Protection System for th	-NA-		

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 512 dated 27/08/2024 and the kitchen on roof of third floor/terrace has been closed with brick wall. (Affidavit & photograph also attached opposite of file)

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/406 dated 22/09/2021, renewal under rule 37 of the Delhi Fire Service

rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HO

20 91 2gm

Director

flly

approved FI

tetter i propret

efer you

Direct

signature

249

m

2019/24 De 199