

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 311

Dated: 25/0.9./2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Rose Café located at Unit nos G6R and G7R1, Ground Floor, Eldeco Centre, Malviya Nagar, New Delhi 110017 comprised of 03 Tiers Basement, Ground plus Three Upper Floors owner/occupied by A Unit of the Dining Room have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 19/09/2024 in the presence of Mr. Dharmender Singh and that the premise is fit for occupancy class Group-D Assembly Building (Restaurant at Ground floor only) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 25/59/2024 at New Delhi by

(AFUL GARG) DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049 (Ref MHA Portal ID 2024090213528 dated 02/09/2024 & MHA Portal ID 2024090613821 dated 06/09/2024)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





	Digne on					
	Name & Address of the Building	ON REPORT	77.0	(# N)		
	Name & Address of the Building	M/s Rose Café (A Unit of the Dining Room) Unit nos G6R and G7R1, Ground Floor, Eldeco Centre, Malviya Nagar, New Delhi 110017				
2	Type of Occupancy	Restaurant at Ground Floor only				
3	Building Comprised of	03 Basement, Ground plus Three Upper Floor				
4	Type of Case	New Case				
5	Details of Previous NOC	Nil Was dock former ()				
6	Fire Safety Directives Letter No	F.6/MS/DFS/BP/2022/58 dated 18-02-2022				
7	Pate of Inspection	19/09/2024				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Dharmender Singh				
10	Year of construction	2023 ACCURE OF BUT BACK COLUMN TO SEE A				
11/4	Applicant letter online ID.	MHA Portal ID 2024090213528 dated 02/09/2024 & MHA Portal ID 2024090613821 dated 06/09/2024				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Directive Requirements	Provided at Site	Remarks MR/NMR		
1	Access to Building.	Building FSC F6/DF8/M8/Mixed/2023/8Z/68 dated 08/02/2023				
	Road width	18 mtr	Provided	MR		
	Gate width	6 mtr	Provided	MR		
1107	Width of internal road	6 mtr	Provided	MR		
2	Number, width, type & arrangement of ex	its.	0.57645 - 1.6326 - 5			
312	a) Number of Staircase	Provided and maintained by MRTS Station				
	➤ Upper floors.	NA	Provided	NA		
	Linevort Immercial	NA	Provided	NA		
	➤ Basement floor.	NA	lays / versual - a			
	b) Width of Staircase	00000 to 20000 yet) - %				
	➤ Upper floors	NA	1.5m x 2, 2 mtr x 2	NA		
7.8	A.S. A.S.	NA	1.5 m x 2 & ramp 4.50	NA		
	➤ Basement floor		m each	INA		
	c) Protection of exits					
	> Fire check door	Required	Provided	MR		
	▶ Pressurization	Required	Provided	MR		
	d) No. of continuous staircase to terrace	04 Nos	Provided	MR		
	e) Width of corridor	Required	Provided	MR		
	f Door size	1.50 mtr each	1.50 mtr each	MR		
3	Compartmentation.	Provided and maintained by MRTS Station				
	Fire check door.	Required	Provided Provided			
168	Sealing of electrical shafts.	Required		MR		
that a	Fire rating of shaft door.		Provided	MR		
-17-6		Required	Provided	MR		
817	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4	Smoke Management system.	Provided and maintained by MRTS Station				
Sild	Basement	N/A	N/A	N/A		
5	Upper floors	12 ACPH	Exhaust fan provided			
5	Fire Extinguishers.	12 ACI II	Exhaust fail provided	MR		
1	Total numbers		00.57	35 31		
6.0		ISI marked	05 Nos	MR		
* 1	• Types		W. CO ₂ , DCP & CO ₂	MR		
-	ISI Marking		Provided	MR		
6	First Aid Hose Reels.	Provided ar	Provided and maintained by MRTS Station			
	 Total numbers on each floor. Length of hose-reel hose. 	Hose Reel	Near restaurant	MR		
-			30m			
	Nozzle Diameter	11000 11001		MR		
7	Automatic fire detection & alarming system.	Provided a	5mm	MR		
	Type of detectors	Parel 1	nd maintained by MF	CIS Station		
		Required	Provided	MR		
	Location of Main Panel	Required	Provided	MR		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	Required	Provided			
	Hooter's location	All floor		MR		
		7.11 11001	Provided	MR		

		12			
8	MOEFA	Required	Provided	MR	
9	Public Address System	Required	Provided	MR	
10	Automatic Sprinkler System	Provided and			
	Basement	Required	Provided	MR	
	Upper floors	Required	Provided	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants.		maintained by MRTS	5 5555 A150-52	
	Size of Riser/Down-comer	150 mm	Provided	MR	
	Number of Hydrant per floor	06 Nos	Provided	MR	
	Hose box.	06 Nos	Provided	MR	
12	Yard Hydrants.	Provided and	d maintained by MRTS	ANNE CONTRACT	
	Total number of hydrants.	Required	07 Nos Provided	MR	
	Hose box.	Required	07 Nos Provided	MR	
13	Pumping arrangements.				
	Ground Level	Provided and	d maintained by MRTS	Station	
	Discharge of main pump.Head of main pump.	2850 LPM	Provided	MR	
	Number of main pumps.	70m	Provided	MR	
	> Jockey Pump output.	Two 180 LPM	Provided	MR	
	Jockey Pump head.	70m	Provided Provided	MR MR	
	Standby Pump output.	2850 LPM	Provided	MR	
	Standby Pump head. Auto Starting/Manual Stopping	70m	Provided	MR	
	 Auto Starting/Manual Stopping. Pump house access. 	Required	Provided	MR	
		Required	Provided	MR	
	 Terrace Level Discharge of pump. 	27/4	All returned 3		
	> Head of pump.	N/A N/A	N/A	N/A	
	Power supply.	N/A N/A	N/A N/A	N/A N/A	
	Auto starting of pump.	N/A	N/A	N/A	
14	Captive water storage for fire fighting.	Provided and maintained by MRT\$ Station			
JUNE .	Underground tank capacity.		Provided	MR	
	Draw-off connection.	Required	Provided	MR	
	Fire Service Inlet.	Required	Provided	MR	
NIA C	Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	30,000 Ltr	Provided Provided	MR	
5	Exit Signage.	Required	nd maintained by MRT	MR	
6	Provision of Lifts.	Required	Provided Provided	MR	
	Pressurization of lift shaft.	Required	Provided	MR	
	Pressurization of lift lobby.	Required	Provided Provided	MR	
JE 1	Communication in lift car.	•	Provided	MR	
ASS	• Fireman's switch.	Required	THE PERSON NAMED IN COLUMN	U. Devomente	
. 3	Lift signage.	Required	Provided	MR	
7	Standby Power Supply	Required	Provided	MR	
8	Refuge Area	27/4	NT/A study	N/A	
112	Total area	N/A	N/A N/A	N/A N/A	
774	• Location	N/A	200 200 00 00 00 00		
9	Fire Control Room.		nd maintained by MR	MR	
	Detector system panel.	Required	Provided	MR	
	 Flow switch panel. 	Required	Provided	MR	
- 1	PA system panel.	Required	Provided	MR	
	Battery backup.	Required	The second second	12 5	
	Building floor plan.	Required	Provided	MR	
	Billiand Hool Diag.	CO ₂ type fire extinguishers provided for HT/LT panel & Transformer			



the Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

NUN Signature of Inspection Officer

Name: Sh. Manoj Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Approved, f.t. Letter in fortist one synature Pl