

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2024/ 380

Dated: 23/09/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Vaishnaw Hotel situated at 23 & 640, Fatehpuri, Delhi - 06, comprised of Ground + 04 upper floors, ground floor- (04 guest rooms + reception + 05 rooms for other uses), 1<sup>st</sup> floor - (09 guest rooms + 01 store), 2<sup>nd</sup> floor - (08 guest rooms + 01 store + 01 staff room), 3<sup>rd</sup> floor- (09 guest rooms + 01 linen store) & 4th floor -(not in use), total 30 guest rooms upto 3rd floor was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/418 dated 24.09.2021. The building/ premises was re-inspected by the officer concerned of this department on dated 11.09.2024 in presence of Manager and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 12.09.2024 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of "Residential (Group-A-1), ground floor - (04 guest rooms), 1st floor - (09 guest rooms), 2nd floor - (08 guest rooms) & 3rd floor - (09 guest rooms) for total 30 guest rooms upto 3rd floor only, with effect from 23 09 224 ..... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on \$3 09 2024 at New Delhi by

ire Service Tel: 011-23414000

1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.

2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2024082713192 dated 28.08.2024.

3. The Licensee, M/S Vaishnaw Hotel at 23 & 640, Fatehpuri, Delhi - 110006.

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the
- 9. The occupancy of above 3<sup>rd</sup> floor not allowed as per clause 7.31 in UBBL-2016.

	Name	& ad	dress of the building	TION REPORT				
				M/s Vaishnaw & 640, Fatehpuri		at 23		
2	Build	ing is	comprised of	(Ground + 04 upper floors) Ground floor - (04 guest rooms + reception + 05 rooms for other purpose)  1 <sup>st</sup> floor - (09 guest rooms + 01 store)  2 <sup>nd</sup> floor - (08 guest rooms + 01 store + 01 staff room)  3 <sup>rd</sup> floor - (09 guest rooms + 01 linen room)				
	1							
			_					
	V							
				4th floor - (not in use as per affidavit dated				
				12.09.2024)				
4		of ca		Residential Group				
<u>†</u> 5		The state of the s		Renewal (old case				
3	Details of previous FSC				NDZ/2021/418 dated			
_	Pina	C +		24.09.2021				
6	Fire safety direction letter no.  Date of inspection		Nil					
7			•	11.09.2024	o (am c			
8			he inspecting officers	Sumit Kumar, AD	O (SPM)			
9	40-0		he designation of officer	Manager				
		from the building side		011				
10			onstruction	Old	1D 11 200	1000712102		
11	Apj	olicant	's letter no.	dated on 28.08.20	on I.D. No. 2024	1082/13192		
S.I	N Mi	nimur	n Standards on fire	Requirement/	Provided at Site	Remarks		
0	Walter Bridge		on and fire safety	Existing fire		MR/		
	req	requirements U/R 33		safety		NMR		
	I dans			arrangements				
1	Access To Building:			T.2	[ S. 1.			
		Road width		NA (Spl. Area)	12 m (approx)	NA		
		te wid		NA NA	NA NA	NA NA		
2	Width of internal road  Number, Width, Type and Arran				INA	INA		
-	A		ber of staircases	genicite of Exits.				
	A		Jpper floor	02 nos.	02 nos.	MR		
	V		Basement	NA NA	NA NA	NA		
	В	1000	th of staircases	(2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	ANEDUTA.	(3.05.E)		
	, D		Jpper floor	80 cms.	100 cms. & 105	MR		
					cms.			
			Basement	NA	NA	NA		
	C		ection of exits		1	1.0		
			ire check door	NA	NA	NA		
	T		Pressurization	NA 01 no	NA Ol	NA		
	D		of continuous staircases	01 no.	01 no.	MR		
	-		dth of corridor	NA	NA	NA		
	E		or size	1.0 mtr.	1.0 mtr.	MR		
	F	Do		1 10 10 10 10 10 10 10 10 10 10 10 10 10		MARK		
3	F	2000	rtmentation:					
3	F	ompa	**************************************	NA	NA	NA		
3	F C	ompa:	rtmentation:	NA NA	NA NA	NA NA		
3	F C A	ompa Fin	rtmentation: re check door		NA	NA		
3	F C A B	Fin Se	rtmentation: re check door aling of electrical shafts	NA	NA NA	NA NA		
	F B C A B C D	Fin Se Fin W	rtmentation: re check door aling of electrical shafts re rating of shaft door ater curtain re dampers	NA NA	NA	NA NA NA		
	F S C A B C D E 4 S	Fin Se Fin W Fin moke	re check door aling of electrical shafts re rating of shaft door ater curtain re dampers  Management System:	NA NA NA	NA NA NA	NA NA		
	F S C A B C C D E S 4 S A	Find See Find Windows Find Months Find Mon	re check door aling of electrical shafts re rating of shaft door ater curtain re dampers  Management System: sement	NA NA NA	NA NA NA	NA NA NA		
	F S C A B C D E 4 S	Find See Find Windows Find Months Find Mon	re check door aling of electrical shafts re rating of shaft door ater curtain re dampers  Management System:	NA NA NA NA	NA NA NA NA	NA NA NA NA		

- N/00 -

5.	Fire	Extinguisher:			
	A	Total numbers	24 nos.	25 nos.	MR
	В	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
	C	ISI marking	Required	Provided	MR
6		st-Aid-Hose Reels:			
	A	Total numbers of each	1 no. for each	Provided	MR
		floor	block		
	В	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
	C	Nozzle diameter	05 mm	05 mm	MR
7		tomatic Fire Detection And A	larming System		
-	A	Type of detectors (CO	Required	Provided	MR
	5.57	type)		Provided at	MR
	В	Location of main panel	Required	ground floor	MAK
		Cton monol	NA	NA NA	NA
	C	Location of repeater panel Alternate source of power	Required	Provided	MR
	D E	Hooters	Required	Provided	MR
8		EFA:	Required	Provided	MR
9		lic Address System:	Required	Provided	MR
10		omatic Sprinkler System:	J		
10	Aut	Basement	NA	NA	NA
		Upper floor	NA	NA	NA
	B	CONTROL CONTRO	NA	NA	NA
	C	Sprinkler above false ceiling	147	5 % E	4 4 1 1 1
11	Into	rnal Hydrants:			
11	A	size of riser/down-comer	100 mm	100 mm	MR
	B	Number of hydrants per	01 no.	01 no.	MR
	D	floor			
	C	Hose box	01 no.	01 no.	MR
12	156	l Hydrants:			
14	A	Total number of hydrants	NA	NA	NA
ŀ	187-196	Hose box	NA	NA	NA
	В		A.A.A.	50.00.00	
3		ping Arrangements:			
	A	Ground level	LNIA	l NIA	NA
	a)	Discharge of main pump	NA	NA	
	b)	Head of main pump	NA	NA	NA
Ī	c)	Number of main pumps	NA	NA	NA
1	d)	Jockey pump out put	NA	NA	NA
ł	e)	Jockey pump head	NA	NA	NA
t	f)	Standby pump out put	NA	NA	NA
t	g)	Standby pump head	NA	NA	NA
ŀ	h)	Auto starting /manual	NA	NA	NA
	•	stopping			
	i)	Pump house access	NA	NA	NA
	В	Terrace level			
	a)	Discharge of pump	450 LPM	450 LPM &	MR
				225 LPM	
	b)	Head of the pump	40 mtrs.	Provided	MR
	c)	Power supply	Required	Provided	MR
	d)	Auto starting of pump	Required	Provided	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	u)	Auto starting of pump	Required	Provided	MR

	A	Underground tank capacity	NA	NA	NA		
	В	Draw-off connection	NA	NA	NA		
٦	C	Fire service inlet	NA	NA	NA		
ı	D	Access to tank	NA	NA	NA		
	E	Overhead tank capacity	50,000 ltrs.	50,000 ltrs. + 10,000 ltrs.	MR		
15	Exi	t Signage:	Required	Provided	MR		
16	Provision of Lifts:						
	A	Pressurization of lift shaft	NA	NA	NA		
	В	Pressurization of lift lobby	NA	NA	NA		
	C	Communication in lift car	Required	Provided	MR		
	D	Firemen's grounding switch	Required	Provided	MR		
	E	Lift signage	Required	Provided	MR		
17	Sta	andby Power Supply:	Required	Provided	MR		
18	Refuge Area:						
	A	Total area	NA	NA	NA		
	В	Location	NA	NA	NA		
19							
	A	Detector system panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	Pa system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plans	NA	NA	NA		
20				NA	NA		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Shortcomings communicated vide letter No.F6/DFS/MS/GH/NDZ/2024/461 dated 02/08/2024 have been rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/418 dated 24.09.2021 is recommended to be renewed upto 3<sup>rd</sup> floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar

Designation ADO (SPM)

DO (CD)

1219/14

Dy eto (nose)

ugh Hamar

м