

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/WZ/IND./2024/ 588

Dated: 26 / 09 /2024

## **FIRE SAFETY CERTIFICATE**

Road, Industrial Area, Delhi-110035, in a building comprised of Basement + Ground + 01 Upper Floors, owned/occupied by M/s. Bawa Masala Company was issued Fire safety Certificate vide Letter No. F6/DFS/MS/WZ/2020/209 dated 16/06/2020, The premises was re-inspected by officer concerned of this department on 27/08/2024 in the presence of Sh. Savinder Singh and observed that fire prevention and fire safety arrangements provided in the building found in good working condition. The said building/Premises have deemed complied with the fire prevention & fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rule 2010 & the said premises is fit for occupancy class "Industrial" (Group-G) with effect from 26 09 2004 for a period of three year in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 conditions printed overleaf.

Issued on 26 09 2024 at New Delhi by.

Atul Garg Director

16/09/224

Copy to:-

- 1. The Owner/occupier M/s. Bawa Masala Company located at B-11, Lawrance Road Industrial Area, Delhi-110035.
- 2. The Commissioner, MCD, Civic Centre, Mitno Road, New Delhi-110002.to depute concerned engineer to check the addition/alteration/illegal construction if any in the premises & intimate this department.

11/18

1	N	VSPE	ECTION RE	PORT				
1 4.	Name & address of the building	M/s. Bawa Masala Company, Located at B-11, Lawrane Road, Industrial Area, Delhi-110035.						
2.	Type of Occupancy	Industrial						
3. Type of Case			Renewal					
Details of previous NOC     Fire Safety directives letter No			DFS/MS/W7	//2020/3	009 dated 16/06/201	20		
			F6/DFS/MS/WZ/2020/209 dated 16/06/2020 F6/DFS/MS/BP/97/136 dated 12/02/1997					
	Date of inspection	27/08/2024						
7. Name of the Inspecting Officers								
8. Name and designation of officers from the building side		Sarabjeet Singh ADO (MN) Sh. Savinder Singh						
9.	Year of Construction	200	6 (As per pre	ev. Insp	report dtd- 13/03/2	2020		
10	. Applicant's letter No.	Ema	ail dated 07/0	6/2024				
~								
S. No.	Minimum Standards on fire prevention and fire safety U/R 33		Required as per Rule 35(6) of DFS Rule 2010		e Remarks MR/NMR			
1	Access to building			,,,,,				
	Road width		09 mts		Provided	MR		
	• Gate width		05 mts		4.90 mts Provided	MR(Old Case)		
	Width of internal road		NA		NA	NA		
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases		00					
	Upper Floors     Basements		02		03 Provided	MR		
	b. Width of staircases		02		02 Provided	MR		
	Upper Floors		1.2 m each	1 1 1 05	1x 0.70 to 1.70 & 1 x 1.20	(   100/01/0		
	Basements		1.2 m each		8m Provided	MR(Old Case) MR(Old Case)		
	c. Protection of exits					MIC(Old Case)		
	Fire check door		Required in basement		nt Provided	MR		
	Pressurization		NA		NA	NA		
	e. No. of continuous staircases to terr	ace	01		Provided	MR		
	f. Width of Corridor		NA		NA	NA NA		
- 11	g. Door Size		1.2 m		0.96cm	MR(Old Case)		
3	Compartmentation.							
	Fire check door		Required		Provided	MR		
	<ul> <li>Sealing of electrical shafts</li> </ul>		NA		NA	NA NA		
	<ul> <li>Fire Rating of shaft door</li> </ul>	Ì	NA		NA	NA		
	Water Curtain		NA		NA	NA		
	<ul> <li>Fire Dampers</li> </ul>		NA		NA	NA		
4	Smoke Management System.		III.					
	Basements		Required		Provided	MR		
	<ul> <li>Upper floors</li> </ul>		NA	5	NA	NA		
5	Fire Extinguishers							
	Total numbers		17nos.		Provided	MR		
	Types		CO <sub>2</sub> , ABC typ	oe	Provided	MR		
	<ul> <li>IS marking</li> </ul>		ISI marked		Provided	MR		

l F	First-Aid Hose Reels.			M
+	Total numbers on each floor	02	Provided	MR MR
	Length of hose reel hose	30m	Provided	1
	Nozzle diameter	5mm	Provided	MR
-	Automatic fire detection and alarming	system.	NA	NA
- 13/4	Type of detectors	NA	NA NA	NA
	Location of Main Panel	NA	NA NA	NA
	Location of Repeater Panel	NA	NA NA	NA
	Alternate source of power	NA	NA NA	NA
1	Hooters' Location	NA	X - 017-237-0	MR
	MOEFA	Required	Provided	NA
,	Public Address System.	NA	NA	1,11.5
_	Automatic Sprinkler System.			
10		Required	Provided	MR
	Basement	NA	NA	NA NA
	Upper Floor     Seriables shows false ceiling	NA	NA	NA
	Sprinkler above false ceiling	Andrew American		
11	Internal Hydrants	100 mm	Provided	MŖ
	Size of riser/down-comer	02	Provided	MR
	Number of hydrants per floor	02	Provided	MR
	Hose Box	UZ		
12	Yard Hydrants.	Required	Provided	MR
	Total number of hydrants	Required	Provided	MR
	Hose Box	Required		
13	Pumping Arrangements.	· · · · · · · · · · · · · · · · · · ·		
	Ground Level	, , , , , , , , , , , , , , , , , , ,		374
	> Discharge of main Pump	NA NA	NA	NA
	> Head of Main pump	NA	NA	NA NA
	Number of main pumps	NA NA	NA NA	NA NA
10	<ul><li>Jockey Pump out put</li><li>Jockey pump head</li></ul>	NA NA	NA NA	NA NA
	<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>	NA NA	NA NA	NA NA
	> Standby Pump Head	NA NA	NA NA	NA NA
	> Auto Starting/ Manual stopping	NA NA	NA NA	NA NA
	> Pump House Access	NA NA	NA	, accerae
	Terrace level	INA	INA	NA
	Discharge of pump	900 lpm	Provided	MR
	> Head of the pump	40 m	Provided	MR
17.	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	
14	Captive Water Storage for fire fighting	I THE DAY ALL AS	Tovided	MR
		1,00,000 ltrs		1
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	NR	Provided	MR
	> Fire service inlet	NR NR	NR	NR
-	Access to tank		NR	NR
	ACCORDANGE AND ACCORD	NR 12 500 H	NR	NR
15	o ternous runk capacity	12,500 ltrs	Provided	MR
13	Exit Signage.	Required	Provided	MR

		م الم		-			
16.	Provision of Lifts.						
	Pressurization of Lift Shaft	NA	NA NA NA NA NA	NA			
	Pressurization of Lift lobby	NA NA NA		NA NA			
	Communication In lift Car			NA			
	Fireman's Grounding Switch     Lift Signage						
		NA		NA			
		Required	Provided	MR			
17	Standby power supply	Marie Committee					
18	Refuge Area.		NA	NA			
,	<ul><li>Total Area</li><li>Location</li></ul>	NA	NA	NA			
		NA					
19	Fire Control Room NA NA						
	Detector System Panel     Flow Switch Panel     PA System Panel     Batter backup	NA	NA	NA NA			
		NA	NA	NA NA			
		NA	NA	1			
		NA NA	NA	NA			
		Required	Provided	MR			
20	Building Floor Plans  Special Fire Protection Systems for  Protection of special Risks, if any:	NA NA	NA	NA			

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcoming issued by this department vide letter no. F6/DFS/MS/2023/WZ/2046 dated 21/09/2023 have been complied.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F6/DFS/MS/WZ/2020/209 dated 16/06/2020 renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

whose area juidiction of L. Road & Clark,

No Officer is posted there.

Submitted please.

Earlier one file is there, where Deneter (Atts)