

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/School/NDZ/2024/ 9 64

Dated: 03/10/2024

## FIRE SAFETY CERTIFICATE

Certified that the Ahlcon Public School located at Mayur Vihar, Phase - I, Delhi - 110091, building comprised of basement (Storage), ground plus three upper floors, owned/occupied by Ahlcon Public School was issued FSC vide letter No. F6/DFS/MS/School//NDZ/2021/759 dated 20/09/2021. The school building was re-inspected by the officer concerned of this department on 18/09/2024 in presence of Dr. Deepak Raj Singh Bisht (Principal) & Mr. Vikram Singh (Administrative Officer) and found that the said school have deemed complied with the fire prevention and fire safety requirements provided in accordance with the Rule 33 of the Delhi Fire Service Rules 2010 and that the premises is fit for occupancy class Group - B "Educational Building" for ground plus three upper floors only with effect from 63/10/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 03/10/2024 at New Delhi by.

DIRECTOR OLD THE SERVICE

Copy to: -

1. The Dy. Director of Education, D - Block, Anand Vihar, Delhi-110092.

2. The Principal, M/s Ahlcon Public School located at Mayur Vihar, Phase-1, Delhi - 110091.

## Conditions for the validity of Fire Safety Certificate

- 1. Fire Safety Certificate is valid for ground plus three upper floors only.
- 2. Presently basement is being used for storage.
- 3. Terrace is being used for passage purpose only (as per affidavit given by the owner dated 18.09.2024).
- 4. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 5. All the means of escape shall be kept free of all the type of obstruction all the time.
- 6. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 7. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 8. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 9. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 10. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

			INSPEC	TION REPORT	01 - 192 - 1		7	
1	Nar	ne d	& address of the building	M/s Ahlcon P Vihar, Phase - 1,	ublic School locat Delhi - 110091.	ed at	Mayu	
2	Building is comprised of Basement (Storage), ground plus three upper floors.					er		
3	Type of occupancy			Educational Building				
4	Typ	e o	f case	Renewal			-	
5	Details of previous FSC			F6/DFS/MS/School//NDZ/2021/759 dated 20/09/2021				
6	Fire safety directives letter no. NBC Part - IV							
7	Dat	e o	finspection	18/09/2024				
8	Naı	ne e	of the inspecting officers	Yashwant Singh Meena ADO (Laxmi Nagar)				
9	Name of the designation of officer from the building side Dr. Deepak Raj Singh Bisht (Principal) & Mr. Vikram Singh (Administrative Officer)					)		
10			f construction	1988 - 1991				
11	2.4	Applicant's letter no. Outdoor Dairy No. 6290 dated 10/09/2024						
S. No		M	inimum standard of fire	NBC/BBL Requirement	Provided at site		Remarks MR/NMR	
1.			ntion and fire safety U/R 33 s to Building:	•••				
1.			oad width	6.0 mtrs.	15 mtrs.	MR		
	A	- 0.5		4.5 mtrs	4.5 mtrs.	180	MR	
	В		ate width	WAR SPENCE	N/A	N/A		
	C	0.0	idth of internal road	N/A	IV/A	N/A		
2.	Nu		er, Width, Type and Arrang	ement of Exits:				
	A	N	lumber of staircases		A Paris		- 100	
		a	Upper floor	04 nos. + 1 ramp		np /	MR	
			Basement	05 nos.	05 nos.		MR	
	В	V	vidth of staircases	104 1 100 10			- MD	
		а	Upper floor	1.5 mtrs.	02 nos 1.70 mt 02 nos 2.0 mt 01 no 0.86 mtrs 01 ramp 1.5 m	rs, &	MR	
			Basement	1.5 mtrs.	03 nos 1.70 mtrs nos 2.0 mtrs		MR	
	C	P	rotection of exits	3114	N/A		N/A	
		a	Fire check door	N/A	00265655		N/A	
		b	Pressurization staircages	N/A 02 nos	N/A 03 nos		MR	
	D		o. of continuous staircases terrace	Q2 1103				
	E		/idth of corridor	1.5 mtrs	1.70 mtrs		MR	
	F Door size			1.0 mtr.	1.0 mtr. / M		MR	
3.	Co	mp	artmentation:					
	A Fire check door			NA	NA	NA		
	B Sealing of electrical shafts			N/A	N/A	N/A		
	C Fire rating of shaft door		40	N/A	N/A	N/A		
	D Water curtain		/ater curtain	N/A	N/A	N/A		
	E Fire dampers			N/A	N/A		N/A	
1			Management System:			7		
4.				Required	Provided	MR		
	A			Required	Provided		MR	
	В	U	pper floor	(W)			_	

Ahlcon Public School located at Mayur Vihar, Phase-1, Delhi – 110091.

5.	Fir	e Extinguisher:	20	35 nos.	MR		
	A	Total numbers	30 nos.	CO <sub>2</sub> & ABC	MR		
	В	Types	CO <sub>2</sub> & ABC	Provided	MR		
	C	ISI marking	Required	Piovided			
6		st-Aid-Hose Reel:		03 no.	MR		
•	A	Total numbers of each floor	03 no.	30 mtrs.	MR		
	B	Length of hose reel hose	30 mtrs.	05 mm	MR		
	-	Nozzle diameter	05 mm	05 11111	5.05		
-	Detection and Alarming System:						
7		Type of detectors	N/A	N/A	N/A		
	A	Location of main panel	N/A	N/A N/A	N/A		
	C	Location of many panel  Location of repeater panel	N/A	SNI	N/A		
	1000	Alternate source of power	N/A	N/A	N/A		
	D		N/A	N/A	MR		
	E	Hooters	Required	Provided	MR		
8		OEFA:	Required	Provided '	MIK		
9	Pu	blic Address System:	A CONTRACTOR	Service of the servic	MD		
10	Au	tomatic Sprinkler System:	Required	Provided /	MR		
	A	Basement	N/A	N/A	N/A		
	В	Upper floor	N/A	N/A	N/A		
	C	Sprinkler above false ceiling	N/A				
11	Int	ternal Hydrants:	40-40-0	N/A	N/A		
11	A	Size of riser/down-comer	N/A	N/A	N/A		
	B	Number of hydrants per floor	N/A	N/A	N/A		
	C	Hose box	N/A	N/A	10		
	- 34			27/4	N/A		
12		rd Hydrants:  Total number of hydrants	N/A	N/A	N/A		
	A		N/A	N/A	INIA		
	В	Hose box		en plu			
13	Pumping Arrangements:						
1	C	Ground level	N/A	N/A	N/A		
	A	Discharge of main pump	N/A	N/A	N/A		
	В	Head of main pump	N/A	N/A	N/A		
	C	Number of main pumps	N/A	N/A	N/A		
	D	Jockey pump out put	22937	N/A	N/A		
	E	Jockey pump head	N/A N/A	N/A	N/A		
	F	Standby pump out put	98	N/A	N/A		
		Standby pump head	N/A	N/A	N/A		
	G	Auto starting /manual	N/A	13//1	672010202		
	H	stopping	NT/A	N/A	N/A		
	I	Pump house access	N/A		,		
2	Te	and I evel	460 I DM V 2	450 & 900 LPM	MR		
2	- Large of nump each block		450 LPM X 2		MR		
	A	Head of the pump	40 mtrs.	40 mtrs. / Provided	MR		
	B	Power supply	Required		MR		
	C	Auto starting of pump	Required	Provided	IVII		
	D	Auto starting of party	(1)		1		

Ahlcon Public School located at Mayur Vihar, Phase-1, Delhi - 110091.

14	Captive Water Storage for Fire Fighting:						
_	A	Underground tank capacity	N/A	N/A	N/A		
+1	В	Draw-off connection	N/A	N/A	N/A		
	C Fire service inlet		N/A	N/A	N/A		
11	D	Access to tank	Required	Provided	MR		
Q.	E	Overhead tank capacity	15,000 liters	20,000 liters	MR		
15		it Signage:	Required	Provided	MR		
16	Dravision of Lifts:						
		Pressurization of lift shaft	N/A	N/A	N/A		
	A	Pressurization of lift lobby	N/A	N/A	N/A		
	B	Communication in lift car	N/A	N/A	N/A		
	C	Communication in int car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
25 11 27 27	E Lift signage		N/A	N/A	N/A		
1.7	Standby Power Supply.						
18	Refuge Area: N/A N/A						
	A	Total area	N/A	N/A	N/A N/A		
	В	Location	N/A	IV/A			
19	Fir	e Control Room:	N/A	N/A			
-	A	Detector system panel	N/A	N/A N/A	N/A		
**	В	Flow switch panel	N/A	N/A N/A	N/A		
	C	PA system panel	N/A	N/A N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A N/A	N/A		
20	Sp	ecial Fire Protection systems for otection of special Risks, if any:	N/A	IV/A	. 17.4.		

The fire protection system provided in the school building were tested, checked at random and found functional at the time of inspection and basement is being used for passage and storage only.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of FSC issued vide letter no. F6/DFS/MS/School//NDZ/2021/759 dated 20/09/2021, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (L.N)

DY. CFO/NDZ

26/09/2

Denotal 9 39 ANITA

0.1.0