

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/NDZ/2024/ 393

Dated: 03/.1.0../2024

FIRE SAFETY CERTIFICATE

Certified that the Gold Regency Guest House located at 4344-50, Main Bazar, Pahar Ganj, New Delhi in a building comprised of Ground + 4/terrace floors, Ground floor (Reception + hall), 1st floor to 2nd floor (17 guest rooms at each floor), Total 34 rooms up to second floor with an undertaking dated 14.01.2022 regarding not to use any floor above second floor submitted by owner, was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2022/42 dated 21/01/22. Now, the premises was re-inspected by the officers concerned of this department on 19/09/24 in the presence of Sh. Amandeep, Owner and found that the said guest house building having guest rooms at first & second floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception), 1st floor to 2nd floor (17 guest rooms at each floor) -Total -34 guest rooms up to second floor only and valid up to the period of three year from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued03/10/2024 at New Delhi by.

DIRECTOR Della Fire Service

Copy to:-

 The Commissioner, North MCD, Civic Centre, New Delhi: to kindly ensure the occupancy as detailed above and deviation if any.

 The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi idno.2024090613828 dated 06/09/24.

3. The Manager, Gold Regency Guest House at 4344-50, Main Bazar, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

 All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for guest house up to second floor only.

Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

N138

INSPECTION REPORT

1. Name & address of the building Gold Regency Guest House at 4344-50

Main Bazar, Pahar Ganj, New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Ground + 04 /terrace floors (total 34 guest rooms)
Ground floor (Reception + hall), 1st floor to 2nd floor

(17 guest rooms at each floor), an undertaking dated 14.01.2022 regarding not to use any floor above second floor submitted by owner

3. Type of case:- Renewal

4. Details of previous FSC:- No.F6/DFS/MS/GH/NDZ/2022/42 dated

21/01/22.

5. Fire safety directives No.- N/A

6. Date of inspection:- 19/09/24

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC) Sh. Raiinder Atwal (DO/CD)

8. Name & designation of officer
From the building side:- Sh. Aman deep, Owner

9. Year of construction:

Id- no.2024090613828 dated 06/09/24.

10. Applicant's letter No:-Old Case Remarks Provided at site Requirement/ Minimum Standards on fire S.No. MR/NMR Existing fire safety Prevention and fire safety U/R 33 arrangements Access to Building 1. N/A N/A N/A 1) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3)Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 02 Nos. 01 No. 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.13 & 0.87 mtr. 0.80 mtr. 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits MR Provided Required 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor MR 01 mtr. 01 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System N/A N/A N/A 1) Basements MR Natural/exhaust 2) Upper floors 12 ACPH Fire Extinguishers 5. MR 12 Nos. 12 Nos. 1) Total numbers ABC & CO2 MR ABC & CO2 2) Types MR Provided Required 3) ISI marking

Nlsa

				-
6.	First-Aid Hose Reel	01	01	MR
	1) Total number of each	01	VI	
	floor	20	30 mtr.	MR
	2) Length of hose reel hose	30 mtr.	05 mm	MR
	3) Nozzle diameter	05 mm		_
7.	Automatic Fire Detection & A	Darwing Syste	Provided	MR
	1) Type of detectors CO type	Required Ground	Provided	MR
	2) Location of main panel		N/A	N/A
	3) Location of repeater panel	N/A	Provided	MR
	4) Alternate source of power	Required Ground	Provided	MR
	5) Hooter's Location .		N/A	N/A
8.	MOEFA	N/A	Provided	MR
9.	Public Address System	Required	Provided	H MAK
10.	Automatic Sprinkler System	No se continu	N/A	N/A
	1) Basement	N/A		N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	I WA
	ceiling			1
11.	Internal Hydrants		100	MR
	1) Size of riser/down-comer	100 mm	100 mm	MR
	2) Number of hydrants per	01	01	IVIK
	floor		01	MR
	3) Hose box	01	01	IVIK
12.	Yard Hydrants	1	127/4	N/A
	1) Total number of hydrants	N/A	N/A	
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pum	p N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump outpu	it N/A	N/A	N/A
	g) Stand by pump head	SANCE THE PARTIES OF	N/A	N/A
	h) Auto starting/Manua		N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 & 180	450 & 180 I	PM MR
	-,	LPM		
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pur		Provided	MR
14.	Captive Water Storage for			14116
14.	1) Under ground tank	N/A	N/A	N/A
	capacity	IN/A	IN/A	IN/A
		- N/A	27/4	NIA
		2000000	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	 d) Over head tank capacity 	5,000 ltr.	10,000 ltr.	MR
			-	





5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sys Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, there is a restaurant at ground floor having separate entry exit and FSC has already been issued. There are rooms at third floor & 4th /terrace floor and an under taking dated 14.01.2022 has already been submitted by the owner regarding not to use any floor above second floor.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. If agreed we may renew the FSC issued vide letter no. .F6/DFS/MS/GH/NDZ/2022/42 dated 21/01/22, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly DFS is prepared and putup for kind perusal and signature please. .

Signature of the inspecting officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation: - DO (CD) Name: Ravinder Singh Designation: ADO (CC)

Three (wost

Denge to Malya

MIN

Acoporen, computato for leas permentano

By relimp phones

det My mun

Uplanded .