GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001



Dated: 03/10/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Moon Shine Entertainment Limited (Miraj Cinema) hall running on first floor (Audi – 01, Audi no. 02 & Audi no. 03, (Miraj Cinema) located at Trilok Puri, Delhi - 110091, building comprised of three basement, ground plus four upper floors, owned/occupied M/s Moon Shine Entertainment Limited, have complied with the Fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 20/09/2024 in the presence of Mr. Vikas Tyagi (Manager) and found that the building/premises is fit for occupancy class (Group – D) "Assembly Building" with effect from 03/10/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010, printed below.

Issued on 03 10 2024 at New Delhi by.

ATUL GARG) DIRECTOR DELHI FIRE SERVICE

Copy to:-

- 1. The Ex. Engineer (Bldg.), MCD, 419, F.I.E. Udyog Sadan, Patpargani, Delhi 110092
- 2. The Manager, Moon Shine Entertainment Limited (Chand Cinema) located at Trilok Puri, Delhi 110091.
- 3. The Deputy Health Officer, Shahdara South Zone, Shahdara, Delhi.
- 4. The Electrical Inspector, Govt. of NCT of Delhi, D-Block, 5 Sham Nath marg, Delhi.

Conditions for the validity of Fire Safety Certificate:

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
 - 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

))

and the								
			INSP	ECTION REPOR	Ţ			
1	Na	ame	& address of the building	Moon Shine Entertainment Limited for (Audi – 01 Audi no. 02 & Audi no. 03, (Miraj Cinema) located at Trilok Puri, Delhi - 110091.				
2	Bı	iild	ing is comprised of	03 Basement, Gr	ound + 04 upper floors	only.		
3	T	ne	of occupancy		(Cinema Hall on first floor) Assembly Building (Cinema Hall)			
4	-	_		New Case				
5	Type of case Details of previous FSC			Nil (FSC also issued to the building vide letter No.				
				F6/DFS/MS/Cinema/NDZ/2024/242 dated 19/04/2024.)				
6 .	_	_	afety directives letter no.		F6/DFS/MS/BP/2019/113 dated 15.03.2019			
7	_	_	of inspection	20.09.2024				
8	Name of the inspecting officers				Yashwant Singh Meena ADO (L.N)			
9	Name of the designation of officer from the building side			Mr. Vikas Tyagi	Mr. Vikas Tyagi (Manager)			
10	Year of construction			2020				
11	Ar	pli	cant's letter no.	Email dated 12/0	9/2024			
S.No		Minimum standard of fire prevention and fire safety U/R 33		Requirement	Provided at site	Remarks MR/NMF		
1	A		s to Building:					
5 5	A	R	toad width	30 mtrs.	30mtrs.	MR		
-	В	G	ate width	6.0mtrs.	6.0mtrs.	MR		
	C	V	Vidth of internal road	9.0mtrs.	9.0mtrs.	MR		
2	Number, Width, Type and Arrangement of Exits:							
	A Number of staircases							
-		a	Upper floor	04 nos.	04 nos.	MR		
		b	Basement	03 nos.	03 nos. + 01 no. ramp	MR		
	В	V	Vidth of staircases					
		a	Upper floor	2.0 mtrs. each	2.0 mtrs. x 04	MR		
10	æ	b	Basement	2.0 mtrs. each	2.0 mtrs. x 04 + (Ramp 7.30 mtrs.)	MR		
	C	P	rotection of exits					
		a	Fire check door	Required	Provided	MR		
4.0		b	Pressurization	Required	Provided	MR		
	D	to	o. of continuous staircases terrace	02 nos.	04 nos.	MR		
	E		idth of corridor	Required	Provided	MR		
	F	F Door size Compartmentation:		2.0 mtrs. & 1.50 mtrs.	Provided /	MR		
3	Co		W. SETTING					
	A	A Fire check door		Required	Provided	MR		
	В	Sealing of electrical shafts		Required	Sealed	MR		
	C			Required	Provided	MR		
	_	hrs) Water curtain		Required	Provided	MR		
	D	E	re dampers	Required	Provided	MR		
	E	oke	Management System:			10-10 Table 1		
	T n amont			20 1	The same of the sa			
	A	R	sement	30 a/c per hrs	Provided	MR		

	Fire l	Extinguisher:	Provided	MR	
-	1101	Total numbers	40 nos.	CO ₂ & ABC	MR
	5.00	Гуреѕ	CO ₂ & ABC		MR
		ar I'	ISI Marked	ISI Marked ,	IVIN
		ISI marking	****		
		-Aid-Hose Reel:	Required one no. in	Provided	MR
	A Total numbers of		each Audi.		MR
-	-	Length of hose reel hose	30 mtrs.	Provided /	
-	10	Nozzle diameter	05 mm	Provided	MR
	C	Nozzie diameter	Jarming System:	1	أسيا
7		omatic Fire Detection and A	Smoke &Heat	Provided	MR
	A	Type of detectors	Ground floor entry	Provided	MR
	В	Location of main panel	gate no. 01	0) Bec. (100)) (D
	C	Location of repeater panel	In main building control room	Provided	MR
		· · · · · · · · · · · · · · · · · · ·	Batter & DG Set	Provided	MR
	D	Alternate source of power	Staircase Staircase	Provided	MR
	E	Hooters location	Required	Provided	MR
8	The state of	DEFA:	Required	Provided	MR
9		olic Address System:	Required		
10	1	tomatic Sprinkler System:	Required	Provided	MR
	A	Basement	Required	Provided	MR
	В	Upper floor		Provided	MR
	С	Sprinkler above false ceiling	Required	Tiovidea	
11	Internal Hydrants:		Transport Company	Provided	MR
N.	A Size of riser/down-comer		150mm	Provided	MR
	В	No. of hydrants per floor	Required one no. in each Audi.	_ /	
	C	Hose box	Required	Provided	MR
12		rd Hydrants:			
	A	Total number of hydrants	05 nos.	05 nos.	MR
	В	Hose box	05 nos.	05 nos.	MR
13	- 1	imping Arrangements:	Common w	ith Mall Building	
1		Ground level "		/	
Ė	A	Discharge of main pump	2850 LPM	2850 LPM	MR
	В	Head of main pump	120 M	120 M	MR
	C	Number of main pumps	02 nos.	02 nos.	MR
	D	Jockey pump out put	180 LPM	180 LPM	MR
	E	Jockey pump head	120 M	120 M	MR
	F	Standby pump out put	2850 LPM	2850 LPM	MR
	G	Standby pump head	120 M	120 M /	MR
	Н	STREET, MACHINE STREET, MACHINE STREET, CO. CO., CO., CO., CO., CO., CO., CO.,	900 LPM	900 LPM	MR
	I	Auto starting /manual stopping	Auto	Provided	MR
	J	Pump house access	Required	Provided	MR
1		errace Level	CONTROL SOUTH CONTROL		
2			N/A	N/A	N/A
2	A				
2	B		. N/A	N/A	N/A
2	_	Head of the pump	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A

\Q/

Miraj Cinema located at Trilok Puri, Delhi - 110091.

4	Captive Water Storage for Fire Fighting: Common with Mall Building Common with Mall Building								
	A	Underground tank capacity	2,00,000 Liters	2,00,000 Liters					
	B	Draw-off connection .	Required	Provided	N/A MR				
	C	Fire service inlet	Required	Provided	MR				
	D	Access to tank	Required	Provided	MR				
	E	Overhead tank capacity	20,000 liters	20,000 liters.	MR				
5	Exi	t Signage:	Required	Provided	MR				
16	Provision of Lifts:								
	A	Pressurization of lift shaft	Required	Provided	MR				
	B	Pressurization of lift lobby	Required	Provided	MR				
	C	Communication in lift car	Required	Provided	MR				
	D	Firemen's grounding switch	Required	Provided	MR				
	E	Lift signage	Required	Provided	MR				
17	Sta	andby Power Supply:	by Power Supply: Required Provided		MR				
18	Re	Refuge Area:							
	Λ	Total area	N/A	N/A	N/A				
	В	Location	N/A	N/A	N/A				
19	Fi								
	A	Detector system panel	Required	Provided	MR				
	В	Flow switch panel	Required	Provided	MR				
	C	PA system panel	Required	Provided	MR				
	D		Required	Provided	MR				
	E		N/A	N/A	N/A				
2	0 S	pecial Fire Protection systems for rotection of special Risks, if any:	Required	Provided	MR				

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (L.N)

DY. CFO/NDZ

NIV PORPY

1 27 91 sory

Directory of

sir. F.T letter is Autup for Sign. Plea

30/9/2024