



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2024/Indl./621

Dated 09 /10/2024

FIRE SAFETY CERTIFICATE

Certified that the Sharp Mint Limited located at Plot No. C-3, SMA, Co-operative, Industrial Estate, G.T.K. Road, Delhi-110033 comprised of Ground & 02 upper floor only owned/occupied by Sharp Mint Limited have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of Fire Service on 20.09.2024 in presence of Sh. Mukesh Yadav (Attendant) of the premise is fit for occupancy class G-2 Industrial occupancy for ground & two upper floors only with effect from O. Ph. 10.1.2024.... for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 09/10 /2024... at New Delhi

Director

Ph:-01/1-23414000

Copy to: -

 The Authorized Signatory, Sharp Mint Limited located at Plot No. C-3, SMA, Cooperative, Industrial Estate, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape shall be kept free from any type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

5. This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.

6. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Sharp Mint Limited at C-3, SMA, Co-Operative, Industrial

Estate, G.T.K. Road, Delhi-110033.

2. Type of Occupancy : Industrial Building

Type of Case : New 3.

Composition of building : Ground floor & 02 upper floors only

5. Details of previous NOC

6. Fire Safety directives letter No : F6/DFS/MS/BP/2023/12 dated 03.01.2024

Date of inspection : 20.09.2024 8. Name of the Inspecting Officers : ADO(RN)

9. Name and designation of officers

from the building side

: Sh. Mukesh Yadav (Attendant)

10. Year of Construction

	A 200 CO	num Standards on fire on and fire safety U/R 33	NBC Part-IV /UBBL 2016 Requirements	Provided at site	Remarks MR/NMF			
	Access to building							
	•	Road width	09 m	24m	MR			
	•	Gate width	05m	05m	MR			
	•	Width of internal road	NA	NA	NA			
2	Number	, Width, Type & Arrangemer	nt of Exits		7.46			
	a. Numb	er of staircases		A				
- 1	:. *	Upper Floors	02	02	MR			
v	8. ·	Basements	NA	NA	NA			
	b. Width of staircases							
		Upper Floors	1.50m each	1.50m each	MR			
	•	Basements	NA	NA	NA			
	c. Protection of exits							
	•	Fire check door	Required	Provided	MR			
	•	Pressurization	NA	NA	NA			
	10 management	of continuous staircases to	02	02	MR			
	terrace e. Width	of Corridor	NA	NA	NA			
	f. Door	Size	1.50m	1.50m	MR			
3	Compartmentation							
	•	Fire check door	NA	NA	NA			
	•	Sealing of electrical shafts	NA	NA	NA			
	•	Fire Rating of shaft door	NA	NA	NA			
	•	Water Curtain Fire Dampers	NA	NA	NA			
	•	r ne Dampers	NA	NA	NA			
4	Smoke Management System.							
1 18	25-55-56		NA	NA	NA			

	Upper floors	N/17 Paguired	Provided	MR		
		Required	7107.252	1-1-		
	Fire Extinguishers					
	Total numbers	25no's	26no's	MR		
	Types	ABC/CO2	ABC-20/Co2-06	MR		
	ISI marking	ISI Marked	Yes	MR		
6	First-Aid Hose Reels.					
	Total numbers on each floor	02 at each floor	Provided	MR		
	Length of hose reel hose	30m	Provided	MR		
	Nozzle diameter	5mm	Provided	MR		
,	Automatic fire detection and alarming system.					
	Type of detectors	Smoke	Provided	MR		
	Location of Main Panel	Required	Provided	MR		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
	MOEFA	Required	Provided	MR		
)	Public Address System.	NA	NA	NA		
0	Automatic Sprinkler System.					
	Basement	NA	NA	NA		
	Upper Floor Sprinkler above false	Required	Provided	MR		
	ceiling	NA	NA	NA		
1	Internal Hydrants.					
	Size of riser/down-comer	100mm	Provided	1.00		
	Number of hydrants per	02 at each floor	Provided	MR		
	floor Hose Box	02 at each floor	Provided	MR MR		
2	Yard Hydrants.		Land V	MK		
	Total number of hydrants 02nos Provided					
	Hose Box	02nos	Provided	MR		
3	Pumping Arrangements.	Required	Provided	MR		
	Ground Level					
	Discharge of mainPump	NA	2280 LPM	NA		
	Head of Main pumpNumber of main pumps	NA	80m	NA		
	➤ Jockey Pump out put	NA	01	NA		
	Jockey pump head	NA	180 LPM	NA		
		NA				



		NA	2280 LPM	NA			
	> Standby Pump out put		80m	NA			
	> Standby Pump Head > Auto Starting/ Manual	NA		NA			
	stopping	NA	NA .				
	> Pump House Access	NA	NA	NA			
	Terrace level			lk will "			
	> Discharge of pump	900 LPM	900 LPM	MR			
	> Head of the pump	40m	40m	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
4 C	aptive Water Storage for fire fighting	ng.					
	Underground tank capacity	50, 000 LTR	75,000 LTR	If agreed MR			
	1	· NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
	> Access to tank	NA NA	30,000 LTR	NA			
	Overhead Tank capacity	0	Provided	MR			
15 E	xit Signage.	Required	Provided				
16 P	Provision of Lifts.						
-	Pressurization of Lift Shaft	· N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	alexan N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding	N/A	N/A	N/A			
Je.	Switch	Required	Provided	MR			
Y	Lift Signage	Required	Provided	MR			
Ne.	tandby power supply	V		111			
18 R	efuge Area.	NUA	N/A	N/A			
l _p c	> Total Area	N/A		N/A			
	> Location	N/A	N/A	A. IN/A			
19 F	ire Control Room		70				
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
		000M005 =	N/A	N/A			
20 S	pecial Fire Protection Systems for rotection of special Risks, if any:	N/A	N/A	4			
*		C _s					

Note:-

It was observed that there is no space to construct overhead water tank at terrace level. Therefore applicant has provided 75,000 liters water tank for firefighting at underground. If agreed than point no.14 may be taken as meeting requirement.

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. F6/DFS/MS/2024/Indl./194 dated 18.04.2024 have been compiled by the management.

Keeping in view of satisfactory compliance of the minimum standards on fire prevention and fire safety required under the rules and fire safety guidelines issued vide letter of even no.F6/DFS/MS/BP/2024/12 dated 03.01.2024, it is recommended to issue Fire Safety Certificate.

D.B. Mukharjee (DO/NW)

Signature of the Inspecting Officer
Name :- C.L. Meena
Designation:- ADO/RN

127109/2024

Please du 'A', overhend lank cap.

75,000 lb vi provide al- under ground with boosting arrangements pump cap. 200 Left. I it is accepted, there For is recommended.

Denetaly 10 /2004

As approved F.T. letter is luxup for your signature blease.

108/10/2024 ADO(RM) OSO OSO