

No. F6/DFS/MS/School/NDZ/2024/ 1007

FIRE SAFETY CERTIFICATE

Certified that the Arwachin International School located at Pocket - B, Facility Centre, . Dilshad Garden, Delhi - 110095, building comprised of basement (Store), ground plus three upper floors owned/occupied by Arwachin International School, was issued FSC vide letter No. F6/DFS/MS/School/2021/ NDZ/722 dated 07/09/2021. The School building was re-inspected by the officer concerned of this department on 04/10/2024 in presence of Mr. Arun Sharma (Director) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules 2010 and that the premises is fit for occupancy class Group B "Educational Building with effect from 10/10/2024 for a period of three years, in accordance with rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on 10/10/2024 at New Delhi by.

Copy to:-

- 1. The Joint Director of Education (Land & Estate) Directorate of Education, Lucknow Road, Delhi - 110053.
- 2. The Principal, Arwachin International School located at Pocket B, Facility Centre, Dilshad Garden, Delhi - 110095.

Conditions for the validity of Fire Safety Certificate

- Fire Safety Certificate is valid for ground plus three upper floors only.
- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form Γ [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 3. All the means of escape shall be kept free of all the type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 7. At the time of inspection basement is being used for store purpose only.
- 8. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 9. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

			INSPEC	CTION REPORT			
At	ا ئىسىن	Name & address of the building Arwachin International School located at Pocket-					
01.	Na	Name & address of the building B, Facility Centre, Dilshad Garden, Delhi-110095.					
1	Building is comprised of Basement, ground plus three upper floors only.					ors only.	
02.	Ty	Type of occupancy Educational Building					
03.			f case	Renewal		-	
04.	13	pe o	of previous FSC	F6/DFS/MS/Scho	ol/2021/ NDZ/722 d	ated	
0 5.	De	tans	of previous 1 50	07/09/2021.	acce dentices of a secondary of the secondary		
			Cata dimentiares letter no	F.6/DFS/MS/BP/2003/1003 dated 15/05/2003.			
06.	Fire safety directives letter no.			04/10/2024			
0 7.	Da	te o	finspection	Yashwant Singh Meena ADO (L.N)			
0 8.	Na	me (of the inspecting officers				
09.	Name of the designation of			Mr. Arun Sharma (Director)			
	officer from the building side		from the building side				
10.	Ye	ar o	f construction	2005	*	2004	
11.	Applicant's letter no.			Outdoor Dairy No.6995 dated 25/03/2024			
			imum standard of fire	NBC Part - IV/	Provided at	Remarks	
S.No			ntion and fire safety U/R	Directives	site	MR/NMR	
	The state of the s		33	Requirement			
01.	1	2200					
UI.	A Road width			12 mtrs.	12 mtrs.	MR	
	<u> </u>		ate width	4.50 mtrs	06 mtrs	MR	
	B	W/	idth of internal road	NA	NA	NA	
02.	N.	ımh	er, Width, Type and Arran	ngement of Exits:			
UZ.	A Number of staircases						
	A	a	Upper floor	04 nos.	04 nos.	MR	
	-	b	Basement	02 nos.	02 nos.	MR	
	<u>_</u>		idth of staircases	V-			
	В	-		1.50 mtrs	1.50 mtrs	MR	
		a	Upper floor			NA	
	7====	b	Basement	NA	NA	INA	
	C	Pro	otection of exits		NA	NA	
		a	Fire check door	NA NA	NA NA	NA	
- Linear		b	Pressurization	NA 02 mg	03 nos.	MR	
No.	D		o. of continuous staircases	02 no	05 1103.	*****	
	-		terrace	1.50 mtrs.	02 mtrs	MR	
	E	-	idth of corridor	01 mtrs	1.20 mtrs	MR	
03.	F		oor size artmentation:	OTHES	1,20 11110		
05.	+-			NA	NA	NA	
	A	_	re check door ealing of electrical shafts	NA NA	NA NA	NA	
	1 12	1 2			NA	NA	
	B	_	re rating of shaft door	l NA	1477		
	CD	Fi	re rating of shaft door	NA NA	NA NA	NA	
	C	Fi	ater curtain	NA NA NA			
04.	C D E	Fi W Fi		NA	NA	NA NA	
04.	C D E	Fi W Fi nok	ater curtain re dampers	NA	NA	NA NA MR	

Arwachin International School located at Pocket-B, Facility Centre, Dilshad Garden, Delhi-110095.

05.	Fire Extinguisher:							
	A	Total numbers	23 nos.	35 nos	MR			
	В	Types	ABC/CO ₂	ABC/CO ₂	MR			
	C	ISI marking	ISI marked	ISI marked	MR			
06.	First-Aid-Hose Reel:							
	A	Total numbers of each floor	02 nos.	02 nos.	MR 🗸			
	В	Length of hose reel hose	30 mtrs	30 mtrs	MR			
	C	Nozzle diameter	05 mm	05 mm	MR			
07.	Automatic Fire Detection and Alarming System:							
	A	Type of detectors	N/A	N/A	N/A			
	В	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
08.	MO	DEFA:	Required	Provided	MR			
09	Pu	blic Address System:	Required	Provided	MR			
10.	Automatic Sprinkler System:							
	A	Basement	Required	Provided	MR 🗸			
	В	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants:							
11.	A	Size of riser/down-comer	N/A	N/A	N/A			
	B	Number of hydrants per floor	N/A	N/A	N/A			
	C	Hose box	N/A	N/A	N/A			
12.	Yard Hydrants:							
14.	A	Total number of hydrants	N/A	Provided	MR			
	B	Hose box	N/A	Provided	MR			
12		78537						
13.	Pumping Arrangements: Ground level							
1	-	Discharge of main pump	1650 LPM	1650 LPM	MR			
	A	Head of main pump	40 mtr	40 mtr	MR /			
	B	Number of main pumps	01 no	01 no	MR			
	C	Jockey pump out put	180 LPM	180 LPM	MR			
	D	Jockey pump head	40 mtr	40 mtr	MR			
	F	Standby pump out put	N/A	N/A	N/A			
			N/A	N/A	N/A			
	G	Standby pump head Auto starting /manual	Required	Provided	MR			
	H	stopping	required	11011404	1711			
	I	Pump house access	Required	Provided	MR			
	j-		<u> </u>					
2	Terrace Level							
7	A	Discharge of pump	450 LPM	450 LPM	MR			
	B	Head of the pump	40 m	40 m	MR			
II II	C	Power supply	Required	Provided	MR			

14.	Captive Water Storage for Fire Fighting:						
	A	Underground tank capacity	50,000 ltrs	50,000 ltrs	MR		
	В	Draw-off connection	N/A	N/A	N/A		
pro 1	C	Fire service inlet	N/A	N/A	N/A		
	D	Access to tank	N/A	N/A:	N/A		
N	E	Overhead tank capacity	20,000 liters	20,000 liters	MR		
15.	Ex	it Signage:	Required	Provided	MR		
16.	Provision of Lifts:						
	A	Pressurization of lift shaft	N/A	N/A	N/A		
	В	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	Required	Provided	MR		
	D	Firemen's grounding switch	Required	Provided	MR		
	E	Lift signage	Required	Provided	MR		
17.	Standby Power Supply:		N/A	N/A	N/A		
18.	Refuge Area:						
	A	Total area	N/A	N/A	N/A		
	В	Location	N/A	N/A	N/A		
19.	Fire Control Room:						
	A	Detector system panel	N/A	N/A	N/A		
	В	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A		
20.	Sp	ecial Fire Protection systems for	NA	N/A	N/A		
		otection of special Risks, if any:					

The fire protection systems provided in the school building were tested, checked at random and found functional at the time of inspections and basement is being used for store purpose only. The earlier shortcomings issued vide letter no. F6/DFS/MS/School/NDZ/2024/618 dated 10.09.2024 by this department have been rectified by the management.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of the FSC issued vide letter no. F6/DFS/MS/School/2021/ NDZ/722 dated 07/09/2021, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended to be renewed.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer

Name: - Yashwant Singh Meena

Designation: -

ADO (L.N)

DY. CFO/NDZ

8 10 20m

Another