## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No F 6/DFS/MS/2024/WZ/School/ 1018

## FIRE SAFETY CERTIFICATE

Dated: 14/10/2024

Certified that the D A V Public School located at Sector-07, Rohini, Delhi-110085 comprised of Ground + Three Upper floors owned/ occupied by D A V Public School was issued Fire Safety Certificated vide this office letter no. F.6/DFS/MS/2021/WZ/School/923 dated 05.11.2021. The premise was re-inspected by the officer concerned of this department on 06.09.2024 in the presence of Mr. Chiraj Chugh (Accountant) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from 14/10/2024 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 14/10/2024 at New Delhi

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, DAV Public School, Sec-07, Rohini, Delhi-110085.

## Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working

2. Loss of life or property due to non functional fire safety measure shall be at the

responsibility of the management.

3. The trained fire fighting staff should be available round the clock. 4. Any deviation with regard to the construction etc shall be verified by the concerned

5. This certificate cannot be treated in any case for regularizations of unauthorized

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

WWW.dfs.Delhigovt.nic.in

5		INS	PECT	1011				
1.	Name &	address of the building	TECT	ION REPORT				
2.	Type of	and cos () The build:						
3.	Type of Occupancy Type of Case			D A V Public School, Sec-07, Rohini, Delhi-110085.  Educational				
4.	Details of many			Renewal (Ground + 03 Upper floor)				
of picylous NOC				F.6/DFS/MS/2021/WZ/School/923 dated 05.11.2021				
6.	Date of	ety directives letter No inspection	NBC Part-04					
7	N.	inspection	06.09.2024					
7.	Name o	f the Inspecting Officers	A.K.	Sharma ADO (Rol	hini			
8.	Name a	nd designation of officers building side		Chiraj Chugh (Acc				
9. \	Year of (	onstruction	1004	2006				
10.	Applica	nt's letter No.		-2006	00 0004			
		inimum Standards on fire	Onn	ne e-mail dated 01				
	prev	ention and fire safety U/R	33	NBC Requirement	Provided at site	Remarks MR/NMR		
	Access	to building						
	•	Road width		Accessible	Accessible	MR		
	•	Gate width		Accessible	5 m	MR		
	•	Width of internal road		N/A-	-N/A-	-N/A-		
	Numb	er, Width, Type & Arrange	ement o			2 10 10 10 10 10 10 10 10 10 10 10 10 10		
	a. Num	ber of staircases						
	•	Upper Floors		04	04	MR		
	•	Basements		-N/A-	-N/A-	-N/A-		
	b. Wid	th of staircases						
					1.75m,1.36m,1.41			
	•	Upper Floors		1.50m	m, 1.80 m & 1.41-142m	MR		
	•	Basements		-N/A-	-N/A-	-N/A-		
	c. Protection of exits				T 220			
	Fire check door			-N/A-	-N/A-	-N/A-		
	Pressurization			-N/A-	-N/A-	-N/A-		
	d. No. of continuous staircases to t		errace	02nos.	Provided	MR -N/A-		
	e. Width of Corridor			-N/A-	-N/A-	MR		
	f. Doo			1 m	1 m	IVIK		
3	Comp	artmentation.		N/A-	-N/A-	-N/A-		
	•	Fire check door			-N/A-	-N/A-		
	•	Sealing of electrical shafts		-N/A- -N/A-	-N/A- -N/A-	-N/A-		
	•	Fire Rating of shaft door Water Curtain		-N/A-	-N/A-	-N/A-		
		Fire Dampers		-N/A-	-N/A-	-N/A-		
4	Smoke Management System.							
•	o mon	Basements		N/A-	-N/A-	-N/A-		
	-	Upper floors		12 a/c per hour	Natural Ventilated	MR		
5	Fi	re Extinguishers		de inches				
	+	Total numbers		30 nos	30 nos	MR		
	•			ABC/Co2	ABC-26 / Co2- 4	MR		
	-	Types     ISI marking		_ISI Marked	Yes	MR		
6	First-Aid Hose Reels.			L -				
	A II St	Total numbers on each floo	r	03 each floor	Provided	MR		
	•			30m	Provided	MR		
1	•	Length of hose reel hose Nozzle diameter		5mm	Provided	MR		
		Nozzie diameter						
-	1	natic fire detection and ala	rming !	system.				
7	Auto	matic fire detection and ala Type of detectors	rming !	system. 	-N/A-	-N/A-		

				No.		
	Location of Repeater Panel	-N/A-	-N/A-	-N/A-		
	Alternate source of power	-N/A-	-N/A-	-N/A-		
	Hooters' Location	-N/A-	-N/A-	-N/A-		
		Required	Provided	MR		
8	MOEFA	NA	NA	NA		
9	D. N. Address System.		*			
10	Automatic Sprinkler System.	-N/A-	-N/A-	-N/A-		
10	Basement	-N/A-	-N/A-	-N/A-		
	Linner Floor	-N/A-	-N/A-	-N/A-		
	Sprinkler above false ceiling	1,1,1				
	Latermal Hydrants	100mm	Provided	MR		
11	o' - of ricer/down-come	03	Provided	MR		
	Name of hydrants per floor		Provided	MR		
	Number of fly drawn 1	03	110110			
	Hose Box		Provided	MR		
2	Yard Hydrants.	03	Provided	MR		
	Total number of hydrants	03	Provided			
	Hose Box					
3	Pumping Arrangements.		-N/A-	-N/A-		
	- Ground Level	-N/A-		-N/A-		
	> Discharge of main Pump	-N/A-	-N/A-	-N/A-		
	> Head of Main pump	N/A-	-N/A- -N/A-	-N/A-		
	> Number of main pumps	-N/A-		-N/A-		
	> Jockey Pump out put	-N/A-	-N/A-	-N/A-		
	> Jockey pump head	-N/A-	-N/A-	-N/A-		
	Standby Pump out put	-N/A-	-N/A-	-N/A-		
	> Standby Pump Head	-N/A-	-N/A-	-N/A-		
	> Auto Starting/ Manual stopping	-N/A-	-N/A-	-N/A-		
	> Pump House Access	= 1.00%		100		
	Terrace level	900 lpm	Provided	MR		
	Discharge of pump	36m	Provided	MR		
	> Head of the pump	Required	Provided	MR		
	> Power Supply	- Required	Provided	MR		
	> Auto Starting of pump					
4	Captive Water Storage for fire fighting	-N/A-	-N/A-	-N/A-		
	Underground tank capacity	-N/A-	-N/A-	-N/A-		
	> Draw-off connection	-N/A-	-N/A-	-N/A-		
	> Fire service inlet	-N/A-	-N/A-	-N/A-		
	> Access to tank	10,000 ltrs	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
5	Exit Signage.					
6	Provision of Lifts.  • Pressurization of Lift Shaft	-N/A-	-N/A-	-N/A-		
	Pressurization of Lift Shart     Pressurization of Lift lobby	-N/A-	-N/A-	-N/A-		
	Communication In lift Car	-N/A-	-N/A-	-N/A-		
	Fireman's Grounding Switch	-N/A-	-N/A-	-N/A-		
	Lift Signage	-N/A-	-N/A-	-N/A-		
17	Standby power supply	N/A	125 KVA	MR		
18	Refuge Area.					
	> Total Area	-N/A-	-N/A-	-N/A-		
	➤ Location	N/A-	-N/A-	-N/A-		
9	Fire Control Room					
	Detector System Panel	-N/A-	-N/A-	-N/A-		
	Flow Switch Panel	-N/A-	-N/A-	-N/A-		

20	•	PA System Panel	7		
		Batter backup	-N/A-	-N/A-	-N/A-
			N/A-	-N/A-	-N/A-
	Special	Building Floor Plans	-N/A-	-N/A-	-N/A-
	Protect	A Fire Protection Systems for ction of special Risks, if any:	-N/A-	-N/A-	-N/A-

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2021/WZ/School/923 dated 05.11.2021 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Designation ADO (Rohini)

DO (NW) Jon lave

FT letter to port up for kind porwal and Signature plean.