

c/61

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI-110001**

Dated...04/10/2024

No. F.6/DFS/MS/EH/2024/SZ/ 317

**FIRE SAFETY CERTIFICATE**

Certified that the Eating House in the name & Style of **M/s Evergreen Sweet House**, located at Ground & First Floor only, S-29 & 30, Green Park, Market, New Delhi 110016 in the building Comprised of Basement, Ground Plus Three Upper Floors owner/occupied by Mr. Mohan Lal Chopra (Partner) was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/SZ/2019/2084 Dated 30/10/2019. The restaurant premise was re-inspected by the officer concerned of this department on 26/09/2024 in the presence of Mr. Yatin Chopra found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** Restaurant at Ground Floor only and **validity upto 31/03/2027** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 04/10/2024 at New Delhi by

(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Joint Commissioner of Police (Lic) 1<sup>st</sup> Floor, PS Defence Colony, New Delhi 110049. (Ref. MHA Portal ID 2024091614307 dated 16/09/2024)

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
5. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



n/20

## INSPECTION REPORT



1	Name & Address of the Building	M/s Evergreen Sweet House, S-29 & 30, Green Park, Market, New Delhi 110016		
2	Type of Occupancy	Restt. running at Ground & First Floor only		
3	Building Comprised of	Basement, Ground plus three upper floor		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/SZ/2019/2084 Dt. 30/10/2019		
6	Fire Safety Directives Letter No	NBC / BBL Requirement		
7	Date of Inspection	26/09/2024		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Yatin Chopra		
10	Year of construction	2004		
11	Applicant letter No.	MHA Portal ID 2024091614307 dated 16/09/2024		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	Road width	Accessible	09 mtr	MR
	Gate width	Required	02 mtr	MR
	Width of internal road	N/A	N/A	N/A
2	Number, width, type & arrangement of exits.			
	a. Number of Staircase			
	Upper floors.	Required	02 No	MR
	Basement floor.	Required	03 No	MR
	b. Width of Staircase			
	Upper floors	Required	1.15m & 1 m	Old case
	c. Basement floor	Required	1.05 m, 1 m, & 0.95 m	Old case
	d. Protection of exits			
	Fire check door	Required	Provided	MR
	e. Pressurization	N/A	N/A	N/A
	f. No. of continuous staircase to terrace	N/A	N/A	N/A
	g. Width of corridor	N/A	N/A	N/A
	h. Door size	2 exits	1.87 m x 3 no	MR
3	Compartmentation.			
	Fire check door.	Required	Provided	MR
	Sealing of electrical shafts.	N/A	N/A	N/A
	Fire rating of shaft door.	N/A	N/A	N/A
	Water curtain	N/A	N/A	N/A
	Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.			
	Basement	12 ACPH	Provided	MR
	Upper floors	12 ACPH	Provided	MR
5	Fire Extinguishers.			
	Total numbers	Required	30 Nos	MR
	Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR
	ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.			
	Total numbers on each floor.	One	Provided	MR
	Length of hose-reel hose.	30m	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming system.			
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A



	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Restaurant area	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	Required	100 mm	MR
	Number of Hydrant per floor	Required	One	MR
	Hose box.	Required	One	MR
12	Yard Hydrants.			
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	Provided	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	Required	10,000 ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A

m/22

	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 93 dated 07/03/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2019/2084 Dt. 30/10/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

*mu*  
Signature of the Inspection Officer  
Name: Sh. Manoj Kumar Sharma  
Design: DO (South)

*15/2/24*  
Signature of the Inspecting Officer  
Name: Sh. Rajesh Kumar  
Design: ADO (BCP)

CFO(HQ)

*High*  
*30/9/2024*  
*Director*  
*11/11/24*

*mu*  
*Amr BCP*

As approved, F.T. letter is put up for  
your signature pl.  
*1/14*  
*03/10/2024*

*Director*  
*mu*

*Uploaded*  
*04/10/24*