

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/EH/2024/SZ/640

Dated. 18... //. D... / 2024

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name and Style of M/s TOSCANO located at S-44, Second Floor, Nexus Select City Walk Mall, A-3, District Centre, Saket, New Delhi- 110017 in the building comprised of 03 tier Basement ground plus 07 upper floors owner/occupied by A Unit of Red Apple Kitchen consultancy Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 14/10/2024 in the presence of Mr. Rajesh Kumar and that the premises is fit for occupancy class "Group-D Assembly Building" (Restaurant running at Second Floor only) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service? Rules, 2010.

Issued on 16 /10 /2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch 1st Floor PS Defence Colony, New Delhi 110049. (Ref. MHA Portal ID 2024092414686 dated 09/10/2024)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



		TON REPORT	(A II - C D - 1 A - 1	YE'. 6		
	Name & Address of the Building	M/s TOSCANO (A Unit of Red Apple Kitchen				
m/	Apply out 1 to 1 to 1	consultancy Pvt Ltd) located at S-44, Sec		nd Floor,		
	The second of th	Nexus Select City Walk Mall, A-3, District Centre, Saket, New Delhi- 110017				
	Line Mark & Differential Line Line Line Line Line Line Line Line					
4	Type of Occupancy	Group-D Assembly Building. (Restaurant)				
ji w	Building Comprised of	03 tier Basements, Ground + 07 Upper Floors				
JH	Type of Case	New Case				
	Details of Previous NOC	F6/DFS/MS/EH/2023/SZ/57 dated 10/02/2023				
DZ	Fire Safety Directives Letter No	F.6/MS/DFS/BP/2006/1141 dated 15/05/2006 &				
	The Salety Breedives Botter No	F.6/MS/DFS/BP/2016/299 dated 23/11/2017 for Mall				
a IV	Date of Inspection	14/10/2024				
5.5	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
)	Name & Designation of Officers	Mr. Rajesh Kumar				
	from the building side	1				
0	Year of construction	2006 Restt located at Second Floor only.				
1	Applicant letter No.	MHA Portal ID 2024092414686 dated 09/10/2024				
	10.1 - 10.2		emin cres le Lest.			
S.	Minimum standards on Fire Prevention	UBBL -2016	Provided at Site	Remarks		
No.	and Fire Safety U/R 33	Requirements	for any partial wall only	MR/NMI		
	Access to Building. (Select Cit	y Walk Mall - F.6/DFS	/MS/Mail/2022/SZ/335 Dt. 2	7/07/2022)		
	Road width	9m	Provided by Mall	MR		
	Gate width	5m	Provided by Mall	MR		
	Width of internal road	11/2/2000	Provided by Mall	MR		
154]6	Width of Internal Toda	6m	the state of search	IVIIC		
2	Number, width, type & arrangement of exits	<b>.</b>				
	Number of Staircase	Provided & Maintained by Select City Walk, Saket				
	Upper floors.	02 Nos	12 Nos Provided*	MR		
	Basement floor.	N/A	N/A	N/A		
			ntained by Select City Wall	ECCONOMIC ELECTRIC		
	Width of Staircase					
Salac	Upper floors	1.50 mtr each	Provided*	MR		
	Basement floor	N/A	medical de N/A magazine	N/A		
	Protection of exits	Provided & Maintained by Select City Walk, Saket				
	Fire check door	Required	Provided*	MR		
			Provided*	MR		
19.1		Required				
	Np. of continuous staircase to terrace	Restt within Mall		MR		
	Width of corridor	Required	Provided	MR		
	Door size	1.50 mtr each	1.50 m & 1.50 m	MR		
3	Compartmentation.		intained by Select City Wa			
- 5	Fire check door.	Required	Provided*	MR		
	Sealing of electrical shafts.	Required	Provided*	MR		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
1	Fire dampers.	N/A	N/A	N/A		
4	Smoke Management system.	Provided & Maintained by Select City Walk, Saket				
	Basement	30 ACPH	N/A	N/A		
	Upper floors	12 ACPH	Exhaust Fans Provided			
5	Fire Extinguishers.	120111	ACCESSED A MILE I TO VICTOR			
-	Total numbers	Required	10 Nos	MR		
VA.	Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR		
	ISI Marking					
6	First Aid Hose Reels.	Required	Provided	MR		
0	Total numbers on each floor.		aintained by Select City W			
29		One near Rest		MR		
1	Length of hose-reel hose.	30m	Provided*	MR		
-	Nozzle Diameter	5mm	Provided*	MR		
7	Automatic fire detection & alarming syste		Maintained by Select City			
	Type of detectors	Required	Smoke & heat	MR		
	Location of Main Panel	Required	Provided*	MR		
	Location of Repeater Panel	Required	Provided*	MR		
	Alternate source of power	Required	Provided*	MR		
	Hooter's location	Required	Provided*	MR		
8	MOEFA	Required	Provided*	MR		
9						



0	Automatic Sprinkler System	Provided & Maintained by Select City Walk, Sake			
71.7	Dasement	Required	Provided*		
	Upper floor	Required		MR	
1	Sprinkler above false ceiling	N/A	Provided	MR	
Ţ	Internal Hydrants.		N/A	N/A	
	CONTRACTOR OF THE PROPERTY OF	Provided & Maintained by Select City Walk, Saket			
	Size of Riser/Down-comer	Required	Provided*	l vo	
	Number of Hydrant per floor Hose box.	One near Restt	Provided*	MR	
2	Yard Hydrants.	One near Restt	Provided*	MR	
	- and Trydrams.	Provided & Main		MR Walk Salvet	
	Total number of hydrants.	Provided & Maintained by Select City Walk, Saket			
	1108C 00X.	N/A	As above	N/A	
3	Pumping arrangements.	N/A	As above	NI/A	
-		Provided & Maintained by Select City Walk, Saket			
	Ground Level				
	Discharge of main pump.	Common pumping arrangements for entire bldg			
	1 Icau Of main nume	4300 LPM	Provided*	MR	
	Number of main numer	88m	Provided*	MR	
	Jockey Pump Output	02 Nos.	Provided*	MR	
	Jockey Pump head	180 LPM	Provided*	MR	
	Standby Pump output	88m	Provided*	MR	
	Standby Pump hood	4500 LPM	Provided*	MR	
	Auto Starting/Manual Stopping.	88m	Provided*	MR	
	amp house access.	and the second s	Provided*	MR	
	Terrace Level	Required	Provided*	MR	
	Discharge of pump.	450		1	
	Head of pump	450 LPM	Provided*	MR	
	Power supply.	40 m	Provided*	MR	
	Auto starting of pump.	Required	Provided*	MR	
14	Captive water storage for fire fighting	Required	Provided*	All III	
	Underground tank capacity	Provided & Maintained by Select City Walk, Saket			
	Draw-off connection.	Required	3,00,000 ltrs	MR	
	Fire Service Inlet.	Required	Provided	MR	
5110	Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	Required	Provided	MR	
15	Exit Signage.	Required	30,000 Ltrs Provided	MR	
16	Provision of Lifts.		Stiffing in all	MR	
	Pressurization of lift shaft.	Provided & Maintained by Select City Walk, Saket			
	Pressurization of lift lobby.	N/A	As above	N/A	
	Communication in lift car.	N/A	As above	N/A	
	Fireman's switch.	N/A	As above	N/A	
	Lift signage.	N/A	As above	N/A	
17	Standby Power Supply	N/A	As above	N/A	
-1/	TOWN OF A TOWNS OF THE DESTRICTION OF POLICE	Required	Provided	MR	
18	Refuge Area	K-11			
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room.	Provided & Mai	ntained by Select City	Walk, Saket	
- 4.1	Detector system panel.	N/A	As above	N/A	
	Flow switch panel.	N/A	As above	N/A	
	PA system panel.	N/A	As above	N/A	
	Battery backup.	N/A	As above	N/A	
	Building floor plan.	N/A	As above	N/A	
				N/A	



The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Rajesh Kumar

Designation: ADO / BCP