



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

F.6/DFS/MS/EH/2024/SZ/ 334 No.

Dated: 14/10/2024

FIRE SAFETY CERTIFICATE

Certified that M/s Encalm Lounge (A Unit of Encalm Hospitality Pvt. Ltd.), D-49 located at Mezzanine Level, Domestic Departure, Terminal-3, IGI Airport, New Delhi-110037 of a building comprised of Two-Tier Basement, Ground & Five Upper Floors issued FSC vide letter No. 602 dated 18/12/2023. The restaurant at mezzanine level, has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 04/10/2024 in the presence of Mr. JP Singh (Manager) and that the said premises is fit for occupancy class "Assembly Group D" (Eating House) with effect from the date of issue of this certificate for a period upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service Rules, 2010.

Issued on 14/10/2024 at New Delhi by

DELHI FIRE SER

Copy to: -

- 1. The Joint Commissioner of Police (Lic.), 1st Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. MHA ID No. 2024081212580 dated 16/09/2024)
- 2. Authorized Signatory M/s Encalm Lounge (A Unit of Encalm Hospitality Pvt. Ltd.), D-49, Mezzanine Level, Domestic Departure, Terminal-3, IGI Airport, New Delhi-110037

Conditions for the validity of Fire Safety Certificate:

- All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working 1. conditions at all time as seen during inspection. Any loss of life property due to non-functional 2. fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of firefighting system.
- The owner/occupier shall submit a declaration every year in form "K" provided in the first 3. schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 4.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any. 5.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its 6. expiry".

		the building	M/s Encalm Lounge (A Unit of Encalm Hospitality Pvt. Ltd.), D-49, Mezz. Level, Domestic Departure, Terminal–3, IGI Airport, New Delhi–110037			
2. Type of Occupancy			Assembly Group D			
3		Building Comprised of	Two Basement, Gro	ound & 5 Upper F	loors but	
4	1.	Type of Case	restaurant running a	at Mezzanine level	only.	
5. Details of previous NOC			New			
			Nil			
_	7.	Date of inspection	F6/DFS/MS/2007/1781 dated 05/07/2007 (Bldg) 04/10/2024 ADO (SJ)			
	8.	Name of Inspecting Officer				
L	9.	Name and designation of Officer				
ľ		from building side	Mr. JP Singh (Man	ager)		
1	0.	Year of Construction	2010			
L	11.	Applicant letter No./Online MHA	2010 THE WORLD	3500 1 116/00	2024	
L	S.	Minimum standards on fire	ID No. 202408121 NBC/UBBL		THE STREET STREET	
L	No.	prevention and fire safety U/R 33	Requirements		Remarks MR/NMR	
Ī	1.		FSC No. F6/DFS/MS			
ı		Road width	Restt within	As above	MR	
١		Gate width	Terminal-3	As above	MR	
		 Width of internal road 	Building	As above	MR	
	2.	Number, width, Type & Arrangement	s of exits			
١		a. Number of staircases	Provided & Main	tained by T-3 Bld	g. Mgmt.	
		 Upper floors 	Restt. within T-3	As above	MR	
		Basements	NA	As above	NA	
		b. Width of staircases	Provided & Mair	ntained by T-3 Blo	lg. Mgmt.	
		 Upper floors 	Restt. within T-3	As above	MR	
		Basement	NA	As above	NA	
		c. Protection of exits	Provided & Main	ntained by T-3 Blo	dg. Mgmt.	
		Fire check door	Restt. within T-3	As above	MR	
		Pressurization	Restt. within T-3	As above	MR	
		d. No of continuous staircase to terrace		As above	MR	
		e. Width of Corridor	Restt. within T-3	As above	MR	
_	1	f. Door Size	Restt. within T-3	As above	MR	
_	3.	Compartmentation	Provided & Mai	ntained by T-3 Bl	dg. Mgmt	
		Fire check door	Restt. within T-3	As above	MR	
	1	 Sealing of electrical shafts 	Restt. within T-3	As above	MR	
	1	 Fire Rating of shaft door 	Restt. within T-3	As above	MR	
		Water Curtain	Restt. within T-3	As above	MR	
		Fire Dampers	Restt. within T-3	As above	MR	
	4. Smoke managements System		Provided & Maintained by T-3 Bldg. Mgmt			
	1	Basements	NA	As above	NA NA	
		Upper floors	Restt. within T-3	As above	MR	
	5.	Fire Extinguishers				
		Total numbers		06 Nos	MR	
		• Types	ISI marked	ABC & CO ₂		
		ISI marking		Required	MR	
	6.	First-Aid Hose Reels	Provided 9- NA		1	
		Total numbers on each floor	Restt. within T-3	nintained by T-3 E		
		Length of hose reel hose	Restt. within T-3	and near ices		
		Nozzle diameter	Restt. within T-3		MR	
-			1.cott. within 1-3	5mm	MR	

7.	Automatic fire detection & alarming sy	stem (Provided & N	Jaintained by T-3 Ride	Mamt)
	Type of detector	Restt. within T-3	Smoke & Heat	MR
	Location of Main Panel	Hotel within T-3	Upper Basement	MR
	r .: cnn1	Hotel within T-3	Provided	MR
		Hotel within T-3	Provided	MR
	Alternate source of power	Hotel within T-3	All Areas	MR
_	Hooters' Location	Restt. within T-3		
8. 9.	MOEFA Public Address System	Restt. within T-3	Provided Provided	MR MR
10.	Automatic Sprinkler System		ntained by T-3 Bldg	
10.	Basements	NA NA	As above	NA
	Upper floors	Restt. within T-3	As above	MR
		Restt. within T-3	As above	MR
11.	Sprinkler above false ceiling Internal Hydrants		ntained by T-3 Bldg	
11.	Size of riser/down- comer	Restt. within T-3	150 mm	MR
		Restt. within T-3	2nos near Restt.	MR
	Number of hydrants per floor Hass Pay	Restt. within T-3	2nos near Restt.	MR
12	Hose Box Vand Hadranta			
12.	Yard Hydrants		ntained by T-3 Bldg.	NA NA
	Total number of hydrants	NA	As above	
	Hose Box	NA	As above	NA
13.	Pumping Arrangements	Provided & Maii	ntained by T-3 Bldg.	Mgmt.
	Ground Level		4721 0 2705 I DM	MD
	➤ Discharge of main pump	Restt. within T-3	4731 & 3785 LPM	MR
	> Head of main pump	Restt. within T-3	130m & 70m	MR
	> Number of main pumps	Restt. within T-3	Two (1 + 1)	MR
	> Jockey pump out put	Restt. within T-3	280 LPM x 2	MR
	> Jockey pump head	Restt. within T-3	130m & 80m	MR
	Standby Pump out put	Restt. within T-3	4731 & 3785 LPM	MR
	Standby Pump Head	Restt. within T-3	130m & 70m	MR
	Auto Staring/Manual stoppingPump House Access	Restt. within T-3	Provided	MR
		Restt. within T-3	Provided	MR
	Terrace level	NI A	NA	NA
	Discharge of pump	NA	NA NA	NA
	Head of the pump	NA		NA
	Power supplyAuto starting of pump	NA	NA NA	NA
14	5 - F F	NA Decided 8 Mail		
14.	Captive water Storage for firefighting		ntained by T-3 Bldg	MR.
-	 Underground tank capacity Draw of connection 	Restt. within T-3 Restt. within T-3	6,00,000 Ltr Provided	MR
	Fire service inlet	Restt. within T-3	Provided	MR
	Access to tank	Restt. within T-3	Provided	MR
1.	Overhead Tank capacity	NA	NA	NA
15.		Required	Provided	MR
16.	> Pressurization of Lift Shaft		ntained by T-3 Bldg.	
	 Pressurization of Lift Shaft Pressurization of lift lobby 	NA NA	As above	NA
	Communication in lift Car	NA	As above	NA
	Fireman's Grounding Switch	NA NA	As above	NA
	➤ Lift Signage	NA NA	As above	NA
17		Restt. within T-3	As above	NA MR
18	. Refuge Area	Acott. Within 1-3	As above	IVIK
	> Total area	NA	NA	NA
	> Location	NA	NA	NA

19.	Fire Control Room	Provided & Maintained by T-3 Bld		MR
1.	➤ Detector system panel	Restt. within T-3	As above	
		Restt. within T-3	As above	MR
	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	Restt. within T-3 Restt. within T-3 Restt. within T-3	As above	MR
			As above	MR
			As above	MR MR

Manager of Note:

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The shortcomings communicated vide this department letter No. F.6/DFS/MS/EH/SZ/2024/318 dated 02/08/2024 found complied,

In view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rule, issue of fire safety certificate under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)

L

3 :8

DO (\$D) What about FSC of building Aro (51)
Sir, Fisc of main probling (73) in
placed c/s prease.