

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

र्गाजादी म अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2024/ 1061

Dated: 25/10/2024

FIRE SAFETY CERTIFICATE

Certified that Sidharth Lekha Public School located at C-3/121, Saboli Extn., (Mandoli Chungi) Nand Nagri, Delhi - 110093, comprised of Ground plus two upper floor only (School is running on ground plus first floor only & second floor used as residence of owner.) owned / occupied by Sidharth Lekha Public School, was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/2021/269 dated 30/03/2021. The school buildings was re-inspected by the officer concerned of this department on 10/10/2024 in the presence of Mrs. Yogita (Principal) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by the Director of Education and observed that the school building is fit for ground plus 1st floor, occupancy class Group - B "Educational Building" with effect from 25/10/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions printed bellow.

Issued on 25/10/2024 at New Delhi by.

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, B-Block, Yamuna Vihar, Delhi-110053.

2. The Principal, Sidharth Lekha Public School located at C-3/121, Saboli Extn., (Mandoli Chungi) Nand Nagri, Delhi - 110093.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

NN

1				INSPEC	CTION REPORT		1 1 10 10 10			
1		Na	me	& address of the building	Sidharth Lekha Public School located at C-3/121, Saboli Extn., (Mandoli Chungi) Nand Nagri Delhi - 110093. Ground plus two upper floor only (School is running on ground plus first floor only & second floor used as residence of owner.)					
2		Bı	iild	ing is comprised of						
3		Ty	ре	of occupancy	Educational Building					
4		Type of case		Renewal						
5		D	tai	ls of previous FSC	F6/DFS/MS/School/2021/269 dated 30/03/2021					
6		Fire safety directives letter no.		afety directives letter no.	F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011.					
7		Date of inspection			10/10/2024					
8		N	me	of the inspecting officers		h Meena ADO (L.N)	٧)			
9		N	ame	of the designation of officer the building side	/ - · · ·					
10		Y	ar	of construction	2009 Outdoor Dairy No. 7297 dated 03/10/2024					
11		Applicant's letter no. Minimum standard of fire		linimum standard of fire	Outdoor Dairy Circular Requirement	Provided at site	Remarks MR/NMR			
S	No			ention and fire safety U/R 33						
1		Access to Building:		The state of the s	COtwo	6.0 mtrs.	MR			
		A	R	load width	6.0 mtrs.	N/A	N/A			
		В		ate width	N/A	N/A N/A	N/A			
		C		Vidth of internal road	N/A	N/A	14/21			
2		N	ıml	oer, Width, Type and Arrang	gement of Exits:					
1		A Number of staircases			11157	L HOLD	1 . m			
			a	Upper floor	01 nos.	02 nos. (MR N/A			
	10		b	Basement	N/A	N/A	10/11			
		В	a	Vidth of staircases Upper floor	1.5 mtrs	0.87 mtrs& 0.88 mtrs	MR			
١			b	Basement	N/A	N/A	N/A			
		C		rotection of exits		AUT U				
١			a	Fire check door	N/A	N/A	N/A			
١				Pressurization	N/A	N/A	N/A MR			
		D		o. of continuous staircases terrace	01 no	02 nos.	MIK			
		E		idth of corridor	1.5 mtrs.	1.50 mtrs. /	MR			
1	ł	F	D	oor size	1.0 meter.	1.0 meter. /	MR			
t	1	Compartmentation:								
1		A	Fi	re check door	NA	NA	NA			
		В	Se	aling of electrical shafts	N/A	N/A	N/A			
	-	C	Fi	re rating of shaft door	N/A	N/A	N/A			
	_	D		ater curtain	N/A	N/A	N/A			
	(A)	E	Fi	re dampers	N/A	N/A	N/A			
T	Smoke Management System:									
		A	Ra	sement	N/A	N/A	N/A			
T			Du	001110111						

1 N/12

Siddharth Lekha Public School, C-3/121, Saboli Extn., (Mandoli Chungi, Nand Nagri), Delhi-11

5.	Fire Extinguisher:						
411	A	Total numbers	04 nos.	06 nos.	MR		
	В	Types	CO ₂ & ABC	CO₂& ABC	MR		
A	C	ISI marking	ISI Marked	Provided	MR		
6	TOSES II	st-Aid-Hose Reel:					
<u> </u>	A	Total numbers of each floor	N/A	N/A	N/A		
	B	Length of hose reel hose	N/A	N/A	N/A		
	C	Nozzle diameter	N/A	N/A	N/A		
7	Automotic Fire Detection and Alarming System:						
	-	Type of detectors	N/A	N/A	N/A		
	A	Location of main panel	N/A	N/A	N/A		
	B	Location of main paner Location of repeater panel	N/A	N/A	N/A		
	C	Alternate source of power	N/A	N/A	N/A		
	D	Alternate source of power	N/A	N/A	N/A		
	E	Hooter's Location	N/A	N/A	N/A		
8		OEFA:	N/A	N/A	N/A		
9	Pu	blic Address System:	437.5	office Gas	T ALL		
10	At	itomatic Sprinkler System:	N/A	N/A	N/A		
	A	Basement	N/A	N/A	N/A		
	В	Upper floor	N/A	N/A	N/A		
10.0	C		IV/A	7.0			
11	In	ternal Hydrants:	N/A	N/A	N/A		
25	A	Size of riser/down-comer	N/A N/A	N/A	N/A		
-	B	Number of hydrants per floor	N/A N/A	N/A	N/A		
	C	Hose box	IN/A	<u> </u>			
12		ard Hydrants:	NT/A	N/A	N/A		
12	A	Total number of hydrants	N/A	N/A	N/A		
	B	Hose box	N/A	THAT IT SIE TO	LINE I		
12	- A managements:						
13	C and love						
1	-	Discharge of main pump	N/A	N/A N/A	N/A N/A		
	A	Head of main pump	N/A		N/A		
	B	Number of main pumps	N/A	N/A	N/A		
	C	Jockey pump out put	N/A	N/A	N/A		
	D	Jockey pump head	N/A	N/A	N/A		
	E	Standby pump out put	N/A	N/A	N/A		
	F		N/A	N/A	N/A		
	G	Standby pump head Auto starting /manual	N/A	N/A	IN/A		
	H		a la cita	NT/A	N/A		
	-	stopping Pump house access	N/A	N/A	1071		
_							
2			N/A	N/A	N/A N/A		
	A	Discharge of pump	N/A	N/A			
ļ	B	Head of the pump Power supply	N/A	N/A	N/A		
	$C \mid$	Power supply	N/A	N/A	N/A		

W

N/13

Siddharth Lekha Public School, C-3/121, Saboli Extn., (Mandoli Chungi, Nand Nagri), Delhi-110093.

Jein	1-11	0093.			111			
14	Captive Water Storage for Fire Fighting:							
P.	A	Underground tank capacity	N/A	N/A	N/A			
4	В	Draw-off connection	N/A	N/A	N/A			
	C	Fire service inlet	N/A	N/A	N/A			
	D	Access to tank	N/A	N/A	N/A			
. V	E	Overhead tank capacity	N/A	N/A	N/A			
15		it Signage:	N/A	N/A	! N/A			
16	Provision of Lifts:							
	A	Pressurization of lift shaft	N/A	N/A	N/A			
	B	Pressurization of lift lobby	N/A	N/A	N/A			
	C	Communication in lift car	N/A	N/A	N/A			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	N/A	N/A	N/A			
17		andby Power Supply:	N/A	N/A	N/A			
18	Defuge Avec							
10	A	Total area	N/A	N/A	N/A			
	B	Location	N/A	N/A	N/A			
19	Eine Control Poom:							
1)	1000	Detector system panel	N/A	N/A	N/A			
	B	Flow switch panel	N/A	N/A	N/A			
	C	PA system panel	N/A	N/A	N/A			
	D	Battery backup	N/A	N/A	N/A			
	E	Building floor plans	N/A	N/A	N/A			
20	Sp	ecial Fire Protection systems for otection of special Risks, if any:		. pd -	N/A			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2021/269 dated 30/03/2021 under the Circular no. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

No file is pending with me before disposal of this case.

15 10 10 14 Signature of the Inspecting Officer Name Yashwant Singh Meena

Designation ADO/ Laxmi Nagar

DY. CFOUNDZ

21 10 2001

Director

Andto

P.J.D