GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2024/SZ/415

Dated: .15././0./2024

FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style M/s Hotel Classic Park located at E-52, Near Corporation Bank, Vasant Kunj Road, Mahipalpur, New Delhi 110037 comprised of Basement (other property) Ground floor, 1st to 3rd floor (05 Guest Room each), Total- 15 Guest/Rooms was issued Fire Safety Certificate by this department vide letter No F6/DFS/MS/GH/2021/SZ/452 dated 30/09/2021. The premise was reinspected by the officer concerned of this department on 07/10/2024 in the presence of Mr. Anil Kumar and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" and validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on _____15 || 0./2024 at New Delhi by

(ATUL GARG) DIRECTOR DELHI FIRE SERVICE

Oh

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID No 2024091914383 dated 19/09/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



| | INSPECTIO | N REPORT | | | |
|-----|--|---|--------------------------|-------------------|--|
| 1 | Name & Address of the Building M/s Hotel Classic Park, E-52, Near Corporation | | | | |
| - 1 | , a lease of the same of the s | Bank, Vasant Kunj Road, Mahipalpur, New | | | |
| | | Delhi 110037 | J coud, manipulpur, i | 1011 | |
| W. | Type of Occupancy | Residential, "Group-A" (Guest House) | | | |
| 1 | Dunding Comprised of | Basement (other property), Ground + 03 upper floors | | | |
| 1 | Type of Case | Renewal | operty), Ground - 05 up | per moors | |
| 5 | Details of Previous NOC | F6/DFS/MS/GH/2 | 2021/SZ/452 dated 30/09/ | 2021 | |
| 6 | Fire Safety Directives Letter No | Nil | | | |
| 7 | Date of Inspection | 07/10/2024 | | | |
| 8 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | | |
| 9 | Name & Designation of Officers from the building side | Mr. Anil Kumar (Manger) | | | |
| 10 | Year of construction | 2009 Total 15 Guest room | | | |
| 11 | Applicant letter No. | MHA Portal ID No 2024091914383 dated 19/09/2024 | | | |
| No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC | Provided at Site | Remarks MR/NMR | |
| 1 | Access to Building. | requirements | | IVIIV/IVIIV | |
| - | Road width | Required | 09 mtr | MR | |
| | Gate width | -NA- | -NA- | -NA- | |
| | Width of internal road | -NA- | -NA- | -NA- | |
| 2 | Number, width, type & arrangement of exits. | TIM | Disease in the Line Con- | 1 - 1 | |
| | a) Number of Staircase | | No. of the second second | | |
| | | THE GROOM | GF to FF- 02 Nos | | |
| | > Upper floors. | Required | FF to Terrace- 01 No | MR | |
| | ➤ Basement floor. | -NA- | -NA- | -NA- | |
| | b) Wilds of Chairman | -NA- | -NA- | -IVA- | |
| | b) Width of Staircase > Upper floors | | GF to FF- 1.66 m each | MR | |
| | Basement floor | 1.25 mtr | FF to Terrace- 1.66 m | | |
| | Basement floor | NIA | -NA- | -NA- | |
| | | -NA- | -NA- | -NA- | |
| | c) Protection of exits > Fire check door | -NA- | -NA- | -NA- | |
| | | -NA- | -NA- | -NA- | |
| | > Pressurization | | | | |
| | d) No. of continuous staircase to terrace | | 01 Provided | MR | |
| | e) Width of corridor | -NA- | -NA- | -NA- | |
| - 6 | f) Door size | - im | 1.15 m (Final exit) | MR | |
| 3 | Compartmentation. Fire check door. | -NA- | -NA- | -NA- | |
| | Sealing of electrical shafts. | -NA- | -NA- | -NA- | |
| | Sealing of electrical sharts. Fire rating of shaft door. | -NA- | -NA- | -NA- | |
| F | Water curtain | -NA- | -NA- | -NA- | |
| | Water curtain Fire dampers | -NA- | -NA- | -NA- | |
| - 1 | | | .31 of UBBL 2016 | -INA- | |
| 4 | Basement | 30 ACPH Exhaust fan provided | | i MR | |
| | | 12 APCH | Exhaust fan provided | - | |
| _ | Upper floors | 12 AFCH | Exhaust fail provided | MR | |
| 1 | Fire Extinguishers. | 12 Nos | Described | | |
| 1-5 | Total numbers | ABC / CO2 | Provided | MR | |
| | Types ISI Modeine | ISI marked | ABC & CO2 | MR | |
| | ISI Marking | 151 marked | Provided | MR | |
| 100 | 6 First Λid Hose Reels. • Total numbers on each floor. | | | 14 75 | |
| 1 | | One | Provided | MR | |
| | Length of hose-reel hose. | 30 mtr | Provided | MR | |



| | Nozzle Diameter | 5 mm | Provided | MR |
|-----|--|--------------------|--------------|-------|
| | Automatic fire detection & alarming system. | As per clause 7.31 | | |
| 7 | Type of detectors | Co Mo. Det. | Provided | MR |
| | Location of Main Panel | Required | Provided | MR |
| | Location of Repeater Panel | -NA- | -NA- | -NA- |
| 1 | Alternate source of power | Required | Provided | MR |
| | Hooter's location | Required | Provided | MR |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System | -NA- | NA | -NA- |
| 10 | Automatic Sprinkler System | | | |
| - | Basement | -NA- | NA | -NA- |
| - 1 | Upper floors. | -NA- | -NA- | -NA- |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA- |
| 11 | Internal Hydrants. | | | |
| | Size of Riser/Down-comer | -NA- | NA | -NA- |
| | Number of Hydrant per floor | -NA- | NA | -NA- |
| | Hose box. | -NA- | NA | -NA- |
| 12 | Yard Hydrants. | 1 | | |
| 12 | Total number of hydrants. | -NA- | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| | | 1 | | |
| 3 | Pumping arrangements. | - | | |
| _ i | Ground Level | -NA- | -NA- | -NA- |
| 9.5 | Discharge of main pump. | -NA- | -NA- | -NA- |
| | > Head of main pump. | -NA- | -NA- | -NA- |
| | Number of main pumps. | | -NA- | -NA- |
| | Jockey Pump output. | -NA- | -NA- | -NA- |
| | Jockey Pump head. | -NA- | -NA- | -NA- |
| i | > Standby Pump output. | -NA- | -NA- | -NA- |
| | Standby Pump head. | -NA- | | -NA- |
| | Auto Starting/Manual Stopping. | | -NA- | -NA- |
| - 1 | Pump house access. | -NA- | -NA- | -7474 |
| | Terrace Level | | 450 T P3 4 | -NA- |
| - 1 | Discharge of pump. | -NA- | 450 LPM | |
| | Head of pump. | -NA- | 25 m | -NA- |
| - 1 | Power supply. | -NA- | Provided | -NA- |
| | Auto starting of pump. | -NA- | Provided | -NA- |
| - | Captive water storage for fire fighting. | | - "HO N - 1" | |
| 14 | TI I would took conscitu | -NA- | NA | -NA- |
| 1 | Underground tank capacity. Draw-off connection. | -NA- | -NA- | -NA |
| | · · · · · · · · · · · I-let | -NA- | -NA- | -NA |
| 1 | Access to tank. | -NA- | -NA- | -NA |
| | | -NA- | 5,000 ltr | -NA |
| | Overhead tank capacity. | | Provided | MR |
| 15 | Exit Signage. | Required | 110.100 | |
| 16 | Provision of Lifts. | NANA- | | -NA- |
| 10 | Pressurization of lift shaft. | -NA- | -NA- | -NA- |
| 1 | Pressurization of lift lobby. | -NA- | -NA- | -NA- |
| 1 | Communication in lift car. | -NA- | -NA- | -NA- |
| | Fireman's switch. | -NA- | -NA- | -NA- |
| | | -NA- | Provided | MR |
| | Lift signage. | Required | Provided | - |
| 17 | Standby Power Supply | | -NA- | -NA- |
| 18 | Refuge Area | -NA- | | -NA- |
| | Total area Location | -NA- | -NA- | 1 |

ादा _{का} नत महोत्सव

| | T G . ID | | | |
|----|--|------|---|------|
| 19 | Fire Control Room. | -NA- | -NA- | -NA- |
| | Detector system panel. Flow switch panel. PA system panel. Battery backup. | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| 20 | Building floor plan. Special Fire Protection System for the Protection of special Risk, if any. | | 02 ABC type fire extinguishers provided near electrical panel | -NA- |

Note: - The occupancy per person at per floor is less than of 10 people hence the FCD requirements under clause 7.31 of UBBL is not applicable.

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/452 dated 30/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (South)

As approved, F.T. telter in portup for your Synature Pl

Director