0/20

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2024/SZ/ 1060

Dated: 24 10 2024

FIRE SAFETY CERTIFICATE

Certified that the Sunita Gyan Niketan School, Located at Village & Post Office Chhawla, New Delhi-110071, comprised of ground plus two upper floors, owned/occupied by Sunita Gyan Niketan School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2023/SZ/624 dated 12.09.2023 (for ground and first floor only). The school building was re- inspected by the officer concerned of this department on 16.10.2024 in the presence of Sh. Suresh Gaur (Manager) and found that School building have complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (ground plus two upper floors) is fit for occupancy class "Educational" w.e.f. 24 10 20 21 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 24 10 2024 at New Delhi by.

Director
Delhi Fire Service

Copy to: -

1 The Manager, Sunita Gyan Niketan School, Located at Village & Post Office Chhawla, New Delhi-110071.

2 Director of Education, GNCT of NCT of Delhi, Old Secretariat, New Delhi- 110054.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Sunita Gyan Niketan School, Village & Post Office Chhawla, New

Delhi-110071.

2. Building comprised of : Ground plus two upper floors

3. Type of Occupancy : Educational

4. Type of Case : New/addition/alteration

5. Details of Previous NOC : F.6/DFS/MS/School/2023/SZ/624 dated 12.09.2023 (for G+1 floor only)

6. Fire Safety directives letter No: N/A

7. Date of inspection : 16.10.2024

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Suresh Gaur (Manager)

10. Year of Construction : 2006

11. Applicant's letter No. : SGNS/2024 dated 30.09.2024

No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR		
	Access to building					
_	Road width	Accessible 06 m	10 m	M/R		
	Gate width	4.5 m	Direct accessible from road	MR, old case		
	Width of internal road	N/A	N/A	N/A		
2.	Number, Width, Type & Arrangement	of Exits				
	a. Number of staircases					
	Upper Floors	02 No.'s	03 No.'s	M/R		
	Basements	N/A	N/A	N/A		
	b. Width of staircases					
	Upper Floor	1.50 m each	1.50 m (2 nos.) & 0.75 m	MR		
	Basements	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircases to					
	terrace	Required	Provided	M/R		
12	e. Width of Corridor	1.50 m	2.05 m	M/R		
1	f. Door Size	1.0 m	Provided	M/R		
3.	Compartmentation		s The			
-	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A	N/A		
	• Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
-	Smoke Management System			oceanies:		
4.		N/A	N/A	N/A		
-	Basements Upper floors	Required	Natural ventilation provided	M/R		
5.		7489114				
	Total numbers	10 no's	Provided	M/R		
	Types	ABC/CO ₂ type	Provided	M/R		
	IS marking	ISI marked	Provided	M/R		
-	6. First-Aid Hose Reels					
-	• Total numbers on each floor	One	Provided	M/R		
	Length of hose reel hose	30 m	Provided	M/R		
# LU	Nozzle diameter	5 mm	Provided	M/R		

7.	Automatic fire detection and alarmin	g system			
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	 Alternate source of power 	N/A	N/A	N/A	
	 Hooters' Location 	N/A	N/A	N/A	
3.	MOEFA	N/A	N/A	N/A	
).	Public Address System	N/A	N/A	N/A	
0.	Automatic Sprinkler System				
	Basement	N/A	N/A	N/A	
	Ground Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
1.	Internal Hydrants				
	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
2.	Yard Hydrants				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
3.	Pumping Arrangements				
	Ground Level		222	77/1	
	 Discharge of main Pump 	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	 Standby Pump Head Auto Starting/Manual 	N/A	N/A	N/A	
	Stopping	N/A	N/A	N/A	
	> Pump House Access	N/A	N/A	N/A	
	Terrace level	460 1 70 6	Descrided	M/R	
	> Discharge of pump	450 LPM	Provided Provided	M/R	
	> Head of the pump	40 m	Provided	M/R	
	 Power Supply Auto Starting of pump 	Required Required	Provided	M/R	
14.					
	Captive Water Storage for fire fighting				
	Underground tank capacity	N/A	N/A	N/A	
	 Draw-off connection Fire service inlet 	N/A	N/A	N/A	
	> Access to tank	N/A	N/A	N/A N/A	
	Overhead Tank capacity	N/A	N/A Provided	M/R	
15.	Exit Signage.	10,000 ltrs	Provided Provided	M/R M/R	
16.	Provision of Lifts.	Required			
			No Lift		
	Pressurization of Lift Shaft Pressuriantian	N/A	N/A	N/A	
	Pressurization of Lift lobby Communication In 1999	N/A	N/A	N/A	
	Communication In lift Car Fireman's Grounding Switch	N/A	N/A	N/A	
A /	Lift Signage	N/A	N/A	N/A	
- 11		N/A	N/A	N/A	

1	Standby power supply	197		
8.	Refuge Area.	N/A	N/A	N/A
	> Total Area			+
	> Location	N/A	N/A	
9.	Fire Control Room	N/A	N/A	N/A N/A
	Detector System PanelFlow Switch Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for	N/A	N/A	N/A
	Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule, 2010.

Note: - Earlier this department issued FSC vide latter No. F.6/DFS/MS/School/2023/SZ/624 dated 12.09.2023 for ground and first floor only but now as per application latter of school management the school is running at ground plus two upper floors.

Signature of Inspecting Officer

Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (South West)

21/16/24

Director

ProffW

DO