

No.F.6/DFS/MS/School/2024/SZ/ 1067

Dated: 28/10/2024

## FIRE SAFETY CERTIFICATE

Certified that the Adarsh Public School located at Shyam Enclave, Deenpur, Najafgarh, New Delhi -110043, comprised of ground floor plus one upper floor, owned/occupied by the Adarsh Public School was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2021/SZ/878 dated 25.10.2021. The school was re-inspected by the officer concerned of this department on 21.10.2024 in the presence of Sh. Pradeep Dabas (Manager), and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 issued by the Director of Education and that the building/ premises (ground and first floor only) is fit for occupancy class "Educational Building" w.e.f. 28/10/2024 for a period of three years, subject to compliance of the conditions printed as under.

Issued on 28/10/2024 at New Delhi by.

## Copy to:-

- 1. The Manager, Adarsh Public School located at Shyam Enclave, Deenpur, Najafgarh, Delhi -110043.
- 2. Director of Education, GNCT of NCT of Delhi, Old Secretariat, New Delhi- 110054.

## Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.





## INSPECTION REPORT

1. Name & address of the building: Adarsh Public School, Shyam Enclave, Deenpur, Najafgarh, New Delhi-43

2. Building is comprised of : Ground plus one upper floor only.

3. Type of Occupancy : Educational 4. Type of Case : Renewal

5. Details of Previous NOC : F6/DFS/MS/School/2021/SZ/878 dated 25.10.2021

6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection : 21.10.2024

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Pradeep Dabas (Manager)

10. Year of Construction : Before 2010

11. Applicant's letter No. : Nil dated 08.10.2024

S. No.		mum Standards on fire ion and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMF		
	Access to	building	0.				
	• R	oad width	Accessible 06 m	06 m	M/R		
	• 0	ate width	N/A	N/A	N/A		
	• 1	Vidth of internal road	N/A	N/A	N/A		
2.	Number, Width, Type & Arrangement of Exits						
	a. Numb	er of staircases					
		Upper Floors	02 No.'s	02 No.'s	MR		
		Basements	N/A	N/A	N/A		
	The second second	of staircases	- William				
		Upper Floor	1.50 & .75 m	1.53 &1.0 m	MR		
		Basements	N/A	N/A	N/A		
	c Protec	tion of exits			1.000		
	200000000000000000000000000000000000000	Fire check door	N/A	N/A	N/A		
		Pressurization	N/A	N/A	N/A		
			IVA	N/A	IVA		
	d. No.	f continuous staircases to	37/4	NVA.	NUA		
	terra	The contract of the contract o	N/A	N/A	N/A		
		h of Corridor	1.5 m	2.36 m	N/A		
	f. Door	Size	Old Case		dents are less that sch class room)		
3.	Compar	tmentation		7			
		Fire check door	N/A	N/A	N/A		
		Sealing of electrical shafts	N/A	N/A	N/A		
		Fire Rating of shaft door	N/A	N/A	N/A		
		Water Curtain	N/A	N/A	N/A		
		Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System						
		Basement	N/A	N/A	N/A		
		Upper floors	Required	Natural ventilation	MR		
5.	Fire Ex	tinguishers	17				
m	•	Total numbers	08 no's	Provided	MR		
	(A)	Types	ABC type	Provided	MR		
	•	IS marking	ISI marked	Provided	MR		
6.	First-A	id Hose Reels		4 . 431			
-	1 12	Total numbers on each floor	N/A	02 no.'s/floor	MR		
1900		Length of hose reel hose	N/A	30 m	MR		
M	6 1000	Nozzle diameter	N/A	5 mm	MR		

Mil

		v					
7.	Automatic fire detection and alarming	14	N/A				
	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A				
8.	MOEFA	N/A	N/A	N/A			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements	32 3(0)	2000,000				
	Ground Level			7			
	> Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
	➤ Standby Pump Head —	N/A	N/A	N/A			
	> Auto Starting/Manual Stopping	N/A	N/A	N/A			
		50,55	-528.61	55,000,00			
	Pump House Access     Terrace level	N/A	N/A	N/A			
	Discharge of pump	N/A	220 1 70 / /02				
	> Head of the pump	N/A	220 LPM (02 no.s)	MR			
	> Power Supply	N/A	40 mtrs N/A	MR N/A			
	> Auto Starting of pump	N/A	N/A	N/A			
4.	Captive Water Storage for fire fighting						
		NI/A	340	1			
	Underground tank capacity     Draw-off connection	N/A N/A	N/A	N/A			
	> Fire service inlet	N/A N/A	N/A	N/A			
	> Access to tank	N/A N/A	N/A	N/A			
	Overhead Tank capacity	N/A N/A	N/A	N/A			
5.	Exit Signage.	N/A	4,000 ltrs N/A	MR N/A			
6.	Provision of Lifts.	, Shortened	*ARCHEVAL				
ice in			(No Lift)				
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car     Firement's Care III Care	N/A	N/A	N/A			
a	Fireman's Grounding Switch     Lift Signage	N/A	N/A	N/A			
V	Lift Signage	N/A	N/A	N/A			

Standby	power supply	N/A	N/A			
Refuge	Area		NA	N/A		
-						
\ \ \ \ \ \ \	Location	N/A	N/A	N/A		
- 4		N/A	N/A	N/A		
Fire Control Room						
•	Detector System Panel	N/A	21/4	T		
		2-22		N/A		
• P	PA System Panel Battery backup Building Floor Plans		N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
Special Protecti	Fire Protection System for on of special Risks, if any:	N/A	N/A	N/A		
	Fire Co	Location  Fire Control Room      Detector System Panel     Flow Switch Panel     PA System Panel     Battery backup	Refuge Area  > Total Area > Location N/A  Fire Control Room  • Detector System Panel N/A • Flow Switch Panel N/A • PA System Panel N/A • Battery backup N/A • Building Floor Plans N/A  Special Fire Protection System for N/A	N/A   N/A   N/A   N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the fire safety certificate issued vide letter No. F6/DFS/MS/School/2021/SZ/878 dated 25.10.2021, renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav Designation: - ADO (JKP)

D.O. (South West)

भ श्रीश्रम

hy/

nectary for 10 /2

M