GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/Hotel/2024/SZ/ 26

Dated: 29 10 2024

FIRE SAFETY CERTIFICATE

Certified that the Hotel Signature Grand, 1-A, Sub-District Centre, Hari Nagar, New Delhi-110064, comprised of two-tier Basements (storage), ground floor plus six upper floors with service floor owned/occupied by Hotel Signature Grand, was issued FSC by this department vide letter No. F.6/DFS/MS/Hotel/2021/SZ/31 dated 07.11.2021. The building was re-inspected by the officers concerned of this department on 18.10.2024 in presence of Sh. Popli and found that Hotel Signature Grand have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class "Residential" w.e.f 29 10 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 29 10 2024 at New Delhi.

Delhi Fire Service

Online application Id 2024093015060 dated 01.10.2024

Copy to: - Executive Engineer (Bldg.), MCD, West Zone, Dr. Sahib Singh Varma Nigam Bhawan, Second Floor, Shivaji Enclave, New Delhi-110027.: - for information regarding use of basement.

Conditions for validity of Fire Safety Certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency. Internal road around the building should be free from all types of obstacles.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. Basement shall be used as per the building bye laws.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Nyc

INSPECTION REPORT

1. Name & address of the building: Signature Grand, 1-A, Sub-District Centre, Hari Nagar, New

Delhi

Building is comprised of : Two tier basement (storage), Ground floor plus six upper floors

With service floor.

3. Type of Occupancy : Residential (Sub Division A-5)

4. Type of Case : Renewal

Details of Previous NOC : F.6/DFS/MS/Hotel/2021/SZ/31 dated 07.11.2021
 Fire Safety directives letter No : F6/DFS/MS/BP/Hotel/2008/780dated 17.03.2008

7. Date of inspection : 18.10.2024

8. Name of Inspecting Officers : R.K. Yadav, ADO (JKP)

9. Name and designation of officers

From the building side : Sh. Popli : Before 2010

11. Applicant's letter No. : Application Id No. 2024093015060 dated 01.10.2024

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR			
	Access to building						
	Road width Gate width Width of internal road	Accessible 06 m 06 m	12 m 4.2 & 4.2 m 5.5-5.7 m	MR MR, being old case being old case			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	Two	Two	MR			
	Basements	Two	Two	MR			
	b. Width of staircases	H-SNOId Case	1.48 & 1.25m	MR, being old case			
	Upper Floor Basements	1.5MQld Case	1.48 & 1.25 m	MR, being old case			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	Required	Provided	MR			
	d. No. of continuous staircases to						
	terrace	Required	One	MR			
	e. Width of Corridor	1.50m	1.75m	MR			
	f. Door Size	1.0 m	.87m	MR, being old case			
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	Required	Sealed	MR			
	Fire Rating of shaft door Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
		N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	Required	Provided	MR			
	Upper floors	Required	Provided	MR			
5.	Fire Extinguishers						
	Total numbers	06 no.'s at each floor	Provided	MR			
	Types	W/CO ₂ / CO ₂ /ABCtype	Provided	MR			
	IS marking	ISI marked	Provided	MR			

h

6.	First-Aid Hose Reels					
	Total numbers on each floor	01 no/floor	Provided	MR MR		
	Length of hose reel hose	30 m	Provided	2000		
	Nozzle diameter	5 mm	Provided	MR		
7.	Automatic fire detection and alarming system					
	 Type of detectors 	Required smoke &	Provided	MR		
	Location of Main Panel	heat Required	G. Floor	MR		
	 Location of Repeater Panel Alternate source of power 	N/A	N/A	N/A		
	Hooters' Location	Required	Provided	MR		
		Required	Provided	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
I.	Basement	Required	Provided	MR		
	Ground Floor	Required	Provided	MR		
	Sprinkler above false ceiling	Required	Provided	MR		
11.	Internal Hydrants	912/02/4 Par (10/9/54)	iou restroreamica 350	Onne de		
_						
	Size of riser/down-comer	150 MM 01 no.	Provided	MR		
	 Number of hydrants per floor Hose Box 	01 no.	Provided Provided	MR MR		
	(# 525%) (# 545%) 	O. no.	riovided	MIX		
2.	Yard Hydrants					
	 Total number of hydrants 	Four	Four	MR		
	Hose Box	Four	Four	MR		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	2280 LPM	Provided	MR		
	> Head of Main pump	80 m	Provided	MR		
	 Number of main pumps Jockey Pump out put 	One	Provided	MR		
	Jockey pump head	180 LPM	Provided	MR		
	> Standby Pump out put	40 m	Provided			
	Standby Pump Head Auto Starting/Manual	2280 LPM	Provided	MR		
	➤ Auto Starting/Manual Stopping	80 m	Provided	MR		
	Stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level		Trovided	MR		
	Discharge of pump Head of the pump	450 LPM	Provided	100		
	 ➤ Head of the pump ➤ Power Supply 	40 m	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR MR		
		Required	Provided	MR		
4.	Captive Water Storage for fire fighting	•		L. Carrie		
	Underground tank capacity	150000 ltrs.	Dec. 11 1			
	Draw-off connection	Required	Provided	MR		
	 Fire service inlet Access to tank 	Required	Provided	MR		
	Overhead Tank capacity	Required	Provided	MR		
	100 2 A St	20000 Ltrs	Provided	MR		
5.	Exit Signage.	Required	Provided	MR		
		daned	Provided	MR		

	Provision of Lift Shaft Required Provided						
17.	Provision Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	Required	Provided	MR			
		N/A	N/A	N/A			
		Required	Provided	MR			
		Required	Provided	MR			
		Required	Provided	MR			
	Standby power supply	Required	Provided	MR			
V	Refuge Area.						
18.	> Total Area > Location	N/A	N/A	N/A			
		Required	Provided	MR			
19.	Fire Control Room						
	Detector System Panel	Required	Provided				
	Flow Switch Panel	Required	Provided				
	PA System Panel Battery backup Building Floor Plans	Required	Provided				
		Required	Provided				
		N/A	N/A				
20.	Special Fire Protection System for Protection of special Risks, if any:	Required water spray in LPG bank Required Manual CO ₂ Flooding in LT & HT panel Provided		MR			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/Hotel/2021/SZ/31 dated 07.11.2021, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note: - As per undertaking given by the hotel management (placed at C- 214) that the both basement in the premises are using for storage purpose only and internal road around the building is free from all types of obstacles (photo enclosed with undertaking).

Signature of Inspecting Offi

Name: -R.K. Yadav Designation: - ADO (JKP)