Dated: 22/10/2024



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2024/ 425

FIRE SAFETY CERTIFICATE

Certified that the India Continental Guest House located at 9143 to 42/3, Multani Dhanda, Pahar Ganj, New Delhi comprised of Ground + Mezzanine + 04 Upper floors, ground floor (05 guest room & reception), mezzanine floor (02 guest room), 1st floor to 2nd floor (04 guest rooms at each floor) total 15 guest room upto 2nd floor only, 3rd & 4th floor not in use as per undertaking dated 09.11.2021 was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2021/508 dated 25/11/2021. Now, the premise was reinspected by the officer concerned of this department on 14/10/24 in the presence of Sh. Jitendra and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 ground floor (05 guest room & reception), mezzanine floor (02 guest room), 1st floor to 2nd floor (04 guest rooms at each floor) total 15 guest room up to 2nd floor only and valid up to the period of three year from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 22/10/2024 .. at New Delhi by.

(Appl Garg)
DIRECTOR
Delhi Fire Service

Copy to:-

- The Commissioner, North MCD, Civic Center, New Delhi: to ensure the occupancy as detailed above and deviation if any.
- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Ref. ID no. 2024100515257 dated 05.10.24.
- The Manager, India Continental Guest House at 9143-42/3, Multani Dhanda, Pahar Gani, New Delhi.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

VIV

INSPECTION REPORT

 Name & address of the building India Continental Guest House at 9143/3, Multani Dhanda, Pahar Ganj, New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. + Mezz. + 04 Upper floors (total 15 Guest rooms)

Ground floor (Reception + 05 guest rooms

Mezzanine floor (02 guest rooms),

1st floor to 2nd floor (04 guest rooms at each floor)
And 3rd floor (4 guest room) & 4th floor (01 guest room + 01 staff room) not in use as per undertaking

dated 09.11.21

3. Type of case:- Renewal

4. Details of previous FSC:- No.F6/DFS/MS/GH/NDZ/2021/508 dated

25/11/2021.

5. Fire safety directives No.6. Date of inspection:11/10

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)

Name & designation of officer From the building side:-

10. Applicant's letter No:-

Sh. Jitender, Manager

9. Year of construction:- 2001

id no. 2024100515257 dated 05.10.24. .

Old Case S.No. Minimum Standards on fire Requirement/ Provided at site Remarks Prevention and fire safety Existing fire safety MR/NMR arrangements U/R 33 1. Access to Building I) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3)Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases 1. Upper floors 01 No. 01 No. MR 2. Basements N/A N/A B. Width of staircase N/A 1. Upper floors 0.80 mtr. 1.25 to 1.30 mtr. MR 2. Basements N/A N/A C. Protection of exits N/A 1. Fire check door N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous N/A 01 01 staircase to terrace MR E. Width of corridor N/A N/A F. Door size N/A 1.0 mtr. 1.0 mtr. Compartmentation 3. MR 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A N/A 5) Fire Dampers N/A N/A 4. Smoke Management System N/A N/A 1) Basements N/A N/A Upper floors N/A 12 a/c per Natural/exhaust MR hour fan

N/25

5.	Fire Extinguishers			-
	1) Total numbers	12 Nos.	12 Nos.	MR
		ABC & CO2	ABC & CO2	MR
		Required	Provided	MR
6.	First-Aid Hose Reel		Tiorided	- MAX
		01	01	MR
		30 mtr.	30 mtr.	MR
		05 mm	05 mm	MR
7.	Automatic Fire Detection & A			
		Required	Provided /	MR
		Ground	Provided	MR
		N/A	N/A	N/A
		Required	Provided	MR
	5) Hooter's Location	Ground floor	Provided	MR
8.		N/A	Provided	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			2772
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor		1	NIA
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		13774	N/A
	1) Total number of hydrants	N/A	N/A	N/A N/A
	2) Hose box	N/A	N/A	IN/A
13.	Pumping Arrangement		37/4	N/A
A115 (T.1)	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	18/75
	pump	131/1	NI/A	N/A
	b) Head of main pump	N/A	N/A N/A	N/A
14.	c) Number of main pump	N/A	N/A N/A	N/A
	d) Jockey pump out put	N/A	N/A N/A	N/A
	e) Jockey pump head	N/A	N/A N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	IVA	2.110.63
	stopping			
	2) Terrace level	450 LPM	450 LPM	MR
	a) Discharge of pump		30 mtr.	/ MR
	b) Head of pump	30 mtr.	Provided	MR
	c) Power supply	Required Required	Provided	MR
	d) Auto starting of pump	Kequireu	1.1071404	30.33375
	Captive Water Storage for	Fire Fighting		N/A
			N/A	1 X 1 / A

	capacity			
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided /	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no F6/DFS/MS/GH/NDZ/2021/508 dated 25/11/2021, renewal under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is prepared and put up for kind perusal and signature.

Signature of the Inspecting Officer

Name: -Rayinder Singh Designation - ADO (CC)

DO(CD)

157x 124

Hitspros

2014

Director 10 n

Apple