0/61

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

No. F.6/DFS/MS/EH/2024/SZ/ 349

Dated: 24 10 2024

FIRE SAFETY CERTIFICATE

Certified that the Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double Storey, Tihar-II, Ashok Nagar, New Delhi-110018, comprised of ground floor plus three upper floors but the restaurant is running at ground and first floor only. The above restaurant was issued FSC vide Letter No. F6/DFS/MS/EH/2021/SZ/314 dated 29.10.2021, owned/ occupied by M/S Connaught Plaza Restaurant Pvt. Ltd. The Restaurant building was re-inspected by the officer concerned of this department on 16.10.2024 in the presence of Sh. Yogesh Kumar (Manager) and found that the M/S Connaught Plaza Restaurant Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (Ground and first floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 24 10 2024 at New Delhi.

Delhi Fire Service

Online application Id 2024092714896 dated 01.10.2024

Conditions for validity of Fire Safety Certificate: -

 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. Basement shall be used as per the building bye laws.

7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

 The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry. INSPECTION REPORT

1. Name & address of the building: Mc Donald's Family Restaurant, located at 30/4 & 30/4A, Double

Storey, Tihar-II, Ashok Nagar, New Delhi-110018.

2. Building is comprised of : G+3 (Restaurant is running at ground plus one upper floor only)

3. Type of Occupancy : Group D (Assembly)

4. Type of Case : Renewal

Details of Previous NOC : F6/DFS/MS/EH/2021/SZ/314 dated 29.10.2021

6. Fire Safety directives letter No : Nil.

7. Date of inspection : 21/10/2021

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Yogesh Kumar (Manager)

10. Year of Construction : Before 2010

11. Applicant's letter No. : ID No. 2024092714896 dated 01.10.2024

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks			
	Access to building						
	Road width Gate width Width of internal road	Accessible 4.5 m N/A	09 m Directly accessible from road N/A	M/R M/R N/A			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
		02 No.'s	Provided	M/R			
	Upper Floors	N/A	N/A	No Basemer			
	Basements						
	b. Width of staircases	1.5 m & 1.0 m	1.70 & 1.10 m	M/R			
	Upper Floor	N/A	N/A	No Basemen			
	Basements						
	Protection of exits	N/A	N/A	N/A			
	Fire check door	NIA	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	377		27/4			
	terrace	N/A	One	N/A			
	e. Width of Corridor	N/A	N/A	N/A			
	f. Door Size	02 m	02 m	M/R			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	No Basement			
	Upper floors	Required	Natural Ventilation	M/R			
5.	Fire Extinguishers						
	Total numbers	08 no's	Provided	M/R			
	Types	ABC/CO ₂	Provided	M/R			
	IS marking	ISI marked	ISI marked	M/R			

	NIT.					
6.	First-Aid Hose Reels (Restaurant at GF &					
	Total numbers on ground floor	One/Floor	Provided	M/R		
	Length of hose reel hose Nozzle diameter	30 mtrs	Provided	M/R		
		5 mm	Provided	M/R		
	Automatic fire detection and alarming system					
·						
	Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location	N/A N/A N/A N/A N/A	ASAT ATMOCRASTIANS	MR		
			Near reception N/A	MR		
			Provided	N/A MR		
			Near staircase	MR		
2	MOEFA	Required	Provided	M/R		
	Public Address System	N/A	N/A	N/A		
	Automatic Sprinkler System					
10.	Description of the second seco	N/A	N/A	N/A		
	Basement Ground Floor & FF in restaurant area	N/A	Provided	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
_			_			
1.	Internal Hydrants	1003414	Provided	M/R		
	Size of riser/down-comer	100 MM One	One	N/A		
	Number of hydrants Hose Box	One	- One	N/A		
	Hose Box	One -				
2.	Yard Hydrants					
-	Total number of hydrants	N/A	one	N/A		
	Hose Box	N/A	one	N/A		
13.	Pumping Arrangements					
	Ground Level		N/A	N/A		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A N/A	N/A		
	Number of main pumps	N/A		N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A			
	Auto Starting/Manual Stopping	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Pump House Access		Provided	M/R		
	Terrace level	450 LPM & 180 LPM	Provided	M/R		
	Discharge of pump	40 mtrs	Provided	M/R		
	Head of the pump	Required	Provided	M/R		
	Power Supply Auto Starting of pump	Required				
4.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	M/R		
	Overhead Tank capacity	10,000 ltrs	Provided			
		Required	Provided	M/R		

N	Provision of Lifts.	WILE		(No Lift)		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
7.	Standby power supply	Required	Provided	M/R		
8.	Refuge Area.					
	Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	- N/A	N/A		
	PA System Panel Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	M/R		
		N/A	N/A	N/A		
).	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/2021/SZ/314 dated 29.10.2021, renewal under Rule, 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name- R.K. Yadav

Designation- ADO(JKP)

DO (South West)

121/10mm

~

Director

Br/XX