c-108

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/GH/2024/SZ/439 No.

Dated: 2.5./.1.0./2024

FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style of M/S Pamposh Guest House located at M-83, M-Block Market, Greater Kailash-II, New Delhi 110048 Comprised of Basement Ground plus three upper floors (4th floor sealed with brick wall by the management) and the guest house running at 1st to 3rd floor with 08 guest rooms was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/2021/SZ/330 dated 24-08-2021. The premise was re-inspected by the officer concerned of this department on 19/10/2024 in the presence of Sh. Vishal Sokhal and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential & Lodging", Group-A" (Guest house running at 1st to 3rd floor with 08 guest rooms only) and Validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ___25 | 10. __/2024 at New Delhi by

Copy to: -

by to:
1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MHA Portal 2024092614856 dated 26.09.2024)

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any. 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





| | INSPECTION REPORT | | | | |
|---------|---|--|------------------|---------------|--|
| 1 | | | | | |
| | Name & Address of the Building | M/s Pamposh Guest House, M-83, M-Block | | | |
| 2 | Type of Occupancy | Transci, Orcale Kallach - II Now Patt 1100 - | | | |
| 3 | Building Comprised of | (Guest House) | | | |
| | S comprised of | Basement + G | round + 03 0 | 0000 (40 0 | |
| 4 | Type of Case | Basement + Ground + 03 upper floors. (4th floor Sealed with brick wall) | | | |
| 5 | Details of Previous NOC | Kenewal | | | |
| 6 | Fire Safety Directives Letter No | F6/DFS/MS/GH/2021/SZ/330 dated 24-08-2021 | | | |
| 7 | Date of Inspection | NII | | | |
| 8 | Name of the Inspecting Officers | 19-10-2024 | | | |
| 9 | Name & Designation of Officers | DO (South) & ADO (BCP) | | | |
| | from the building side | Mr. Vishal Sokhal | | | |
| 10 | Year of construction | | | | |
| 1.37128 | or consudence | 1998 Guest house running at 1st to 3rd floor total 08 | | | |
| 11 | Applicant letter No. | Guest R | Guest Rooms | | |
| S. No. | Minimum standards on Fire Prevention | MHA Portal 2024092614856 dated 26.09.2024 | | | |
| | and Fire Safety U/R 33 | Old NOC | Provided at Site | Remarks | |
| 1 | Access to Building. | Requirements | | MR/NMR | |
| | Road width | Required | 12 | 1 10 | |
| | Gate width | -NA- | 12 mtr -NA- | MR | |
| | Width of internal road | -NA- | -NA- | -NA- | |
| 2 | Number, width, type & arrangement of exits. | -14/12 | -NA- | -NA- | |
| 2 / | a) Number of Staircase | | | | |
| | ➤ Upper floors. | Required | One | MR | |
| | Basement floor. | -NA- | -NA- | -NA- | |
| | b) Width of Staircase | | | | |
| | ➤ Upper floors | Required | 1.02 mtr | MR (old case) | |
| | ➤ Basement floor | -NA- | -NA- | -NA- | |
| | c) Protection of exits | | | | |
| | Fire check door | -NA- | -NA- | -NA- | |
| | > Pressurization | -NA- | -NA- | -NA- | |
| | d) No. of continuous staircase to terrace | Required | One | MR | |
| | e) Width of corridor | -NA- | -NA- | -NA- | |
| - | 1) Door size | l m | 1 m (fire exit) | MR | |
| 3 | Compartmentation. | -NA- | NA. | T NA | |
| | • Fire check door. | -NA- | -NA- | -NA- | |
| | Sealing of electrical shafts. Fire retire of shaft door. | -NA- | -NA- | -NA- | |
| | Fire rating of shaft door. Water curtain | -NA- | -NA- | -NA- | |
| | Water curtain Fire dampers. | -NA- | -NA- | -NA- | |
| 4 | Smoke Management system. | As per clause 7.31 of UBBL 2016 | | | |
| - | Basement | -NA- | -NA- | -NA- | |
| | Upper floors | 12 APCH | Provided | MR | |
| 5 | Fire Extinguishers. | | | | |
| - 3 | Total numbers | Required | 10 Nos | MR | |
| | Types | ABC / CO2 | CO2 & ABC | MR | |
| | ISI Marking | ISI marked | Provided | MR | |
| 6 | Rirst Aid Hose Reels. | | | | |
| 0 | Total numbers on each floor. | 01 | Provided | MR | |
| | Length of hose-reel hose. | 30 m | Provided | MR | |
| | Dan Or most | 5 mm Provided MR | | 27222 | |

गजादीक अमृत महोत्सव

| | 19 | 33 | | |
|-----|---|----------------------|---------------|-------|
| , , | Automatic fire detection & alarming system. | As per clause 7.31 o | of UBBL 2016. | |
| | NIESTONIA SALONIES II SEEMA L | Co. Mo. Det. | Provided | MR |
| - 1 | Type of detectors Location of Main Panel | Required | Provided | MR |
| | Location of Repeater Panel | -NA- | -NA- | -NA- |
| | Alternate source of power | Required | Provided | MR |
| | Hooter's location | Required | Provided | MR |
| 1 | MOEFA | Required | Provided | MR |
| | Public Address System | ÑA | Provided | NA |
| 0 | Automatic Sprinkler System | | | T 314 |
| | Basement | -NA- | -NA- | -NA- |
| | Upper floors | -NA- | -NA- | -NA- |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA- |
| 1 | Internal Hydrants. | | | |
| | Size of Riser/Down-comer | -NA- | -NA- | -NA- |
| | Number of Hydrant per floor | -NA- | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| 2 | Yard Hydrants. | | | |
| * | Total number of hydrants. | -NA- | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| 3 | Pumping arrangements. | San Maria | | 1 111 |
| | Ground Level | | 1000 | |
| | Discharge of main pump. | -NA- | -NA- | -NA- |
| | Head of main pump. | -NA- | -NA- | -NA- |
| | Number of main pumps. | -NA- | -NA- | -NA- |
| | Jockey Pump output. | -NA- | -NA- | -NA- |
| | > Jockey Pump head. | -NA- | -NA- | -NA- |
| | Standby Pump output. Standby Pump head. | -NA- | -NA- | -NA- |
| | Auto Starting/Manual Stopping. | -NA- | -NA- | -NA- |
| | > Pump house access. | -NA- | -NA- | -NA- |
| 10 | Terrace Level | -NA- | -NA- | -NA- |
| | Discharge of pump. | | | 1 |
| | Head of pump. | 450 LPM | Provided | MR |
| | ➤ Power supply. | 35 m | Provided | MR |
| | Auto starting of pump. | Required | Provided | MR |
| 4 | Captive water storage for fire fighting. | Required | Provided | MR |
| | Underground tank capacity. | XIX I | | TARK |
| | Draw-off connection. | -NA- | NA | -NA- |
| | Fire Service Inlet. | -NA- | -NA- | -NA- |
| | Access to tank | -NA- | -NA- | -NA- |
| 5 | Overhead tank capacity. | 5,000 Ltrs | -NA- | -NA- |
| 6 | Exit Signage. | Required | Provided | MR |
| , | Provision of Lifts. | reclaired | Provided | MR |
| | Pressurization of lift shaft. | -NA- | | |
| | Pressurization of lift lobby. | -NA- | -NA- | -NA- |
| | Communication in lift cos | -NA- | -NA- | -NA- |
| | • Fireman's switch. | -NA- | -NA- | -NA- |
| 7 | Lift signage. Standby Pa | -NA- | -NA- | -NA- |
| 8 | Standby Power Supply Refuge Area | Required | -NA- | -NA- |
| | | required | Provided | MR |
| | Total area | -NA- | | WIK |
| | Location | 200133 | -NA- | -NA- |
| | | -NA- | -NA- | -NA |



| | | M34 | 341 | ्टा महोत्सव |
|----|--|------|--------|-------------|
| 19 | Fire Control Room. | TV 1 | | |
| | Detector system panel. Flow switch panel. | -NA- | -NANA- | |
| | | -NA- | -NA- | -NA- |
| | PA system panel. Battery backup. | -NA- | -NA- | -NA- |
| | Building floor plan. | -NA- | -NA- | -NA- |
| 20 | Special Fire Protection System for the P | -NA- | -NA- | -NA- |
| | Special Fire Protection System for the Protection of special Risk, if any. | | | |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 478 dated 12/08/2024 and 4th floor sealed with brick wall by the management (Affidavit Submitted)

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/330 dated 24-08-2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

O (South)

As approved, F.t. (teller is pritity