GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE** NEW DELHI-110 001

No.F.6/DFS/MS/School/2024/SZ/ 1075

Dated: 29 10 2024

FIRE SAFETY CERTIFICATE

Certified that the Sri Ram International School, Prem Nursery, Gopal Nagar, Najafgarh, New Delhi-110043, comprised of three blocks namely A- Block (G+3), B- Block (G+3) & C-Block (G+3 not in use), A-block having 11 rooms on GF, 11 rooms on FF, 09 rooms on SF & 10 rooms on TF (total 41 rooms) B-block is having 02 rooms and open auditorium on GF, 11 rooms on FF, 09 rooms on SF, 08 rooms on TF (01 room on library side hall not in use on FF, SF & TF). owned/occupied by Sri Ram International School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2021/SZ/477 dated 14.07.2021. The school building was re-inspected by the officer concerned of this department on 21.10.2024 in the presence of Smt. Jyoti (Admin. Officer) and found that Sri Ram International School have complied/deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Except Library side hall/area and Block-C) is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule-37 or sooner cancelled under Rule-40 and subject to compliance of the conditions under Rule-38 of the Delhi, Fire Service Rules, 2010 printed as below.

29 10 2024 at New Delhi by.

Delhi Fire Service

Copy to: -

1. The Principal, Sri Ram International School, Prem Nursery, Gopal Nagar, Najafgarh, New Delhi-110043.

Director of Education, GNCT of NCT of Delhi, Old Secretariat, New Delhi- 110054.

Conditions for the validity of fire safety certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning

6. The certificate may not be treated in any case for the regularization of the unauthorized

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Sri Ram International School, Prem Nursery, Gopal Nagar,

Najafgarh, New Delhi-110043

2. Type of Occupancy : Educational

3. Building Composition : having three blocks namely A- block (G+3), B- block (G+3) & C- block

(G+3 floors not in use)

4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2021/SZ/477 dated 14.07.2021

6. Fire Safety directives letter No : N/A
7. Date of inspection : 21.10.2024

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Smt. Jyoti Kohli (Admin. Officer)

10. Year of Construction : 2001 (Old Block) & 2016-17 (New Block & C-Block)

S. No.	140 (1444) (1470) (1470)	um Standards on fire tion and fire safety U/R 33	NBC/BBL Requirements	Provided at site	Remarks MR/NMR		
1.	Access to building						
	•	Road width Gate width	Accessible 06 m 4.5 m N/A	12 m 4.7 m N/A	MR MR N/A		
2.	Numb	Width of internal road	of Frite	N•.Ma.a./	*****		
6.	Number, Width, Type & Arrangement of Exits a. Number of staircases						
	a. Nui	Upper Floors	03 No's	03 No's & 01 ramp (01 staircase & 01 ramp are common with RCIT)	MR		
		Basements	N/A	N/A	N/A		
	b. Wic	Ith of staircases					
	•	Upper Floor	1.50 m in A- block & 1.50 & .75 m in B- block	1.30, 1.50 m & 1.38 m 1.60 m ramp. (1.38 m S.case & 1.60 m ramp are common with RCIT)	MR		
		Basements	N/A	N/A	N/A		
	c. Pro	tection of exits					
	•	Fire check door	N/A	N/A	N/A		
	•	Pressurization	N/A	N/A	N/A		
		. of continuous staircases to terrace	Required	Provided	MR		
		dth of Corridor or Size	1.50 m	1.35/2.80 m in A- blk & 2.60 m in B- Blk	MR, being		
			1.0 m 1.20 m in B-blk	.90 to 1.0 m in A- blk & 1.20 m in B- blk	MR, being old case		
3.	Comp	artmentation					
	•	Fire check door	N/A	N/A	N/A		
	•	Sealing of electrical shafts	N/A	N/A	N/A		
		Fire Rating of shaft door Water Curtain	N/A	N/A	N/A		
		Fire Dampers	N/A	N/A	54708.76		
	· · · · · ·	The Dampers	N/A	N/A	N/A		
4.	Smoke Management System N/A N/A N/A						
	•	Basements	N/A	N/A	N/A		
	•	Upper floors	Required	Natural ventilation	MR		
5.	Fire E	xtinguishers					
	•	Total numbers	24 no.'s	Provided	1 100		
		Types	ABC/CO ₂ type	The second secon	MR		
		IS marking	ISI marked	Provided ISI marked	MR		
. ,	First-A	Aid Hose Reels	151 market	131 marked	MR		
7		Total numbers on each floor	02 == 1-				
		Length of hose reel hose	02 no.'s	Provided	MR		
		Nozzle diameter	30 mtrs	Provided	MR		
0			5 mm	Provided	MR		

m	20

7.	Automatic fire detection and alarmin	J		1 1
	and alarmin	g system		
	 Type of detectors 	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A		N/A
	Alternate source of power Hooters' Location	N/A	N/A N/A	N/A
	1 Hooters Location	N/A	N/A N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		100	N/A
	Basement	N/A	N/A	
	Ground Floor	N/A	N/A N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants		N/A	N/A
	Size of riser/down-comer	100 MM	100 104	1 10
	Number of hydrants per floor	Two	100 MM	MR
	Hose Box	Two	Two Two	MR
12.	Yard Hydrants	1110	1 WO	MR
	Total number of hydrants	N/A	N/A	N/A
1700	Hose Box	N/A	N/A	N/A N/A
13.	Pumping Arrangements		I.V.G	IN/A
	Ground Level			
	Discharge of main Pump	N/A	N/A	NUA
	> Head of Main pump	N/A	SHOUND THE	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	➤ Jockey pump head	8840382	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/Manual	N/A	N/A	N/A
	Stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			AWATA
	Discharge of pump	450 LPM	450 LPM	MR
	➤ Head of the pump	40 mtrs	40 mtrs	MR
	> Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
4.	Captive Water Storage for fire fighting	at .		
	Underground tank capacity	N/A	N/A	21/4
	➤ Draw-off connection	N/A	N/A N/A	N/A
	Fire service inlet	N/A	Provided	N/A
	Access to tank	N/A	N/A	MR
	Overhead Tank capacity	10000 ltrs		MR
5.	Exit Signage.	Required	10000 ltrs Provided	MR MR
6.	Provision of Lifts.			ASSAULTED TO SECONDARIO
			No Lift	
	Pressurization of Lift Shaft Pressurization of Lift Johby	N/A	N/A	N/A
	Pressurization of Lift lobby Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	
'. :	Standby power supply	N/A	N/A	N/A
100	11455		17/17	N/A

18.	> Total Area	N/A	N/A	N/A	
1	> Location	N/A	N/A	N/A	
19. Fire	Fire Control Room				
	Detector System Panel Flow Switch Panel PA System Panel	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
	Battery backup		N/A	N/A	
	Building Floor Plans	N/A			
0.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection. The shortcomings issued by this department vide latter No. F.6/DFS/MS/School/2024/SZ/576 dated 03.09.2024 has been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/2021/SZ/477 dated 14.07.2021, renewal under rule, 37 of the Delhi Fire Service Rules, 2010 is recommended, if agreed.

Note: - As per the undertaking given by the Vice Principal (placed at C-58 & 59) that the channel gate and doors connected to building block will remain open during school hours and Block-C is not in use (photo enclosed at C- 60). There are less than 45 students in each class.

Signature of Inspecting Off Name: - R.K. Yadav

Designation: - ADO (JKP)