GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/Hospital/SZ/2024/ 650

Dated: -30/10/24

FIRE SAFETY CERTIFICATE

Certified that M/s Kids Clinic India Ltd. (Cloudnine Hospital) located at WZ-66, Khasra No. 26/4/2/2, Khata Khatoni No. 18/18, Manohar Nagar, Keshopur Colony, Outer Ring Road, Adjoining Vikaspuri, New Delhi- 110018, comprised of basement, stilt, upper ground plus three upper floors, owned/occupied by M/s Kids Clinic India Ltd., was inspected by the officers concerned of this department on 21.10.2024 in the presence Mr. Naveen (MD) and found that the management have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules 2010 and that the building/premises is fit for occupancy class Group-C Institutional Building (Basement, stilt, upper ground plus three upper floors) with effect from 3 0/10/24 for a period of 03 years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions printed below.

Issued on 30/10/24 at New Delhi by.

Director Delhi Fire Service

Copy to: -

- The Authorized Signatory, M/s Kids Clinic India Ltd. (Cloudnine Hospital) located at WZ-66, Khasra No. 26/4/2/2, Khata Khatoni No. 18/18, Manohar Nagar, Keshopur Colony, Outer Ring Road, Adjoining Vikaspuri, New Delhi- 110018.
- The MS, Nursing Homes, Directorate of Health Services, Govt. of NCT of Delhi, S-1, 3rd Floor, School Block, Shakarpur, Delhi-110092.
- 3. Executive Engineer (Bldg.), MCD, West Zone, Dr. Sahib Singh Varma Nigam Bhawan, Second Floor, Shivaji Enclave, New Delhi-110027 for information and to check the use of basement, whether it is permissible or not. If the use of the basement is not as per requirement of building sanctioning authority, the fire safety certificate shall stand cancelled and necessary action against may be taken.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. Basement shall be used as per the building bye laws.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

4

INSPECTION REPORT

1. Name & address of the building : Kids Clinic India Limited (Cloudnine Hospital), at WZ-66, Khasra

No. 26/4/2/2, Khata Khatoni No. 18/18, Manohar Nagar, Keshopur Colony, Outer Ring Road, adjoining Vikaspuri, New Delhi- 110018.

2. Building is comprised of : Basement (OPD, USG & Pharmacy), Stilt (Parking), Upper Ground floor

(Patient's Rooms), 1st floor (Patient's Rooms), 2nd floor (Patient's Rooms)

& 3rd floor (Ots, LDR, workstation & NICU...

3. Type of Occupancy : Institutional (Hospital Building)

4. Type of Case : New Case : New Case 5. Details of Previous NOC : N/A

6. Fire Safety directives letter No : F6/DFS/MS/ BP/2024/281 dated 05.09.2024

7. Date of inspection : 21.10.2024

8. Name of Inspecting Officer : Vedpal Chhikara, DO (SW) & R.K. Yadav, ADO (JKP)

9. Name and designation of officers

From the building side : Mr. Naveen (MD)

10. Year of Construction : 2023-24

11. Applicant's letter No. : Nil, dated Nil, Outdoor dairy No. 7765 dated 11.10.2024.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building					
X 64	Road width Gate width Width of internal road	06 m N/A N/A	35 m N/A N/A	M/R N/A N/A		
ARM ROS	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases • Upper Floors	02 nos.	02 no.'s	M/R		
	Basements Width of staircases	02 nos.	02 no.'s	M/R		
	Basements Protection of exits Fire check door	2 m & 1.5 m 2 m & 1.5 m	2.0 m each 2.0 m each	MR MR		
		Required N/A	Provided N/A	M/R N/A		
	d. No. of continuous staircases to terrace	02	02	M/R		
	e. Width of Corridor f. Door Size	2.40 m 2.0 m	2.40 m 2.0 m	MR MR		
3.	Compartmentation	-1111				
	Fire check door Sealing of electrical shafts	Required Required	Provided Sealed	M/R M/R		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain Fire Dampers	N/A N/A	N/A . N/A	N/A N/A		
4.	Smoke Management System					
	Basements	Required	Provided	M/R		
	Upper floors	Required	Natural Ventilation Provided	M/R		
5.	Fire Extinguishers					
	Total numbers Types	15 no.'s ABC/ CO ₂ type	Provided Provided	M/R M/R		
	IS marking	ISI marked	Provided	M/R		

4

Refu

, 1	Etunt Atd Have Doub	/U				
	First-Aid Hose Reels	00.11	ONCO NOTO 15			
do	Total numbers on each floor Length of hose reel hose	02 No.	Provided Provided	M/R		
	Nozzle diameter	30 m	Provided	M/R		
	Automatic fire detection and alarming system	5 mm	Provided	M/R		
	Type of detectors Location of Main Panel	Smoke/Heat	Provided	M/R		
	Location of Repeater Panel	N/A	Ground floor	M/R		
	Alternate source of power	N/A Populard	Ground floor	M/R		
	Hooters' Location	Required Required	Provided Provided	M/R		
8.	MOEFA	Required	Provided	M/R M/R		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System		N/A	IVA		
	Basement	Required	D. C. I			
	Upper Floor	Required	Provided	M/R		
	Sprinkler above false ceiling	N/A	Provided	M/R		
11.	Internal Hydrants	IVA	N/A	N/A		
	- Anti-Anti-Anti-Anti-Anti-Anti-Anti-Anti-	1/	- Long by			
	Size of riser/down-comer Number of hydronto non Standard	100 mm	Provided	M/R		
	Number of hydrants per floor Hose Box	one	Provided	M/R		
12.	Yard Hydrants	one	Provided	M/R		
	Total number of hydrants	N/4	ter and to be	4		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements	N/A	N/A	N/A		
		Fr. 1				
	Ground Level Discharge of main Pump			_		
	> Head of Main pump > Head of Main pump > Number of main pumps > Jockey Pump out put > Jockey pump head > Standby Pump out put > Standby Pump Head > Auto Starting/Manual Stopping	2280 LPM	2280 LPM	MR		
		80 m	80 m	MR		
		one	one	MR		
		180 LPM	180 LPM	MR		
		60 m	60 m	MR		
		2280 LPM	2280 LPM	MR		
		80 m	80 m	MR		
	40 00	Required	Not Provided	MR		
	> Pump House Access	Required	Not Provided	MR		
	Terrace level	8.9.5		774		
	Discharge of pump	450 LPM	450 LPM	M/R		
	 ➢ Head of the pump ➢ Power Supply 	40 m	40 m	M/R		
	> Auto Starting of pump	Required Required	Provided	M/R		
14.	Captive Water Storage for fire fighting	Required	Provided	M/R		
	Underground tank capacity	1.50.000	pult proces	1 0		
	> Draw-off connection	1,50,000 ltrs.	1,50,000 ltrs	M/R		
15.	> Fire service inlet	Required	Provided	M/R		
	> Access to tank	Required	Provided	M/R		
	Overhead Tank capacity	Required	Provided	M/R		
		10,000 Ltrs	10,000 Ltrs	M/F		
0.25%	Exit Signage.	Required	Provided	M/F		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	Required	Provided	1 4-72		
	Pressurization of Lift lobby	Required	Provided	M/1		
	Communication In lift Car	Required	Provided	M/		
1	Fireman's Grounding Switch	Required	A A A A A A A A A A A A A A A A A A A	- M/		
V	Lift Signage	Required	Provided	M/		
	ATTIVITY OF A STATE OF THE STAT	Required	Provided	M/		

17.	Standby power supply	Required	Provided	M/R	
18.	pefuge Area.		1		
10.	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19.	Fire Control Room				
-	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	• PA System Panel	N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
•	Special Fire Protection System for Protection of special Risks, if any:	Required	Provided	MR	

The fire protection systems provided in the building were test checked randomly and found functional at the time of inspection. All shortcoming issued by this department vide letter No. F.6/DFS/MS/Hospital/2024/SZ/2261 dated 09.10.2024 has been rectified. The dimension of underground water storage tank given in undertaking submitted by management of hospital (placed at C-25). Terrace floor plan submitted by management of hospital (placed at C-17) and ventilation system, fire pumps and basement photograph also attached with undertaking.

Note: - The hospital building is comprised of basement (OPD, USG & Pharmacy), Stilt (Parking), upper ground floor (Patient Rooms), first floor (Patient rooms), second floor (Patient rooms) and third floor (OT's, LDR, Workstation & NICU).

In view of the above substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rule 35 of Delhi Fire Service Act – 2007 & Rules 2010, if agreed.

Accordingly, DFA is put up for approval & signature please.

Signature of Inspecting Officer

Name: - R.K. Yadav

Designation: - ADO (JKP)

Signature of Inspecting Officer

Name: - Vedpal Chhikara Designation:- DO (SW)

CFO (South Zone)

Denester My 11/2

ADO (TIMOR)

Dollsw

Sh 8/16