



No.F6/DFS/MS/School/SZ/2024/ 1084

Dated: 01/11/2024

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Gagan Public School located at 308/13, Lakhpat Colony, Part-I, Meethapur Extension, Badarpur, New Delhi, was granted Fire Safety Certificate by this department vide letter no.- F6/DFS/MS/School/2018/SZ/802 dated 27.04.2018 for school running at Ground + 01 upper floor only in a building comprised of Ground + 03 upper floors. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 16.10.2024 in the presence of Mr. Naresh Kumar Sharma (Principal) and it was observed that the school is now running on **Ground + 03 upper floors**. The school building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises/building (**Ground + 03 upper floors**) is fit for occupancy of Group B "Educational Building" (School) with effect from ....01/11/2024... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on....01/11/2024...at New Delhi by

(Atul Garg)  
Director  
Delhi Fire Service

**Copy to:-**

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
2. The Principal, M/s Gagan Public School located at 308/13, Lakhpat Colony, Part-I, Meethapur Extension, Badarpur, New Delhi.

**Conditions for the validity of Fire Safety Certificate**

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

## INSPECTION REPORT

1	Name and address of the building:	M/s Gagan Public School located at 308/13, Lakhpat Colony Part-I, Meethapur Extension, Badarpur, New Delhi.		
2	Building is comprised of	Ground + 03 upper floors		
3	Type of occupancy	Educational Building (Group -B)		
4	Type of case:	Renewal		
5	Details of previous FSC:	F6/DFS/MS/School/2018/SZ/802 dated 27.04.2018 for Ground + 01 upper floor only in a building comprised of Ground + 03 upper floors		
6	Fire safety directives no.:	UBBL & NBC -2016		
7	Date of inspection:	16.10.2024		
8	Name of the inspecting officer:	ADO Rajesh Kumar Shukla (M. Road)		
9	Name and designation of the officer from the building side:	Mr. Naresh Kumar Sharma (Principal)		
10	Year of construction:	G + 2-1998 & 3 <sup>rd</sup> floor- 2013		
11	Reference letter no.:	Email dated 07.05.2024		
S.No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	Requirement as per UBBL/NBC	Provide at site	Remarks MR/NMR
1	<b>Access to Building</b>			
A	Road width	6.0 mtrs	6.0 mtrs	MR
B	Gate width	NA	NA	NA
C	Width of internal roads	NA	NA	NA
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
A	<b>No. of staircase:</b>			
a)	Upper floor	2 nos.	3 nos. (3 <sup>rd</sup> staircase from 2 <sup>nd</sup> floor to 3 <sup>rd</sup> floor only)	MR
b)	Basements	NA	NA	NA
B	<b>Width of the staircase:</b>			
a)	Upper floor	* 1.50 m & 0.75 m (As per order no. F6/DFS/MS/2011/293 dated 15.02.2011)	- Main staircase-1.66 mtrs to 1.75 mtrs - Alternate staircase-1.20 mtrs - Additional staircase- 1.0 mtrs (from 2 <sup>nd</sup> floor to 3 <sup>rd</sup> floor only)	MR
b)	Basements	NA	NA	NA
C	<b>Protection of exits</b>			
a)	Fire check door	NA	NA	NA
b)	Pressurization	NA	NA	NA
D	No. of continuous staircase to terrace:	02 nos.	Provided	MR
F	Width of the corridor	1.5 mtrs	Provided	MR
E	Door size	1.0 mtrs (for class room)	Provided	MR
3	<b>Compartmentation:</b>			
A	Fire check doors	NA	NA	NA
B	Sealing of electrical shafts	NA	NA	NA
C	Fire rating of shaft doors	NA	NA	NA
D	Water curtain	NA	NA	NA
E	Fire dampers	NA	NA	NA
4	<b>Smoke Management System:</b>			
A	Upper floors	NA	NA	NA
B	Basements	NA	NA	NA
5	<b>Fire Extinguishers</b>			
A	Total numbers	12 nos.	16 nos.	MR
B	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
C	ISI marking	Required	Provided	MR

<b>6</b>	<b>First Aid Hose reel</b>				
	<b>A</b>	Total no. at each floor	01 no.	01 no.	MR
	<b>B</b>	Length of hose reel	30 m	30 m	MR
	<b>C</b>	Nozzle diameter	5 mm	5 mm	MR
<b>7</b>	<b>Automatic Fire Detection and Alarm System (ADAS)</b>				
	<b>A</b>	Type of detectors	NA	NA	NA
	<b>B</b>	Location of main panel	NA	NA	NA
	<b>C</b>	Location of repeater panel	NA	NA	NA
	<b>D</b>	Alternate power source	NA	NA	NA
	<b>E</b>	Hooter's location	NA	NA	NA
<b>8</b>	<b>MOEFA</b>		NA	NA	NA
<b>9</b>	<b>Public Address System</b>		NA	NA	NA
<b>10</b>	<b>Automatic Sprinkler System</b>				
	<b>A</b>	Basement	NA	NA	NA
	<b>B</b>	Upper floor	NA	NA	NA
	<b>C</b>	Sprinklers above false ceiling	NA	NA	NA
<b>11</b>	<b>Internal Hydrants</b>				
	<b>A</b>	Size of the riser/down comer	NA	NA	NA
	<b>B</b>	No. of hydrants per floor	NA	NA	NA
	<b>C</b>	Hose box	NA	NA	NA
<b>12</b>	<b>Yard Hydrants</b>				
	<b>A</b>	Total no. of hydrants	NA	NA	NA
	<b>B</b>	Hose box	NA	NA	NA
<b>13</b>	<b>Pumping Arrangements</b>				
	<b>A</b>	Ground Level			
		a) Discharge of main pump	NA	NA	NA
		b) Head of main pump	NA	NA	NA
		c) Number of main pump	NA	NA	NA
		d) Discharge of jockey pump	NA	NA	NA
		e) Head of jockey pump	NA	NA	NA
		f) Discharge of standby pump	NA	NA	NA
		g) Head of standby pump	NA	NA	NA
		h) Auto starting/ manual stopping	NA	NA	NA
	<b>B</b>	Terrace Level			
		a) Discharge of terrace pump	450 LPM	Provided	MR
		b) Head of terrace pump	40 m	Provided	MR
		c) Alternate power supply	Required	Provided	MR
		d) Auto starting of pump	Required	Provided	MR
<b>14</b>	<b>Captive Water Storage for Fire Fighting</b>				
	<b>A</b>	Underground tank capacity	NA	NA	NA
	<b>B</b>	Draw off connection	NA	NA	NA
	<b>C</b>	Fire service inlet	NA	NA	NA
	<b>E</b>	Access to tank	NA	NA	NA
	<b>D</b>	Overhead tank capacity	10,000 ltrs	Provided	MR
<b>15</b>	<b>Exit Signage</b>		Required	Provided	MR
<b>16</b>	<b>Provision of lift</b>				
	<b>A</b>	Pressurization of lift shaft	NA	NA	NA
	<b>B</b>	Pressurization of lift lobby	NA	NA	NA
	<b>C</b>	Communication in lift car	NA	NA	NA
	<b>D</b>	Fireman switch	NA	NA	NA
	<b>E</b>	Lift signage	NA	NA	NA
<b>17</b>	<b>Standby Power Supply</b>		NA	NA	NA

2/19

<b>18 Refuge Area</b>				
A	location	NA	NA	NA
B	Total area	NA	NA	NA
<b>19 Fire Control Room</b>				
A	Fire detection system panel	NA	NA	NA
B	Flow switch panel	NA	NA	NA
C	P A system panel	NA	NA	NA
D	Battery backup	NA	NA	NA
E	Building floor plan	NA	NA	NA
<b>20 Special Fire Protection for special risk if any</b>				NA

**Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).**

**\*Note:** The staircase width requirements are as per order no. F6/DFS/MS/2011/293 dated 15.02.2011(copy of order placed at C/26).

The school was granted Fire Safety Certificate by this department for Ground + 01 upper floor only vide letter no. F6/DFS/MS/School/2018/SZ/802 dated 27.04.2018. The 2<sup>nd</sup> & 3<sup>rd</sup> floor had been sealed earlier and an affidavit stating sealing of 2<sup>nd</sup> & 3<sup>rd</sup> floor is already placed on file at C/14 & C/15 respectively. However now the 2<sup>nd</sup> & 3<sup>rd</sup> floor was found unsealed and school is running on Ground+ 03 upper floors. The required fire safety arrangements were found provided in building during at the time of inspection dated 16.10.2024.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above & in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter F6/DFS/MS/School/2018/SZ/802 dated 27.04.2018 is recommended to be renewed for Ground + 03 upper floors under Rule 35 of the Delhi Fire Service Rules 2010.

Accordingly, FSC is put up for approval and signatures please.

*[Signature]*  
Signature of the Inspecting Officer  
Name Rajesh Kumar Shukla  
Designation ADO (M. Road)

*Pl. ask for plans.*

DO (SD) *[Signature]* 16/10/24

*[Signature]*  
ADO (MS) Many cases covered under Rule 27 of DFS Rules without Plans from local act including fresh case 2010 have been directly done / cleared, with due approval from the competent authority. Its requested that the file may plz be sent to the competent authority for concurrence so that there is uniformity in departmental policies.

*[Signature]*  
29/10/24

DO (SD) *[Signature]* 28/10/24

CFO (MS) *[Signature]*  
I agree with this as per the plan we are in care of school.  
DU (SD)

Director *[Signature]*