## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/BNQT./2024/SZ/ 47

Dated:05/11/24

## FIRE SAFETY CERTIFICATE

Certified that the Seven Pearls Banquet Hall running at upper ground & first floor only in a building emprised of basement (sealed), stilt (office), upper ground & first floor (banquet hall) second & third floor not in use, located at RZ-7, Old Pankha Road, Opp. A1-Block, Janak Puri, New Delhi-110059, owned/occupied by the Seven Pearls hotel (P) Ltd, was issued Fire Safety Certificate vide Letter No. F.6/DFS/MS/2021/SZ/462 dated 24.09.2021. The Banquet Hall building was re-inspected by the officer concerned of this department on 25.10.2024 in the presence of Sh. Jitin Pal Singh (Director) and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (upper ground and first floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. 05/11/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on \_05 11 2024 at New Delhi.

Dolhi Fire Service

Online application Id 2024100415223 dated 07.10.2024.

Copy to: - Executive Engineer (Bldg.), MCD, West Zone, Dr. Sahib Singh Varma Nigam Bhawan, Second Floor, Shivaji Enclave, New Delhi-110027: -for information as basement found sealed by banquet hall management.

## Conditions for validity of Fire Safety Certificate:-

 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

Use of the basement will only be allowed after permission from MCD, w.r.t. use and prior approval of this department from fire safety point of view.

The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

 The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/23

INSPECTION REPORT

1. Name & address of the building: Seven Pearls hotel (P) Ltd., RZ-7, Old Pankha Road, Opp. A1-Block,

Janak Puri, New Delhi-110059.

2. Building is comprised of : Basement (sealed), stilt (office), upper ground & first floor (Banquet

Hall), second & third floor (not in use).

3. Type of Occupancy : Assembly D-3
4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/2021/SZ/462 dated 24.09.2021

6. Fire Safety directives letter No : N.A
7. Date of inspection : 25.10.2024
8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Jitin Pal Singh (Director)

10. Year of Construction : Before 2010

11 Applicant's letter No : Online application Id 2024100415223 dated 07.10.2024

S. No.		um Standards on fire prevention and ety U/R 33	UBBL/NBC requirements	Provided at site	Remarks MR/NMR			
1.	Access to building							
	•	Road width Gate width Width of internal road	Accessible (09 m.) 4.5 m N/A	Provided 05 m N/A	MR MR N/A			
2.	Numbe	er, Width, Type & Arrangement of Exi	s Table		r Åggradelid			
X 51	a. Num	ber of staircases						
	•	Upper Floors	02 No's	03 No's	MR			
	•	Basements	N/A	N/A	N/A			
	b. Wid	th of staircases	1.50 m	1.50, 1.50 & 1.30	m MR			
	•	Upper Floor	N/A	N/A	N/A			
	F1.	Basements	IN/A	IVA	1974			
	c. Prote	ection of exits Fire check door	NIA	N/A	N/A			
		Pressurization	N/A		N/A N/A			
		1 CSSUITZACION	N/A	N/A	N/A			
	d. No.	of continuous staircases to						
	terra		Required	Provided	MR			
		th of Corridor	1.50 m	Opening in hal	II MR			
	f. Doo	Size	1.50 m	1.50 m (02 no.'	s) MR			
١.	Compa	rtmentation						
	•	Fire check door	N/A	N/A	N/A			
		Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
,	Smoke	Management System		F 14	1.			
_	•	Basements	N/A	N/A	N/A			
	•	Upper floors	Required	Natural ventilation provided	on MR			
k <sub>N</sub>	Fire Ex	linguishers						
	•	Total numbers on each floor	03 no.'s	Provided	MR			
		Types	ABC/CO <sub>2</sub> /W CO <sub>2</sub> type	Provided	MR			
		IS marking	ISI marked	ISI marked	MR			

6

U	29
0.	0

	First-Aid Hose Reels		/1				
	m ( I have such Open	01 no.	Provided	MR			
	Total numbers on each floor	30 m	Provided	MR			
	Length of hose reel hose     Nozzle diameter	05 mm	Provided	MR			
	Automatic fire detection and alarming system	1 1/4					
	Type of detectors	Smoke/Heat	Provided	MR			
	Type of detectors     Location of Main Panel	At entrance	Provided	MR			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	In hall	Provided	MR			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System		27/4				
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	100 mm	Provided	MR			
	Number of hydrants per floor	One	Provided	MR			
	Hose Box	One	Provided	MR			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
-	Ground Level						
	Discharge of main Pump	2280 LPM	Provided	MR			
	> Head of Main pump	60 m	Provided	MR			
	> Number of main pumps	One	Provided	MR			
	<ul> <li>Jockey Pump out put</li> <li>Jockey pump head</li> </ul>	180 LPM	Provided	MR			
	Standby Pump out put (with DG set	60 m	Provided	MR			
	supply)	2280 LPM	Provided	MR			
	> Standby Pump Head	60 m	Provided	MR			
	> Auto Starting/Manual Stopping	Required	Provided	MR			
	> Pump House Access	Required	Provided	MR			
	Terrace level	•	77.0				
	<ul> <li>Discharge of pump</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Head of the pump</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Power Supply</li> </ul>	N/A	N/A	N/A			
	> Auto Starting of pump	N/A	N/A	N/A			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	50,000 ltrs	Provided	MR			
	> Draw-off connection	Required	Provided				
	> Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	Overhead Tank capacity	10000 ltrs		MR			
15.	Exit Signage.	Required	Provided	MR			
13.		Keamrea	Provided	MR			

0						
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
8	Pressurization of Lift lobby	N/A	N/A	N/A		
	<ul> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> </ul>	N/A	N/A	N/A		
		Required	Provided	MR		
	Lift Signage	N/A	N/A	N/A		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.					
	➤ Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	FA System Panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20.	Special Rire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/2021/SZ/462 dated 24.09.2021, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended

Note: - As per the undertaking given by the Director of the banquet hall (placed at C-82) the management has sealed the basement hall with brick wall & second & third floor not use for any work

Signature of Inspecting Officer

Name: - R.K. Yadav Designation: - ADO (JKP)

D.O. (South West)

dag 16/M-

Deneta MIIIX

Appri= e/L