Dated: 13 /// /2024

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No.F6/DFS/MS/SZ/2024/EH 374

FIRE SAFETY CERTIFICATE

Certified that the Ms Evva Restaurant (Evva A unit of salt & straw LLP.) Located at Plot No. 30B, 3rd floor, Old Rajinder Nagar, Pusa Road, New Delhi, in a building comprised of Basement, Stilt, Ground + 3 Upper Floors was issued FSC vide letter No. F6/DFS/MS/EH/SZ/2021/280 dated 08/10/2021. The premises was inspected by the officers concerned of this department on 06/11/2024 in the presence of Sh. Mayank (Owner) and found that premises have deem complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly" Group D (At Third Floor) with effect from 13 11 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...13.].11].2024... at New Delhi by.

Delhi Fire Service

Copy to:

- 1. The Joint Commissioner Police, Licensing, 1st Floor, PS, Defence Colony, N Delhi.
- 2. The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi.
- The Manager, Ms Evva Restaurant (Evva A unit of salt & straw LLP.) Located at Plot No. 30B, 3rd floor, Old Rajinder Nagar, Pusa Road, New Delhi.

Condition for the validity of fire safety certificate:-

- The stairs/ passage shall be kept clear from any obstruction & free from lock & key, as seen during the inspection otherwise the FSC shall be null & void
- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

11/15

INSPECTION REPORT

 Name & address of the building: Ms Evva Restaurant (A unit of salt & straw LLP.) Located at Plot No. 30B, 3rd floor, Old Rajinder Nagar, Pusa Road, New Delhi.

2. Type of Occupancy : (Assembly)

3. Type of Case : Renewal (Running at 3rd floor in a building comprised of Basement, Stilt + Ground + 3 Upper Floors)

4. Details of previous NOC: F6/DFS/MS/EH/SZ/2021/280 dated 08/10/2021

5. Fire Safety directives L. No.: NBC/UBBL

6. Date of inspection

: 06/11/2024

7. Name of the Inspecting Officer; DO/SW & ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Mayank (Owner)

9. Year of Construction

: 2021

10. Applicant's Letter No: 2024102215979, dated-22/10/2024

-11	Minimum standards on fire prevention and fire safety U/R 33	As per N/4, N/	5 & N/6	Provide site	d at	10000000	marks R/NMR			
.	Access of building	574):								
	Road width	Required	Provid	Provided N		MR				
	Gate width	4.5m	Provi	ded	MR	1				
	Width of internal road	NA	NA		NA					
2.	Number, width, Type & Arrangements of exits									
1	a. Number of staircases									
	Upper floors	2 Nos.	1.5	Provided			MR			
	Basements	NA	NA				NA			
	b. Width of staircases		* =							
1	Upper floors	1.5m each	to reason the	1-41-2-17-1-41-04 -00-1-41		MR				
- 1	Basements Protection of exits	NA	NA NA		N/		A			
1	Fire check door									
- 1	Pressurization	Required			ided		MR			
	d. No of continuous staircase t	o NA					NA			
	terrace	02	02	02		MR				
	e. Width Of Corridor	NA	NA	NA			NA			
	f. Door Size	2x1.5m	Provided	ided Old case MR		Being Old case				
3.	Compartmentation	_								
	Fire check door	Required	Pro	Provided			MR			
	Sealing of electrical shafts	Required	Pro	Provided			MR			
	Fire Rating of shaft door	NA	377922	NA			NA			
	Water Curtain	NA	NA			NA	L			
	Fire Dampers	NA	NA	Y		NA	V			
4.	Smoke managements System									
	Basements	NA		NA			NA			
1	Upper floors	12 a/c per	12 a/c per hour		Provided					



	Fire Ex	tinguishers		D	and .	Pro	vided		N	1R	
	•	Total numbers		Requ	CO2		vided		N	1R	
- 1	•	Types		ISI m		- 515-5	vided		M	1R	
	•	IS marking		151 m	arkeu			nt	ΤT		
5.	First -	Aid Hose Reel Provided &	& mai	ntain	ea by b	Dr	ovided		M	IR	
	•	Total numbers on each flo	or	01 No			ovided		М	IR	
	•	Length of hose reel hose	- 1	30 m			ovided		M	IR	
	•	Nozzle diameter		5 mm		FF	JVIded				
7.	Autom	atic fire detection and alarr	ning s	ystem		D	Islad		MF	2	
	•	Type of detectors		quired		-	rided Provided		1,,,,	MR	
	•	Location of Main Panel	_		estaurar		Provided		NA	E.M. C.	
	•	Location of Repeater	NA			NA			The state of		
		Panel Alternate source of power	Re	quired		Prov			MR		
		Hooters' Location			estaurar	it area	Provide	d	MR	t _	
8.	MOEF			quired		Prov	ided		MR		
9.	4004.5-000	Address System	_	quired		Prov	ided		MR	1	
10.	Autom	atic Sprinkler System Not				ded					
	·	Basements		NA			NA	NA			
		Upper Floor		NA			Provided		N.	A	
	•	Sprinkler above false ceili	ng	NA			NA	NA			
11.	Interna	7.7		ntained by building management							
H1050	•	Size of riser/down- comer		100			Provided		MR	3	
		Number of hydrants per fl	oor	01			Provided	_	MR	ŭ ŭ	
	•	Hose Box		01			Provided		MR	2 2	
12.	Yard I	lydrants									
	•	Total number of hydrants	N/	A		NA		NA			
	•	Hose Box	NA			NA		NA			
13.	Pumping Arrangements: Provided & maintained by building management										
	•	Ground Level									
	•	Discharge of main pump		lpm	Provide						MR
	4	Head of main pump	60 m	1	Provide	-4-					MR
	A	Number of main pumps Jockey pump out put			Provide						MR
		No. 1 I		180 lpm Provi		T 5.10					MR MR
	>	Standby Pump out put			Provided Provided					MR	
	>	Standby Pump Head	60 m) lpm	Provide	c//.					MR
	>	Auto Staring/Manual		Required Provide						MR	
		Stopping	_	uired	Provide					MF	
		Pump House Access Terrace level	100000		10550000	K-7		-	_	1 -0-1	
	4	Discharge of pump	4501	pm	F	rovide	d		1	MR	
	4	Head of the pump	45 n		F	rovide	d		1	MR	
	4	Power supply	Req	uired	F	Provide	d		1	MR	
	8	Auto starting of pump	Req	uired	F	rovide	d		1	MR	
					-		3				
							*1				

	Under ground tank capacity	100000 ltr		Old case	MR Being O	ding management Being Old Case		
11	> Fire service inlet > Access to tank Overhead Tank capacity	NA Required Required		NA	NA	NA		
				Provided	MR	MR MR		
				Provided	MR			
				Provided	7.5 Main 1977			
5	Exit Signage	Required		Provided	MR			
	Provision of Lifts							
0.	> Pressurization of Lift Shaft	NA		NA		NA		
	 Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch Lift Signage 	NA		NA		NA		
1		Required		Provided		MR		
1		Required		Provided		MR		
		Required		Provided	MR			
17.	Standby power supply	Required		Provided	MR			
18.	Refuge Area		*	271	NA			
	> Total area	NA		NA	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	NA		
	> Location	NA		NA	1000	IVA		
19.	Fire control room			NA	NA			
0.00	 Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	NA		NA NA	NA			
		NA		NA NA	NA	12/43		
		NA		NA	NA			
		NA		NA NA	NA			
		NA	1574	NA	1.1.	NA		
20	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA			A. Aller		

The fire protection systems provided in the building were test checked and found

functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No F6/DFS/MS/EH/SZ/2021/280 dated 08/10/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended

Note:- Seating arrangement was seen in basement however Restaurants manager informed that the basement has been closed by order of MCD.

Signature of the Inspecting Officer

Name: Sh. Vedpal Designation: DO/SW Signature of the Inspecting Office

Name: Udai Vir Singh Designation: ADO/DWK

Afreeday All 20m

Ru

V plands 9