GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/2024/ 368

Dated: 08/.11../2024

FIRE SAFETY CERTIFICATE

Certified that the My Bar (A Unit of Guru Tegh Bahadur Enterprises), located at 5136, Pahar Ganj, New Delhi comprises of basement (storage) and ground (restaurant). The FSC was earlier granted for said premises by this department vide letter No.F6/DFS/MS/EH/2020/NDZ/172 dated 07/12/20 for the name & style My Restaurant. Now, the premises was re-inspected by the officer concerned of this department on 25/10/24 in the presence of Mr. Ayush and found that the said restaurant premises has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant is fit for occupancy class Assembly occupancy (Group D)Restaurant running at Ground floor only with effect from. 08. 11. 2.29. for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued08/11/2024 ... at New Delhi by.

shi Fire Servi

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi: to kindly ensure the occupancy as detailed above and deviation if any.

2. The Joint Commissioner of Police (Licensing)1st Floor, Police Station Defence Colony, New

Delhi.Online ID no. 2024101515705 dated 15/10/24.

3. The Manager My Bar (A Unit of Guru Tegh Bahadur Enterprises)" located at 5136, Pahar Ganj, New Delhi.

Conditions for the validity of fire safety certificate

This FSC is valid for restaurant at ground floor only.

2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

3. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any

7. Presently Basement is being used for storage purpose.

8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in The means of escape such as exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation

10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

N)29

			INSPECT	TION	REPORT
MI	0_	- 11 - 0.1	 	Victory of the	

1. Name & address of the building My Bar (A Unit of Guru Tegh Bahadur

Enterprises), 5136, Main Bazar, Pahar Ganj,

New Delhi.

2. Type of occupancy:- Assembly Building Group-D

Basement + Ground floor

Basement (storage) & Ground floor Restaurant

3. Type of case:- Renewal (restaurant)

4. Details of previous FSC:- F6/DFS/MS/EH/2020/NDZ/172 dated 07/I2/20.

5. Fire safety directives No.-6. Date of inspection:-25/10/24

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)

Sh. Rajinder Atwal (DO/CD)

 Name & designation of officer From the building side:-

Mr. Ayush

9. Year of construction:-

10. Applicant's letter No:- Online ID No. 2024101515705 dated 15/10/24.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	N/A	N/A	N/A			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arr						
	A. Number of staircases						
	1. Upper floors	N/A	N/A	N/A Gr. Floor			
	2. Basements	01	01	MR			
	B. Width of staircase						
	1. Upper floors	N/A	N/A	N/A			
	2. Basements	1 mtr.	1.10 mtr.	MR(old Case)			
	C. Protection of exits	HI 17F					
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase to terrace	N/A	N/A	N/A			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	02 exit	Provided	MR			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	1) Basements	12 ACPH	Exhaust fan	MR			
	2) Upper floors	12 a/c per hour	N/A	N/A			
5.	Fire Extinguishers						

N	30
L	0

		10		
	1) Total numbers	06 Nos.	06 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1) Total number of each	01	01	MR
	floor			1 (1)
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst	em	137/4
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	K-0.001/90		
	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	provided	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			
)	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	100000000	D. C. A. C. C. A. C.	1) 13-2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	: 4	-Ci	
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	Ground level	N/A	N/A	N/A
	a) Discharge of main	450 LPM	450 LPM	MR
	pump			
	b) Head of main pump	40 mtr.	40 mtr.	MR
	c) Number of main pump	01	01	MR
	d) Jockey pump out put	250 LPM	250 LPM	MR
	 e) Jockey pump head 	40 mtr.	40 mtr.	MR
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	Required	Provided	MR
	stopping	A 1727-172 11 (1745-1747)	- SOUTH AND THE STATE OF THE ST	
4.)	Terrace level			
	 a) Discharge of pump 	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	
				N/A
	d) Auto starting of pump	N/A	N/A	NT/A
14.	Captive Water Storage for F	N/A ire Fighting	N/A	N/A
14.	Captive Water Storage for F 1) Under ground tank	N/A ire Fighting 5,000 ltr.		
14.	Captive Water Storage for F	ire Fighting	5,000 ltr.	N/A MR

	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	N/A	N/A	N/A
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
ZÌ.	a) Pressurization of lift shaft	N/A	N/A	N/A
i A	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
1 74	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	NA		

The fire protection systems provided in the restaurant building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. No.F6/DFS/MS/EH/2020/NDZ/172 dated 07/12/20, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name:- Sh. Rajinder Atwal Designation:- DO (CD)

Name: Sh. Ravinder Singh Designation: ADO (CC)

Phice (was

30/10/2

Directo My

Apple