GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2024/SZ/ 11/5

Dated: 19 11 2024

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043 comprised of ground plus one upper floor only, owned/occupied by Govt. Girls Sr. Sec. School was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2021/SZ/1089 dated 29.12.2021 (for three blocks). The school building was re- inspected by the officer concerned of this department on 12.11.2024 in the presence of Ms. Sunita Yadav (Principal) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (ground and first floor only) is fit for occupancy class "Educational Building" w.e.f. 19 11 2024 for a period of three years, subject to compliance of the conditions printed as under.

Issued on 19 11 2024 at New Delhi.

Director Delhi Fire Service

Copy to: -

1. The Principal, Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

Conditions for the validity of fire safety certificate: -

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building :

Govt. Girls Sr. Sec. School, Paprawat, New Delhi-110043.

2. Building Clomprised of

Ground plus one upper floor.

3. Type of Occupancy 4. Type of Case

Educational

Renewal

5. Details of Previous NOC

: F.6/DFS/MS/School/2021/SZ/1089 dated 29.12.2021 (for three blocks)

6. Fire Safety directives letter No

: F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection

: 11.12,2024

8. Name of Inspecting Officer

: A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

Ms. Sunita Yadav, Principal

10. Year of Construction

: Before 2010

11. Applicant's letter No.

: GGSSS/PAP/2024/360 dated 18.10.2024

S. No.	Minim preven	um Standards on fire tion and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR				
i Çr	A STATE OF THE PARTY OF THE PAR								
	•	Road width	Accessible 06 m	07 m	MR				
		Gate width Width of internal road	4.5 m N/A	Directly accessible from road N/A	M/R N/A				
2.	Numbe	r, Width, Type & Arrangeme		mont.					
	a. Num	ber of staircases		Contract of the second					
		Upper Floors	02 no.'s	03 no.'s	MR				
		Basements	N/A	N/A	N/A				
	b. Widi	th of staircases	0						
	-	Upper Floor Basements	1.50 & .75 m	1.40, 1.40 & 1.62 m	MR				
		Daschielles	N/A	N/A	N/A				
	- 22								
	c. Prote	ection of exits	N/A	N/A	N/A				
		Fire check door Pressurization	N/A	N/A	N/A				
	d No	of continuous staircases to	Required	two	MR				
	terra	Control of the Contro	1.50 m	1.52 m	MR				
A	A CONTRACTOR	th of Corridor	1.0 m	1.0 m (double door)	MR, old cas				
	f. Doo	Size		The im (deducte decry	iviit, old cas				
	Compa	rtmentation							
	1	Fire check door	N/A	N/A	N/A				
1		Sealing of electrical shafts	N/A	N/A	N/A				
- 9	•	Fire Rating of shaft door Water Curtain	N/A	N/A	N/A				
		Fire Dampers	N/A	N/A	N/A				
	10.00		N/A	N/A	N/A				
	Smoke Management System								
	•	Basements	N/A	N/A	N/A				
	•	Upper floors	Required	Natural Ventilation provided	MR				
	Fire Extinguishers								
12.0		Total numbers Types 1\$ marking	10 No's ABC/CO ₂ type	Provided	MR				
				Provided	MR				
	. 57/		ISI marked	ISI marked	MR /				

	N	U	-		
6.	First-Aid Hose Reels				
	Total numbers on each floor	N/A	N/A	N/A	
	Length of hose reel hose	N/A	N/A	N/A	
	Nozzle diameter	N/A	N/A	N/A	
7.	Automatic fire detection and alarming system		Ujeki j	H	
	Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
	MOEFA	N/A	N/A	N/A	
).	Public Address System	N/A	Provided	N/A	
0.	Automatic Sprinkler System	1.500			
	Basement	N/A	N/A	N/A	
	Ground Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
1.	Internal Hydrants				
	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
2.	Yard Hydrants				
	Total number of hydrants	N/A	N/A	N/A	
000	Hose Box	N/A	N/A	N/A	
3.	Pumping Arrangements				
	Ground Level			Y	
	 Discharge of main Pump 	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A	
	> Pump House Access	N/A	N/A	N/A	
	Terrace level		107.11		
	Discharge of pump	N/A	N/A	N/A	
,	> Head of the pump	N/A	N/A	N/A	
	➤ Power Supply	N/A	N/A	N/A	
	> Auto Starting of pump	N/A	N/A	N/A	
	9				
4.	Captive Water Storage for fire fighting			N/A	
4.	Underground tank capacity	N/A	N/A	IN/A	
4.	Underground tank capacity	N/A N/A	N/A N/A	N/A	
4.	 Underground tank capacity Draw-off connection Fire service inlet 		N/A	N/A	
4.	Underground tank capacity Draw-off connection Fire service inlet Access to tank	N/A		N/A N/A	
4.	 Underground tank capacity Draw-off connection Fire service inlet 	N/A N/A	N/A N/A	N/A	

_	Provision of Lifts.	(No Lift)					
6.	Pressurization of Lift Shaft	N/A	N/A	N/A			
	• Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch Lift Signage Standby power supply	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
3.	Refuge Area.	NIA	N/A	N/A			
_	> Total Area	N/A N/A	N/A	N/A			
	> Location						
	Fire Control Room	N/A	N/A	N/A			
9.	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel Battery backup	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Dlone.	N/A	N/A	N/A			
	Building Floor Plans Special Fire Protection System for Protection of special Risks, if any:						

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2021/SZ/1089 dated 29.12.2021 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended. No.

vide latter department this by issued **FSC** Earlier F.6/DF\$/MS/School/2021/SZ/1089 dated 29.12.2021, for three blocks namely, Main block comprised of ground plus one upper floor, 2nd & 3rd block each comprised of ground floor only. Now school comprised of ground plus one upper floor only. 2nd & 3rd block both are demolished by school management.

Signature of In

Name: - R.K!Yadav Designation: - ADO (JKP)

DO (South West)