GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No F 6 / DFS / MS / 2024/ School/WZ/ 1135

FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Vidyalaya (ID- 1310247) located at Auchandi, Delhi-110039 comprised of Ground plus three upper floors was issued FSC by this department vide letter No F6/DFS/MS/2021/School/WZ/935 dated 12.11.2021. The premises was re-inspected by the officer concerned of this department on 16.11.2024 in the presence of Sh. Rajesh Kumar Soni (Estate Manager), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with fire prevention & fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy Group B Educational with effect from 25./11/2024... for a period of three years, in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on .. 25.11. 2024. at New Delhi, by

Director Ph/011-23414000

Copy to: -

- The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054.
- The Principal, Sarvodaya Vidyalaya (ID- 1310247) located at Auchandi, Delhi-110039.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Sarvodaya Vidyalaya (ID-1310247) located at Auchandi, Delhi- 110039.

2. Type of Occupancy Educational

 Building Comprised of
 Type of Case Ground plus Three Upper Floors.

Renewal

5. Details of Previous NOC : F6/DFS/MS/2021/School/WZ/935 Dated- 12/11/2021

6. Fire Safety directives letter No : NBC Part IV 7. Date of inspection 16/11/2024

8. Name of Inspecting Officer R.K.Sinha, ADO (BW)

9. Name and designation of officers

From the building side : Sh. Rajesh Kumar Soni (Estate Manager)

10. Year of Construction : 2021

Io.	Minimum Standards on fire	E Mail id dated 05/11/ NBC Part IV	Provided at site	Remarks MR/NMR		
	prevention and fire safety U/R 33	Requirement				
1	Access to building	6 m	Provided	MR		
	Road width		Provided	MR		
	Gate width	4.5 m	NA NA	NA		
	Width of internal road	NA NA	IVA			
2.	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		02	MR		
	 Upper Floors 	02	NA NA	NA		
	Basements	NA	INA			
	b. Width of staircases			MR		
	Upper Floor	1.50 m each	1.70 m each	NA		
	Basements	NA	NA	IVI		
				NA		
	c. Protection of exits	NA	NA			
	Fire check door	NA	NA	NA		
	 Pressurization 			100		
	d. No. of continuous staircases to	02	Provided	MR		
	tегтасе	1.50 m	Provided	MR		
	e. Width of Corridor	1.20 m	Provided	MR		
	f. Door Size					
3.	Compartmentation		NA	NA		
J	- I I dene	NA	and Asset	NA		
		NA	NA	70183		
	Sealing of electrical shafts	NA	NA	NA		
	 Fire Rating of shaft door 	NA	NA	NA		
	Water Curtain	NA NA	NA	NA		
	• Fire Dampers					
4.	Smoke Management System	NA	NA	NA		
J. C.	Basements	[20150]	Naturally Ventilated	MR		
	Upper floors	Required	Naturally Ventuated			
_	Fire Extinguishers		46 Nos.	MR		
5.	Total numbers	15 Nos.	Provided	MR		
	• Types	ABC/ Co2 Type		MR		
	IS marking	Required	Provided	им.		
,	First Aid Hose Reels		Provided	MR		
6	Total numbers on each floor	02	The state of the s	MR		
	Length of hose reel hose	30 m	Provided	1000		
	Nozzle diameter	5 mm	Provided	MR		
7.	die Gradutection and alarming system					
	C 1-t-store	NA	NA	NA		
	CMain Danel	NA	NA	NA		
	Location of Main Failer A control of Papeater Papeater	NA	NA	NA		
	Location of Repeater Panel Alternate source of power	NA NA	NA	NA		
		NA NA		NA		
	 Hooters' Location 	, , ,	NA	NA		

N	,	10

		0.	10	Ball Ball
		N	-10	Specie A
_	MOFFA	NA	NA	NA
8.	MOEFA Public Address System	NA	NA	NA
9. 10.	Automatic Sprinkler System			
10.	Basement	NA	NA NA	NA NA
	Ground Floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	NA	NA
12.	Yard Hydrants			
12.	Total number of hydrants	· NA	NA	NA
	Hose Box	NA	NA	NA
13.	Pumping Arrangements			
	Ground Level			
	➤ Discharge of main Pump	NA	NA	NA
	➤ Head of Main pump	NA	NA	NA
		274	NIA	NA '
	> Number of main pumps	NA	NA NA	
	> Jockey Pump out put	NA	NA NA	NA NA
	> Jockey pump head	NA NA	NA NA	NA NA
	> Standby Pump out put	NA	NA NA	NA NA
	> Standby Pump Head	NA	NA NA	NA NA
	> Auto Starting/Manual	NA	NA	INA
	Stopping > Pump House Access	NA	NA	NA
	Terrace level			
	> Discharge of pump	450 lpm	Provided	MR
		40 m	Provided	MR
	> Head of the pump			
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	 Underground tank capacity 	NA	NA	NA
	> Draw-off connection	NA	NA NA	NA
	➤ Fire service inlet	NA	NA	NA
Ì	> Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000 ltrs	Provided	MR
5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.			
	P. C. STARLE T.	NIA T	NA	NA
L	Pressurization of Lift Shaft	NA		- O.F.
-	Pressurization of Lift lobby	NA NA	NA NA	NA
L	Communication In lift Car	NA	NA	NA
	 Fireman's Grounding Switch 	NA	NA	NA
	Lift Signage	NA	NA	NA
7.	Standby power supply	NA	NA	NA
8.	Refuge Area.			
	> Total Area	NA	NA	NA
	> Location	NA	NA NA	NA NA
).	Fire Control Room			
	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA NA
		NA	NA	
	PA System Panel	1123	INA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The school management had rectified the shortcomings issued vide letter no. F6/DFS/MS/School/2024/WZ/636 dated 19/09/2024.

Note:- Electric meter and electrical panel are at safer location.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, it is recommended to renew the fire safety certificate issued vide letter no. F6/DFS/MS/2021/School/WZ/935 dated 12/11/2021 under Rule 37 of the Delhi Fire Service Rules, 2010.

> Signature of Inspe Name: Rajeev Kumar Sinha Designation: ADO/B.W.