

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/GH/2024/SZ/ 466

Dated: 26/11./2024

## FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style of M/s Beyond Inn located at A-91, A- Block, Malviya Nagar, New Delhi 110017 comprised of Basement & ground (other property) 1st and 3rd floor, guest house, (Total 11 Guest room) was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2021/SZ/460 dated 30/09/2021. The premise was re-inspected by the officer concerned of this department on 23/11/2024 in the presence of Mr. Shankar Singh (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (Guest House with 11 Guest rooms) and validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on \_26 11 /2024 at New Delhi by

(ATU DIRECTOR DELHI FIRE SERVICE Alu

Copy to: -1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. Portal ID No 2024102816247 dated 28/10/2024)

## Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting 3.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

p/25



1	INSPECT	INSPECTION REPORT					
2	Name & Address of the Building	M/s Beyond Hotels located at A-91, Malviya Nagar, New Delhi 110017					
3	ype of Occurancy	Residential, "Group-A" (Guest House)					
3	Building Comprised of	Basement & Ground (other property) 1st to 3rd upper					
4		floors					
5	Type of Case	Renewal					
6	Details of Previous NOC	F6/DFS/MS/GH/2021/SZ/460 dated 30/09/2021					
7	Fire Safety Directives Letter No	Nil 23/11/2024					
8	Date of Inspection						
9	Name of the Inspecting Officers	ADO (BCP)					
	Ivaine & Designation of Officers	Mr. Shankar Singh (Manager)					
10	from the building side						
11	1 car of construction	2010 Total 11 Guest room					
S. No.	Applicant letter No.	MHA Portal ID 2024102816247 dated 28/10/2024					
5.T. (#1.M.)	standards on Fire Prevention	Old NOC Provided at Site Remarks					
1	and Fire Safety U/R 33	requirements MR/NM					
	Access to Building.		06-4-	MD			
	Road width	Required	06 mtr -NA-	MR -NA-			
	Gate width	-NA-		-NA-			
2	Width of internal road	-NA-	-NA-	-NA-			
~	Number, width, type & arrangement of exits.  a) Number of Staircase						
	- Control Cust	01.2/	01 Nos	MR			
	> Upper floors.	01 Nos	Para de la companya d	787.000			
	➤ Basement floor.	-NA-	-NA-	-NA-			
	b) Width of Staircase			1			
	> Upper floors	1.25 mtr	1.25 mtr	MR			
	➢ Basement floor	-NA-	-NA-	-NA-			
	c) Protection of exits						
	➢ Fire check door	-NA-	-NA-	-NA-			
	> Pressurization	-NA-	-NA-	-NA-			
	d) No. of continuous staircase to terrace	Required	01 Provided	MR			
	e) Width of corridor	-NA-	-NA-	-NA-			
	n Door size	1m	1.10 mtr (Final Exit)	MR			
3	Compartmentation.	Terrough, and the	THE PERSON NAMED IN				
<u> </u>	Fire check door.	-NA-	-NA-	-NA-			
	Sealing of electrical shafts.	-NA-	-NA-	-NA-			
	Fire rating of shaft door.	-NA-	-NA-	-NA-			
	Water curtain	NΛ	NA	NΛ			
		-NA-	-NA-	-NA-			
	• Fire dampers	As per clause 7.31 of UBBL 2016					
	Smoke Management system.	-NA-	-NA-	-NA-			
	Basement						
	Upper floors	12 ACPH	Exhaust fan provided	MR			
	Fire Extinguishers.						
-	Total numbers	08 Nos	Provided	MR			
	• Types	ABC / CO2	ABC & CO2	MR			
	ISI Marking	ISI marked	Provided	MR			
	First Aid Hose Reels.		AND DESCRIPTION OF THE PARTY.				
5	Total numbers on each floor.	One	Provided	MR			
			14.45.532.541.540.				
	<ul> <li>Length of hose-reel hose.</li> </ul>	30 mtr	Provided	MR			
	Nozzle Diameter	5 mm	Provided	MR			
1	Automatic fire detection & alarming system. As per clause 7.31 of UBBL 2016						

1



Type of detectors	Co. Mo. Det.	Provided	MR
T and the CA ( at a Date )		Pigvided	
<ul> <li>Location of Main Panel</li> </ul>	Required -NA-	-NA-	-NA
<ul> <li>Location of Repeater Panel</li> </ul>		Provided	MR
			MR
			-NA
			-NA
	-NA-	IVA	
		NIA	-NA
Also distributions			-NA
7.7	A 100 M 100		-NA
	-NA-	-INA-	-11/2
			-NA
<ul> <li>Size of Riser/Down-comer</li> </ul>			-NA-
<ul> <li>Number of Hydrant per floor</li> </ul>			-NA-
Hose box.	-NA-	-NA-	-NA
Yard Hydrants.	ALL THE STATE OF T		D. D. T.A.
<ul> <li>Total number of hydrants.</li> </ul>			-NA-
Hose box.	-NA-	-NA-	-NA-
Pumping arrangements.			
Ground Level		1,500	
Discharge of main pump.	-NA-		-NA-
		77.72.75.55	-NA-
Standby Pump nead.			-NA-
			-NA-
· · · · · · · · · · · · · · · · · · ·	-NA-	-NA-	-NA-
	520 E	12/2/27	-
			-NA-
			-NA-
			-NA-
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-NA-	-NA-	-NA-
	NY A	274	374
			-NA-
I I			-NA-
			aNAa
		15/4/0	-NA-
			-NA-
Exit Signage.	Required	Provided	MR
		120	
- San Market Company of the Company	The state of the s		-NA-
			-NA-
			-NA-
			-NA-
	-NA-	-NA-	-NA-
	NA	Provided	NA
	20000000	-NA-	-NA-
<ul> <li>Location</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>Alternate source of power</li> <li>Hooter's location</li> <li>MOEFA</li> <li>Public Address System</li> <li>Automatic Sprinkler System</li> <li>Basement</li> <li>Upper floors.</li> <li>Sprinkler above faise ceiling</li> <li>Internal Hydrants.</li> <li>Size of Riser/Down-comer</li> <li>Number of Hydrant per floor</li> <li>Hose box.</li> <li>Yard Hydrants.</li> <li>Total number of hydrants.</li> <li>Hose box.</li> <li>Pumping arrangements.</li> <li>Ground Level</li> <li>Discharge of main pump.</li> <li>Number of main pumps.</li> <li>Jockey Pump output.</li> <li>Jockey Pump output.</li> <li>Standby Pump output.</li> <li>Standby Pump head.</li> <li>Auto Starting/Manual Stopping.</li> <li>Pump house access.</li> <li>Terrace Level</li> <li>Discharge of pump.</li> <li>Head of pump.</li> <li>Power supply.</li> <li>Auto starting of pump.</li> <li>Captive water storage for fire fighting.</li> <li>Underground tank capacity.</li> <li>Draw-off connection.</li> <li>Fire Service Inlet.</li> <li>Access to tank.</li> <li>Overhead tank capacity.</li> <li>Exit Signage.</li> <li>Provision of Lifts.</li> <li>Pressurization of lift shaft.</li> </ul>	• Alternate source of power • Hooter's location  MOEFA Public Address System  • Basement • Upper floors. • Sprinkler System • NA- NA- NA-  NA-  **NA-  **NA-  **ONA-  **Internal Hydrants. • Size of Riser/Down-comer • Number of Hydrant per floor • Hose box.  **Total number of hydrants. • Total number of hydrants. • Total number of hydrants. • Total number of main pump.  **NA-  **Pumping arrangements.  • Ground Level  **Discharge of main pump.  **NA-  **NA	Alternate source of power   Required   Provided





555	Detector system panel.     Flow switch panel.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.     Building floor plan	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

Note: As per MHA Portal Application details per floor occupancy is below mentioned.

1. First Floor: 04 Rooms

8 Nos of Bed

Second Floor: 04 Rooms

6 Nos of Bed

3. Third Floor: 03 Rooms

4 Nos of Bed

The occupancy per person at per floor is less than of 10 people hence the FCD requirements under clause 7.31 of UBBL is not applicable.

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 659 dated 25/10/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/460 dated 30/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Raiesh Kumar Design: ADO (BCP)