GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 Dated: 28/11 /2024

No.F.6/DFS/MS/2024/SZ/

FIRE SAFETY CERTIFICATE

Certified that the M/s Sarvodaya Co-Operative Housing Society Ltd, Community Centre located at B-74A, Sarvodaya Enclave, New Delhi - 110017 Comprised of Basement, Ground plus One Upper Floor and one room at terrace level (not in use) owned/occupied Sarvodaya Co-Operative Housing Society Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concern of this department on 21/11/2024 in the presence of Mr. Amit Kumar and that the premises is fit for occupancy class "Assembly Building, Group-D" (Community Hall at Basement, Ground plus one upper floor only) with effect from 28 / 11 /2024 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 98/11 /2024 at New Delhi by

(ADUL GARG) DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. The Executive Engineer (Bldg.) HQ, Municipal Corporation of Delhi, 8th Floor, Dr. SPM Civic Centre, JLN Marg, New Delhi 110002

2. The President, Sarvodaya Co-Operative Housing Society Ltd, Community Centre, B-74A, Sarvodaya Enclave, New Delhi - 110017.

Conditions for the validity of Fire Safety Certificate: -

1. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

2. All the staff members must know the correct method of operation of fire fighting system.

The basement shall be used strictly as per the provision of UBBL-2016/NBC Part-IV.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

7. This FSC is valid for Basement, Ground plus one upper floor only, no occupancy above first floor is allowed. Unless otherwise this FSC will be treated null & void.





1	INSPECTION REPORT Name & Address of the Building					
	Sarvodaya Co-Operation					
		Community Centre B-74A Society Ltd				
2	Type of Occupancy	Delhi - 110017 Nev				
3	Building Comprised of	Group "D" Community Hall				
	S comprised of	Dasement Grou	nd + One II			
4	Type of Case	Basement, Ground + One Upper floor (01 Room at terrace level is Not in use)				
5	Details of Previous NOC	New Case				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	F6/DFS/MS/BP/98/2392 dated 10.12.1998				
8	Name of the Inspecting Officers	14/11/2024				
9	Name & Designation of Officers	ADO (BCP) Mr. Amit Kumar				
	from the building side					
10	Year of construction	1 1 1 1 2 0 1				
11	Applicant letter No.	2024				
S. No.	Minimum standards on Fire Prevention	Outdoor diary no 8754 dated 08-11-2024				
	and Fire Safety U/R 33	Old NOC	Provided at Site	Remarks		
1	Access to Building.	requirements		MR/NMR		
1	Road width			MINIMI		
_	Gate width	Required	13.5 mtr	MR		
- 1		Required	4.5 mtr	MR		
2	Width of internal road	-NA-	-NA-	- CONTAIN		
4	Number, width, type & arrangement of exits.		144	-NA-		
	a) Number of Staircase					
	Upper floors.	02 No	01 No	100		
	Basement floor.	03 No		NMR		
	b) Width of Staircase	37.7(37.11.4	03 No	MR		
	Upper floors	1.50 mtr each	160			
	Basement floor	1.50 mtr each	1.50 mtr & 1.50 mtr (iron)	MR		
	c) Protection of exits	1.50 IIII each	1.50 mtr each	MR		
	➤ Fire check door	Daw i 1				
Į.	➤ Pressurization	Required	Provided	MR		
- Indiana	(Company of the Comp	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace e) Width of corridor	Required	02 Nos	MR		
- 1		1.50 mtr	Provided	MR		
3	f) Door size (Exits in hall) Compartmentation.	1.50 mtr	Provided	MR		
				MAK		
	• Fire check door.	Required	Provided	MR		
	Sealing of electrical shafts.	Required	Provided	MR		
	Fire rating of shaft door. Water and it.	Required	Provided	MR		
	Water curtain	-NA-	-NA-	-NA-		
4.	• Fire dampers.	-NA-	-NA-	-NA-		
4.	Smoke Management system.			1111		
	Basement	12 ACPH	Exhaust fan Provided	MR		
	Upper floors	12 ACPH	Natural ventilation	2001000		
5.	Fire Extinguishers.		- tendrar ventuation	MR		
	Total numbers	Required	24 Nos			
	Types	ISI marked		MR		
	ISI Marking		Co2 & ABC	MR		
6.	The state of the s	ISI marked	Provided	MR		
0.	First Aid Hose Reels.					
	 Total numbers on each floor. 	02 Nos	Provided	MR		
	 Length of hose-reel hose. 	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided			
	The second secon	1	Dapivora	MR		

आज़ादी का अमृत महोत्र

7	Automatic fire detection & alarming system.	-NA-	-NA-	-NA-
	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	 Alternate source of power 	-NA-	-NA-	-NA-
	Hooter's location	TOTAL PROPERTY.	TOTAL SECTION SECTION	-NA-
8.	MOEFA			-NA-
9.	Public Address System	-NA-		
10.	Automatic Sprinkler System		Provided	MR
	Basement	Required		-NA-
	 Upper floors. 			-NA-
	 Sprinkler above false ceiling 	-NA-	-14/1	
11.	Internal Hydrants.		Provided	MR
	Size of Riser/Down-comer	Required		MR
	 Number of Hydrant per floor 	Required		MR
	Hose box.	Required	Plovided	
12.	Yard Hydrants.		NA.	-NA-
	Total number of hydrants.	-NA-		-NA-
	Hose box.	-NA-	-NA-	-MA-
13.	Pumping arrangements.			
10.	Ground Level			100
	Discharge of main pump.	1000 LPM		MR
	➤ Head of main pump.	40 m		MR
	Number of main pumps.	NA		-NA-
	> Jockey Pump output.	NA		-NA-
	A CONTROL OF CONTROL AS THE WARRENING CONTROL OF CONTRO	NA		-NA-
	> Jockey Pump head.			-NA-
	Standby Pump output.			MR
	Standby Pump head.	Required	Provided	
	Auto Starting/Manual Stopping.	Required	Provided	MR
	Pump house access.			
	Terrace Level	NIA	-NA-	-NA-
	Discharge of pump.			-NA-
	➤ Head of pump.			-NA-
	➤ Power supply.			-NA-
	➤ Auto starting of pump.	-INA-	- 4.16 A	
14.	Captive water storage for fire fighting.	25,000 Ltrs	NA-	MR
	Underground tank capacity.	Required		MR
	> Draw-off connection.	Required		MR
	Fire Service Inlet.	Required		MR
	Access to tank.	12,500 Ltrs		MR
	Overhead tank capacity.	Required	Provided	MR
15.	Exit Signage.	2.05		
16.	Prevision of Lifts. Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift shart.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. Communication in lift car. 		NAV75	-NA-
				-NA-
	Fireman's switch.		10000-0-	-NA-
	Lift signage.		11.27400-1211-	
17.	Standby Power Supply	-NA-	-NA-	-NA-
18.	Refuge Area		V-1	374
10.	Total area	-NA-		-NA-
	Total alon	314	NIA-	-NA-

7



-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
	-NA-	-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
	-NA- -NA- -NA- -NA-	-NANA- -NANA- -NANA-

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 245 dated 08/05/2024 & one room at terrace level is locked & key by the management. (photograph attached)

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire

Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (South)