

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/EH/2024/SZ/ 306

Dated.02./12/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Perch Wine and Coffee Bar located at Unit No M-31, GF, M Block Market, Greater Kailash Part-II, New Delhi 110048 comprised of Basement, Ground plus Two upper floor owned/occupied by Unit of White Water Café Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 22/11/2024 in the presence of Mr. Gokul and found that the premise is fit for occupancy class Group-"D" (Assembly Building) "Restaurant running at Ground floor only" and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on od /12 /2024 at New Delhi by

DIRECTOR

PELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049 (Ref. Portal ID No 2024110416360 dated 04/11/2024)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. The basement shall be used as per the provisions of UBBL-2016.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



		of Address of the Building	Café Pvt Ltd) lo	and Coffee Bar (Unit ocated at Unit No M-3 Kailash Part-II, New Del	1, GF, M Block		
2		of Occupancy	Assembly Building "Group-D" (Restt. at GF only)				
3	Buil	ding Comprised of	Basement, Ground + 02 upper floors				
4	Тур	of Case	New Case				
5	Deta	ils of Previous NOC	Nil				
6		Safety Directives Letter No	UBBL 2016				
7		of Inspection	22/11/2024				
8	_	e of the Inspecting Officers	ADO (BCP)				
9	Name & Designation of Officers		Mr. Gokul				
-	from the building side		MI. COMM.				
10		of construction	1990				
			MUA Portal ID 2024110416360 dated 04/11/2024				
11	Applicant letter No.		UBBL 2016	Provided at Site	Kemarks		
. No.	Minimum standards on Fire Prevention		UBBL 2010	AUDIENT CANAL	MR/NMR		
1	and Fire Safety U/R 33 Access to Building.				MR		
•	Att	Road width	06 mtr	Provided	MR		
		Gate width	Abuts on road	Approachable	N/A		
		Width of internal road	NA	N/A	N/A		
2	NI.	mber, width, type and arrangements of	exits.	man a al 191 e			
	Nu	Number of Staircase			N/A		
	a.	Upper floors	NA	N/A	D/30375		
		Basement floor	NA	N/A	N/A		
	-	Width of Staircase	parve.	THE RESERVE	- N//A		
	b.	Upper floors	NA	N/A	N/A		
		Basement floor	NA	N/A	N/A		
		Protection of exits					
	c.	• Fire check door	N/A	N/A	MR		
		Pressurization	N/A	N/A	N/A		
	_	No. of continuous staircase to terrace	NA	N/A	N/A		
	d.	Width of corridor	N/A	N/A	N/A		
	e. f.	Door size	1.50mtr each	1.50 mtr & 1.50 mtr	MR		
3		mpartmentation.		polarettal. Vice struc	- 17		
-	-	Fire check door.	NA	N/A	N/A		
	1	Sealing of electrical shafts.	NA	N/A	N/A		
		Fire rating of shaft door.	NA	N/A	N/A		
		Water curtain	N/A	N/A	N/A		
		Fire dampers.	N/A	N/A	N/A		
4.	Sı	noke Management system.					
(15,575)	1	Basement	N/A	N/A	N/A		
		Upper floors	12 ACPH	Provided	MR		
5.	F	ire Extinguishers.					
		Total numbers	Required	04 Nos.	MR		
1 3	1	Types	ABC/CO2	ABC/Co2	MR		
		ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.						
		Total numbers on each floor.	01 No	Provided	MR		
		 Length of hose-reel hose. 	30m	Provided	MR		
		Nozzle Diameter	5mm	Provided	MR		
7	7 Automatic Fire Detection and Alarming system.						
		Type of detectors	NA	NA	N/A		
		Location of Main Panel	NA	N/A	N/A		
		Location of Repeater Panel	NA	N/A	N/A		

				J		
	Alternate source of power	NA	N/A	N/A		
	Hooter's location	NA	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System		1			
	Basement	N/A	N/A	N/A		
	 Upper floors 	N/A	N/A	N/A		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11.	Internal Hydrants.			1		
	 Size of Riser/Down-comer 	100 mm	Provided	MR		
	 Number of Hydrant per floor 	01 Nos	Provided	MR		
	Hose box.	01 Nos	Provided	MR		
12.	Yard Hydrants.			T NVA		
	 Total number of hydrants. 	N/A	N/A	N/A		
100	• 2. Hose box.	N/A	N/A	N/A		
13.	Pumping arrangements.					
	Ground Level		25.00	5.00		
	> Discharge of main pump.	NΛ	N/A	N/A		
	➤ Head of main pump.	NA	N/A	N/A		
	Number of main pumps.	NA	N/A	N/A		
1	Jockey Pump output.	NA	N/A	N/A		
	Jockey Pump head.	NA	N/A	N/A		
i	Standby Pump output.	NA	N/A	N/A N/A		
-	> Standby Pump head.	NA	N/A	N/A N/A		
	Auto Starting / Manual Stopping.	NA	N/A	N/A N/A		
	> Access to pump house	NA	N/A	N/A		
	Terrace Level	1.2 8222 1		MR		
- 1	Discharge of pump.	450 LPM	Provided Provided	MR		
- 1	Head of pump.	40m	5.42 (10)			
	Power supply.	Required	Provided	MR		
	Auto starting of pump.	Required	Provided	MR		
14. (Captive water storage for Fire Fighting.					
	 Underground tank capacity. 	NA	N/A	N/A N/A		
	Draw-off connection.	NA	N/A	N/A N/A		
1	Fire Service Inlet.	NA	N/A			
- 1	> Access to tank.	NA	N/A	N/A		
- 1	 Overhead tank capacity. 	20,000 ltr	20,000 ltr	MR		
15. F	Exit Signage.	Required	Provided	MR		
16. P	Provision of Lifts.		3111	N//A		
	 Pressurization of lift shaft. 	NA	N/A	N/A		
	 Pressurization of lift lobby. 	NA	N/A	N/A		
- 1	Communication in lift car.	N/A	N/A	N/A		
- 1	Fireman's switch.	N/A	N/A	N/A		
-1	 Lift signage. 	N/A	N/A	N/A		
17 S	tandby Power Supply	Required	Provided	MR		
-DE-151	efuge Area	11.00		2.22		
-		N/A	N/A	N/A		
	Total area	N/A	N/A	N/A		
	• Location			4		
9. F	ire Control Room.	37/4	N/A	N/A		
	Detector System Panel.	N/A	N/A	N/A		
	Flow Switch Panel.	N/A	N/A	N/A		
	PA system Panel.	N/A	N/A	N/A		
	Battery backup	N/A		N/A		
- 1	Building floor plan	N/A	N/A	IVA		

m19



20. Special Fire Protection System for the Protection of special Risk, if any: N/A N/A N/A The fire protection system provided in the building were randomly checked and found functional at the time of inspection. Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010. Accordingly, DFA is put up for approval and signature please. Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP) DO (South)