


## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6/DFS/MS/2024/WZ/ 721

Dated: 10/12/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Himanshu Cosmetics located at H-234, Sector 3, Bawana Industrial Area, Bawana, Delhi-110039 comprised of Basement, Ground plus Two upper floors was issued fire safety certificate vide Letter No. F6/DFS/MS/2021/WZ/Cos/318 dated 13/07/2021 have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of fire service on 02/12/2024 in the presence of Sh. Rajeev Sahni and that the building premise is fit for occupancy under "Class Industrial Building Group G-2 (ii)" with effect from ...10 1(2) 224... for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on ...I.O. 1.2.2024..... at New Delhi by

Conditions for the validity of Fire Safety Certificate:

1. Means of escape shall not be kept locked or bolted from outside and shall be easily open able at the time of emergency.

2. All the fire safety arrangement provided there-in shall be maintained in good working

3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

6. This certificate cannot be treated in any case for regularizations of unauthorized

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to

8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

9. The basement shall be used as per BBL.

## Copy to : -

- 1. M/s Himanshu Cosmetics located at H-234, Sec-3, DSIIDC Bawana, Delhi-110039.
- 2. The Dy. Drugs Controller/ Licensing Authority, Drug Control department, F-17, Karkardooma, Delhi- 110032.

INSPECTION REPORT

1. Name & address of the building: M/s Himanshu Cosmetics located at H-234, Sec. 3, Bawana Industrial

Area, DSIIDC Bawana, Delhi- 110039.

 Type of Occupancy
 Building Comprised of Industrial G-2(ii)

Basement, Ground plus Two upper floors.

4. Type of Case

5. Details of Previous NOC F6/DFS/MS/2021/WZ/Cos/318 dated 13/07/2021

6. Fire Safety directives letter No : NBC Part- IV 7. Date of inspection 02/12/2024

8. Name of Inspecting Officer R.K.Sinha, ADO (BW)

9. Name and designation of officers

From the building side Sh. Rajeev Sahni

10. Year of Construction 2010-11

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part IV/ Inspection report dated 17/06/2021	Provided at site	Remarks MR/NMR			
1.	Access to building						
	Road width	9 m	Provided	MR			
	Gate width	NA	NA	NA			
	Width of internal road	NA	NA	NA			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	02	02	MR			
	Basements	02	02	MR			
	b. Width of staircases						
	Upper Floor	1.5 m	1.25 m & 0.96 m	MR (old case)			
	Basements	1.5 m	1.25 m & 0.96 m	MR (old case)			
	c. Protection of exits						
	<ul> <li>Fire check door</li> </ul>	NA	NA ·	NA			
	<ul> <li>Pressurization</li> </ul>	NA	NA	NA			
	d. No. of continuous staircases to terrace	01	Provided	MR			
	e. Width of Corridor	NA	NA	NA			
	f. Door Size	1 m	Provided	MR			
3.	Compartmentation						
-	Fire check door	NA_	NA	NA			
	Sealing of electrical shafts	NA NA	NA	NA			
		NA NA	NA NA	_ 500			
	Fire Rating of shaft door     Water Curtain	NA NA	NA NA	NA			
		NA NA	NA NA	NA NA			
4.	Fire Dampers NA NA NA Smoke Management System						
3.5	And the second of	Required	Exhaust Fan Provided	100			
	Basements		Exhaust Fan Provided	MR			
	Upper floors	Required	Exhaust Fan Provided	MR			
5.	Fire Extinguishers						
	<ul> <li>Total numbers</li> </ul>	12	20	MR			
-	Types	ABC/CO2 Type	ABC/ CO2 Type	MR			
	IS marking	Required	Provided	MR			
6.	First-Aid Hose Reels						
	<ul> <li>Total numbers on each floor</li> </ul>	01	Provided Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	THE PARTICULAR STATE	MR			
	Nozzle diameter	5 mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	Type of detectors	NA	NA	NA			
	Location of Main Panel	NA	NA	NA			
	Location of Repeater Panel	NA	NA	NA			
	Alternate source of power	NA	NA	NA			

N-18

_		Jan. 181.				
	Hooters' Location	NA	NA	NA		
1	MOEFA	NA	NA	NA		
	Public Address System	NA	NA	NA		
).	Automatic Sprinkler System					
		Desuled	Provided	MR		
1	Basement	Required Required	Provided	MR		
+	Upper Floor     Sprinkler above false ceiling	NA	NA NA	NA		
1.	Internal Hydrants	344405	www.nc.dr			
1521	Control (Control (Con	W/	NA			
- 1	Size of riser/down-comer	NA	NA NA	NA NA		
1	Number of hydrants per floor	NA NA	NA NA	NA NA		
12.	Hose Box  Vard Hydronte	NA	NA	III		
	Yard Hydrants					
	Total number of hydrants	NA	NA	NA NA		
	Hose Box	NA	NA	NA		
13.	Pumping Arrangements					
	Ground Level					
	<ul> <li>Discharge of main Pump</li> </ul>	NA	NA	NA		
	➤ Head of Main pump	NA	NA	NA		
	> Number of main pumps	NA	NA	NA		
	> Jockey Pump out put	NA	NA	NA		
	> Jockey pump head	NA NA	NA	NA		
	> Standby Pump out put	NA	NA	NA		
	> Standby Pump Head	NA	NA	NA		
	➤ Auto Starting/Manual Stopping	NA	NA	NA		
	> Pump House Access	NA	NA	NA		
	Terrace level					
	➤ Discharge of pump	900 lpm	Provided	MR		
	> Head of the pump	40 m	Provided	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14.	Captive Water Storage for fire fighting					
	<ul> <li>Underground tank capacity</li> </ul>	NA	NA	NA		
	> Draw-off connection	NA	NA	NA		
	➤ Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA	NA		
	Overhead Tank capacity	10,000 ltrs	Provided	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA NA	NA NA	NA NA		
	Communication In lift Car	NA NA	NA	NA		
	Fireman's Grounding Switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17.	Standby power supply	NA	NA	NA		
18.	Refuge Area.					
	> Total Area	NA NA	NA NA	NA NA		
	> Location	NA NA	NA NA	NA NA		

W

	Fire Control Room					
1	Detector System Panel	NA	NA	NA NA		
1	Flow Switch Panel	NA	NA	NA		
	PA System Panel	NA	NA	NA		
	Battery backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested, checked and found

functional at the time of inspection.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/2021/WZ/Cos./318 dated 13/07/2021 under Rule 37 of the Delhi Fire Service Rules, 2010.

> Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

Do(HU)