

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2024/SZ/ 1172

Dated: 09/12 / 2024

## FIRE SAFETY CERTIFICATE

Certified that New Little One's Public School, 162, Rajpur Khurd Colony Ext., New Delhi- 110068 comprised of Ground plus One upper floor was issued Fire Safety Certificate by this department vide letter No. F6/MS/DFS/School/2021/SZ/862 Dated 21-10-2021. The said premise was re-inspected by officer concerned of this department on 26/11/2024 in presence of Mrs. Mamta Sahu (Manager) of the school and found that the said school building have deemed complied with the fire prevention and fire safety accordance with Directorate of Education F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building is fit for occupancy class "Educational Building Group - B" with effect from 9/12/2024 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Service Rules 2010.

Issued on 69/12 2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. New Little One's Public School, 162, Rajpur Khurd Colony Ext., New Delhi- 68

2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-54

## Conditions for the validity of Fire Safety Certificate:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

2. All the staff members must know the correct method of operation of firefighting

3. This certificate cannot be treated as regularization of unauthorized construction, if

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTIO				
1	Name & Address of the Building	New Little One's Public School, 162, Rajpur			
		Knurd Colony Ext. New Delhi- 110068			
2	Type of Occupancy	Educational, Group=B (School)			
3	Building Comprised of	Ground + One upper floor.			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/MS/DFS/Scho	ol/2021/SZ/862 Dated	21-10-2021	
6	Fire Safety Directives Letter No	DOE Circular 01/	03/2011		
7	Date of Inspection	26/11/2024			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar			
9	Name & Designation of Officers from the building side	Mrs. Mamta Sahu (Manager)			
10	Year of construction	2002 & 2013	ACTOR PROPERTY.		
11	Applicant letter No.	Outdoor diary no 9359 dated 20/11/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR	
1.	Access to Building.	P. Commission		p 1	
	Road width	Required	6 mtr	MR	
	Gate width	-NA-	-NA-	-NA-	
		-NA-	-NA-	-NA-	
	Width of internal road		-IVA-	-NA-	
2	Number, width, type & arrangement of ex	its.		T <sub>1</sub>	
	a) Number of Staircase			1	
	▶ Upper floors.	02 Nos	Provided	MR	
	➤ Basement floor.	-NA-	-NA-	-NA-	
	b) Width of Staircase		how will by	No.	
	➤ Upper floors	1.5 m /0.75 m	1.6 m & 0.90 m	MR (old case	
	➤ Basement floor	-NA-	-NA-	-NA-	
	c) Protection of exits				
	Fire check door	-NA-	-NA-	-NA-	
	> Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	Required	01 No	MR	
	e) Width of corridor	-NA-	-NA-	-NA-	
	O Door size	1m	Provided	MR	
2	Compartmentation.				
3.	Fire check door.	-NA-	-NA-	-NA-	
	The Company of the Co	-NA-	-NA-	-NA-	
	Sealing of electrical shafts.  Signature of shaft door.	-NA-	-NA-	-NA-	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-11/1-	-MA-	1171	
4.	Smoke Management system.	20 4 CDIT	417	NIA	
	Basement	30 ACPH	-NA-	-NA-	
	Upper floors	12 ACPH	NA	NA	
	Fire Extinguishers.				
5,	Total numbers	Required	08 Nos	MR	
,		ABC / CO2	ABC & CO2	MR	
9	Types		Provided	MR	
	ISI Marking	ISI marked	Provided	IVIK	
6.	First Aid Hose Reels.		The state of the s		
0.	Total numbers on each floor.	-NA-	-NA-	-NA-	
	The transfer and the same of t	-NA-	-NA-	-NA-	
	Length of hose-reel hose.	The second	-NA-	-NA-	
	Nozzle Diameter	-NA-	-14/4-	-1474	
	Automatic fire detection & alarming system.		1 1		
7.	Automatic in a serious				

	Location of Main Panel	-NA-	-NA-	-NA
	Location of Repeater Panel	-NA-	-NA-	-NA
	Alternate source of power	-NA-	-NA-	-NA
	Hooter's location	-NA-	-NA-	-NA
8.	MOEFA	-NA-	-NA-	-NA
9.	Public Address System	-NA-	-NA-	-NA
10.	Automatic Sprinkler System	-147		
	Basement	-NA-	-NA-	-NA
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.	-144		
	Size of Riser/Down-comer	NA	-NA-	NA.
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.	-NA	11/1	1 1112
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.	-11/1-	-141	147
10.	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	➢ Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	Discharge of pump.	-NA-	-NA-	-NA-
	➢ Head of pump.	-NA-	-NA-	-NA-
	Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.			11 -
	Underground tank capacity.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet. Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	-NA-	-NA-	-NA-
15.	Exit Signage.	-NA- Required	-NA-	-NA-
16.	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	
	Communication in lift car.	-NA-		-NA-
	Fireman's switch.		-NA-	-NA-
	Lift signage.	-NA-	-NA-	-NA-
17	30. 2	-NA-	-NA-	-NA-
17. 18.	Standby Power Supply	-NA-	-NA-	-NA-
	Refuge Area			- 1
	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
9.	Fire Control Room.			
	Detector system panel.	-NA-		
	e. 187		-NA-	-NA-

-	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel. Battery backup. Building floor plan.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/MS/DFS/School/2021/SZ/862 Dated 21-10-2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

DO (SP)

F-1. |-etter in fortryb for