GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



Dated: 27/11/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Star City Mall located at Plot no. 1/A, District Centre, Mayur Vihar Phase -1, Delhi - 110091, comprised of basement, ground plus two upper floors, owned/occupied by M/s Mahatta Towers Private Limited was issued FSC vide letter no. F6/DFS/MS/NDZ/2021/376 dated 05.08.2021. The premise was re-inspected by the officers concerned of this department along with team of Star City Mall on dated 12/11/2024 in presence of Mr. Nadeem Ahmed and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Mercantile Building" basement, ground plus two upper floors with effect from 27/11/2024 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the

at New Delhi by.

Delhi Fire Service Rule 2010, printed below. Issued on 27/11/2024

Copy to:-

1. Mr. Nadeem Ahmed, M/s Star City Mall located at Plot no. 1/A, District Centre, Mayur Vihar Phase -1, Delhi – 110091.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- Basement is being used as store and parking presently.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

M)23

1		me	& address of th	NSPECTION RE			1701			
2	_	ilding		M/s Star City Mall located at Plot no. 1/A, District Centre, Mayur Vihar Phase -1, Delhi – 110091.						
_	Tu	Haing	is comprised of	Basement, ground plus two upper floors						
3	_		occupancy	Mercantile Building						
4	-	pe of		Renewal						
5	_		f previous FSC	F6/DFS/MS/NI	F6/DFS/MS/NDZ/2021/376 dated 05.08.2021					
6			ty direction letter no.	F6/DFS/BP/2004/1969 dated 30/08/2004 12/11/2024						
7	Da	te of i	nspection							
8	Name of the inspecting officers			Ashok Kumar Jaiswal, Divisional Officer / East & Yashwant Singh Meena, A.D.O / Laxmi Nagar						
9	Nai	me o	f the designation o	f Mr. Nadeem Al	Mr. Nadeem Ahmed					
	officer From the building side									
10			onstruction	2004						
11	Applicant's letter no									
	Minimum Standards on			Requiremen	Outdoor Dairy No. 6650 dated 18/09/2024					
S.No	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		Prevention and fire	BBL/NBC		Provided at Site	Remarks MR/NMR			
l			to building							
	a	R	oad width	12 meters.		13 meters.	MR			
	b	G	ate width	4.5 meters.		6.0 meters.	MR			
	c Width of internal road		idth of internal road	6.0 meters.			MR			
2	N	umbe	r, Width, Type and A		xits		TYLK			
	A Number of staircases				-meste.					
		a	Upper floor	05 nos		05 nos.	MR			
		b	Basement	09 nos.		09 nos. + 01 ramp	MR			
	B	1	Width of staircases			os noo. · or ramp	TVIIC			
		a	Upper floor	1.25 meters		1 no. 1.35 meters, 03 s. of 1.25 meters & 01 no. of 0.90 meter	MR (as accepted earlier)			
		b	Basement	1.25 meters	1.2	25 mtrs to 1.35 mtrs	N/A			
	C	Pro	otection of exits	var II		و دو پیدالانالان ا				
		a	Fire check door	Required		Provided	MR			
		b	Pressurization	Required		Provided	MR			
	D No. of continuous staircases to terrace			03 nos.	05 nos.		MR			
	E Width of corridor		dth of corridor	2.5 meters	2.5 meters		MR			
	F Door size		01 meter	1.2 meters /		NA				
it.	Co	mpar	tmentation							
	a Fire check door		check door	Required		Provided	MR			
	b Sealing of electrical shafts			Required		Provided	MR			
	c Fire rating of shaft door d Water curtain		rating of shaft door	02 hrs N/A		02 hrs /	MR			
						N/A	N/A			
	e Fire dampers			Required		Provided	MR			
	Smoke Management System.									
	a Basement			30 A/C Per hour		Provided M				
L.	b Upper floor			30120101			MR			

(W) 1

Star City Mall located at Plot no. 1/A. District Centra, Mayur Vihar Phase -1, Delhi-110091.

5.	Fire Extinguisher								
	a	To	otal numbers	15	50 nos.	MR			
	b		pes	45 nos.	Provided	MR			
	c	_	I marking	CO ₂ & ABC	Provided	MR			
6	Fi		aid-Hose Reels.	ISI marked Provided					
	a			7 05	Provided	MR			
	b	Le	ength of hose reel hose	05 nos.	30 mtrs.	MR			
	c Nozzle diameter		ozzle diameter	30 mtrs.	05 mm	MR			
7	A		natic fire detection and alar	05 mm					
	a Type of detectors								
	b	L	ocation of main panel	Heat & Smoke	CHAIL SPECIAL CONTROL OF STREET	MR MR			
	c	L	ocation of repeater panel	Control Room	Basement	MR			
	d	A	Alternate source of power	Reception	Provided	MR			
	е	H	looter's location	Battery & D.G Set	Provided	MR			
8	M	10EFA		Strategic Location	Provided Provided	MR			
9		ublic address System.		Required	HIMEG	MR			
10	Automatic Sprinkler System.			Required	Provided	MIK			
	a	Ba	sement	D	D 11 1	1 MD			
	b	-	oper floors	Required	Provided	MR			
				Required	Provided	MR			
11	c Sprinkler above false ceiling			N/A	N/A	N/A			
11	Internal Hydrants								
	a	22017CHA		150 mm 150 mm		MR			
	b		imber of hydrants per floor	05 no.	Provided	MR			
	c Hose Box each floor			05 no.	Provided	MR			
12	Y	_	Hydrants.						
	a	Total number of hydrants		06 no.	06 nos.	MR			
	b	Hose Box		06 no. 06 nos.		MR			
13	Pu	ımp	ing Arrangements.			-10			
	Α		Ground Level						
		a	Discharge of main Pump	4500 LPM	4500 LPM	MR			
		b	Head of Main Pump	50 mtrs	50 mtrs	MR			
		c	Number of main pumps	02 nos	02 nos.	MR			
		d	Jockey pump out put	450 LPM	450 LPM	MR			
		e	Jockey pump head	50 mtrs	50 mtrs	MR			
		f	Standby pump out put	4500 LPM	4500 LPM	MR			
		g	Standby pump head	50 mtrs.	50 mtrs.	MR			
		h	Auto starting /manual stopping	Required	Provided	MR			
	В	Te	rrace Level	All above pumps on terrace					
		a	Discharge of pump	N/A	N/A	N/A			
		b	Head of the Pump	N/A	N/A	N/A			
		С	Power supply	N/A	N/A	N/A			
		d	Auto Starting of pump	N/A		N/A			
		d	Auto Starting	of pump	of pump N/A	of pump N/A N/A			



Star City Mall located at Plot no. 1/A, District Centre, Mayur Vihar Phase -1, Delhi-110091.

14	C	aptive Water Storage for Fire F	ighting.	2 00 000 14	MR		
2.	a	Underground tank capacity	2,00,000 liters	2,00,000 liters'	MR		
	b	Draw-off connection	Required	Provided			
	c	Fire service inlet	Required	Provided	MR		
	d	Access to tank	Required	Provided	MR		
	e	Overhead Tank capacity	2,50,000 liters	2,50,000 liters	MR		
15		xit Signage.	Required	Provided	MR		
16	Description of Lifts						
10	= (Pressurization of Lift Shaft	Required	Provided	MR		
	a b	Pressurization of Lift lobby	Required	Provided in basement	MR		
		a to the lift cor	Required	Provided	MR		
	С	Communication in lift car	Required	Provided	MR		
	d	Firemen's switch	Required	Provided	MR		
	e	Lift Signage		Provided	MR		
17	Standby power supply Required Provid						
18	Refuge Area. NA NA 214 NA						
	a	Total area		NA NA	NA NA		
	ь	Location	NA	NA			
19	Fire Control Room						
	a	Detector system panel	Required	presentation of the second	MR MR		
	b	Flow switch panel []	Required	Provided			
	-	PA system panel	Required	Provided	MR		
	c		Required	Provided	MR		
	d	Battery backup	Required	Provided	MR		
	e Building Floor Plans Special Fire Protection systems for		r protection of speci	protection of special Risks, if			
20	Sp	n	nels.				

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view of above deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC / FSC was issued vide letter no. F6/DFS/MS/NDZ/2021/376 dated 05.08.2021 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer

: Ashok Kumar Jaiswal Name

Designation: Divisional Office/ East

Signature of the Inspecting Officer

: Yaswant SinghMeena Name Designation: ADO /Laxmi Nagar

what is the use of Basement?