

No.F6/DFS/MS/GH/NDZ/2024/ 498

Dated: 16/12/2024

FIRE SAFETY CERTIFICATE

Certified that the Aman Continental located at 1048-984, Main Bazar, Mantola, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (03 guest rooms + Reception + Lounge + Office), 1st floor (08 guest rooms), 2nd floor (10 guest rooms), 3rd floor (10 guest rooms) as above 31 guest rooms up to third floor only and an affidavit dated 08.12.2019 given by applicant regarding to not use any floor above third, owned/occupied by Aman Continental was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2022/40 dated 19/01/2022. Now, the premises was re-inspected by the officer concerned of this department on 09/12/24 in the presence of Manager and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (03 guest rooms + Reception + Lounge + Office), 1st floor (08 guest rooms), 2nd floor (10 guest rooms), 3rd floor (10 guest rooms) as above 31 guest rooms upto third floor only and valid up to three year from the date of in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .16.112.2024 at New Delhi by.

Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed above and deviation if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi online ID No. 2024112517257 dated 26.11.24

3. The Manager, Aman Continental, 1048-984, Main Bazar, Mantola, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for guest house ground to third floor only.

2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.

TION REPORT

1. Name & address of the building

Aman Continental at 1048-984, Main Bazar, Mantola, Pahar Ganj, New Delhi .

2. Type of occupancy:-

Residential, Sub Division-A-1

Ground + 04 Upper floors (total 31 guest rooms)
Ground floor (03 guest rooms + Reception + Lounge + Office), 1st floor (08 guest rooms), 2nd floor (10° guest rooms), 3rd floor (10 guest rooms) and 4th floor an affidavit given by owner dated 08.12.2019 regarding not to use any floor above third floor.

3. Type of case:-

Renewal

4. Details of previous FSC:-

No. F6/DFS/MS/GH/NDZ/2022/40 dated

19/01/2022.

5. Fire safety directives No .-

N/A

6. Date of inspection:-

09/12/24.

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

Mr Aman Deep

9. Year of construction:-

2014

10. Applicant's letter No:-

online ID No. 2024112517257 dated 26.11.24

Old Case Remarks Provided at site Requirement/ Minimum Standards on fire MR/NMR S.No. Existing fire safety Prevention and fire safety U/R 33 arrangements Access to Building 1. MR 6 mtr. Required 1) Road width N/A N/A N/A 2) Gate width N/A N/A N/A 3) Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 No. 01 No. 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.55 mtr. 1.5 mtr. 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits MR Provided Required 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace N/A N/A N/A E. Width of corridor MR 01 mtr. 01 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. N/A N/A N/A 1) Basements MR Natural/exhaust 12 a/c per 2) Upper floors fan hour Fire Extinguishers 5. MR 12 Nos. 12 Nos. 1) Total numbers MR ABC & CO2 ABC & CO2 2) Types MR Provided 3) ISI marking Required

a lu

	1
4	hn.
, ,	100

					21	
6.	First-Aid Hose Reel			1		
	1) Total number of eachfloor	01	01	1	I N	
	2) Length of hose reel hose	30 mtr.	30 mtr.		M	
	3) Nozzle diameter	05 mm	05 mm		M	
7.	Automatic Fire Detection &	In the Bon Stiff Stiff feet	vstem			
(Folder 1)	1) Type of detectors CO	Required	Provided		M	
	Type	Roquired	- H. T. S.			
	2) Location of main panel	Required	Provided		M	
	3) Location of repeater panel	N/A	N/A	-	N/A	
	4) Alternate source of power	Required	Provided	- 1	MR	
	5) Hooter's Location	Required	Provided	1	MR	
	No. 2 Contract Contra	Required	Provided	1	MR	
8.	MOEFA	Required	Provided	Į,	MR	
9.	Public Address System					
10.	Automatic Sprinkler System	N/A	N/A		N/A	
	1) Basement(Less than 189 SQM)	N/A	N/A		N/A	
	Upper floors Sprinkler above false	N/A	N/A		N/A	
	ceiling			4	DI/A	
11.	Internal Hydrants 1) Size of riser/down-comer	N/A	N/A	4	N/A N/A	
	2) Number of hydrants per	N/A	N/A		14/24	
	floor		37/4	+	N/A	
	3) Hose box N/A N/A N/A					
12.	Vord Hydrants	27/1	N/A	1	N/A	
12.	1) Total number of hydrants	N/A	N/A	I	N/A	
	2) Hose box	N/A		1		
13.	Pumping Arrangement	N/A	N/A		N/A	
	1) Ground level	N/A	N/A		N/A	
	a) Discharge of main	4763556		-	N/A	
	b) Head of main pump	N/A	N/A	#	N/A	
	c) Number of main pump	N/A	N/A N/A	+	N/A	
	d) Jockey pump out put	N/A	N/A	1	N/A	
	e) Tockey pump head	N/A N/A	N/A	1	N/A	
	f) Stand by pump output	N/A	N/A		N/A	
	g) Stand by pump head h) Auto starting/Manual stopping	N/A	N/A		N/A	
-	2) Terrace level		1	1) (D	
	a) Discharge of pump	450 LPM	450 LPM	/	MR MR	
	b) Head of pump	40 mtr.	40 mtr. Provided	+	MR	
	c) Power supply	Required Required	Provided		MR	
	d) Auto starting of pump Required Provided Captive Water Storage for Fire Fighting					
14.	1) Under ground tank capacity	N/A	N/A		N/A	
	a) Draw-off connection	N/A	N/A		N/A	
	b) Fire service inlet	N/A	N/A		N/A	
	c) Access to tank	N/A 10,000 ltr.	N/A 10,000 ltr.		N/A MR	
	d) Over head tank capacity	10,000 1	F. S. S. F. G. S. F. G. S.	/ I		

6.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
•:	 b) Pressurization of lift lobby 	N/A	N/A	N/A
- 14	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	N/A		

The above fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2022/40 dated 19/01/2022, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is prepared and put up for kind perusal/approval please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

11/12/24

Kiv Plata

Dênea M. M.

A Ce