

OVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2024/SZ/401 No.

FIRE SAFETY CERTIFICATE

Certified that The Eating House in the Name & Style of M/s GUNG THE PLACE located at D-1/B, GF, FF & SF Green Park, New Delhi 110016 in the building Comprised of Basement, ground plus two upper floors owned/occupied by (A Unit of YJ EXIM & Restaurants Pvt. Ltd) was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/SZ/2021/274 dated 05/10/2021. The restaurant premise was re-inspected by the officer concerned of this department on 04/12/2024 in the presence of Mr. Moses (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant at ground plus two upper floor only) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12 / 12 / 2024 at New Delhi by

DEHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MCD Portal ID 2024111416805 dated 14/11/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

5. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

6. This fire safety certificate may not in any way be treated as regularization (Clause UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six

		W 15	7			
	INSPECTIO	N REPORT	आजादी	का		
1 1	Name & Address of the Building	M/s GUNG THE PLACE, (A Unit of YJ EXIM & Restaurants Pvt. Ltd) D-1/B, GF, FF & SF Green				
2	Type of Occupancy	Park, New Delhi 110016				
3	Building Comprised of	Group-D Assembly Building. (Eating House) Basement, Ground + Two upper Floor				
	Type of Case	Renewal	id + I wo upper Floor			
5	Details of Previous NOC	A PRESE				
	Fire Safety Directives Letter No		SZ/2021/274 dated 05	5/10/2021		
323	Date of Inspection	Nil				
8		04/12/2024				
9	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
,	Name & Designation of Officers from the building side	Mr. Moses (Manager)				
10	Year of construction	2001 Restt. Running at Ground First Floor & Second Floor only.				
11	Applicant letter No.	MCD Portal ID 2024111416805 dated 14/11/2024				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMI		
1	Access to Building.					
	Road width	Required	10 mtr	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of ex	its.				
	a) Number of Staircase	ľ				
	> Upper floors.	02 No's	02 No	MR		
	➤ Basement floor.	N/A	N/A	N/A		
	b) Width of Staircase					
	> Upper floors	1.25 m each	1.0 m & 0.78 m (iron)	MR (old case)		
1	➤ Basement floor	N/A	N/A	N/A		
	c) Protection of exits					
	➤ Fire check door	N/A	N/A	N/A		
	▶ Pressurization	N/A	N/A	N/A		
	d) No. of continuous staircase to terrace	Required	02 Nos	MR		
	e) Width of corridor	N/A	N/A	N/A		
	f) Door size	2 Exit	1.05 m & 0.84 m	MR (old case		
3	Compartmentation.		ng b			
	Fire check door.	N/A	N/A	N/A		
	Sealing of electrical shafts.	N/A	N/A	N/A		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
4	Fire dampers. Smoke Management system.	N/A	N/A	N/A		
	Basement	12 ACDU	2011			
	Upper floors	12 ACPH	N/A	N/A		
5	Fire Extinguishers.	12 ACPH	Exhaust Fans Provide	d MR		
	Total numbers	200				
		06 Nos	08 Nos	MR		
1	Types	ABC/CO ₂	ABC-06 & CO ₂ -	MR		
	ISI Marking	ISI marked	02 Provided	MR		



	Total numbers on each floor.	One	Provided	M
	Length of hose-reel hose.	30m	Provided	M
	Nozzle Diameter	5mm	Provided	MI
7	Automatic fire detection & alarming syst			
1		N/A	N/A	N/A
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel CR	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
-	Hooter's location		Provided	MR
8	MOEFA	Required N/A	N/A	N/A
9	Public Address System	N/A		
10	Automatic Sprinkler System	N/A	N/A	N/A
	Basement	N/A N/A	N/A	N/A
	 Ground/ upper floors. 	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A		
11	Internal Hydrants.	N/A	N/A	N/A
	Size of Riser/Down-comer	N/A	N/A	N/A
	 Number of Hydrant per floor 	N/A	N/A	N/A
	Hose box.			N/A
12	Yard Hydrants.	N/A	N/A	N/A
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.			-
13	Pumping arrangements.			N/A
	Ground Level Discharge of main pump.	N/A	N/A	N/A
	 Head of main pump. 	N/A	N/A	N/A
	> Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.Auto Starting/Manual Stopping.	N/A	N/A	N/A
	> Auto Starting/Manual Stopping. > Pump house access.	N/A	N/A	N/A
	/ Tump nous	N/A	N/A	14/21
	Terrace Level		Provided	MR
	Discharge of pump.	_ 450 LPM	Provided	MR
	➢ Head of pump.	40m	Provided	MR
	Power supply.Auto starting of pump.	Required	Provided	MR
	AND SECURITIONS ASSESSMENT OF THE PROPERTY OF	Required	Hoylded	
14	Captive water storage for fire fighting.	N/A	N/A	N/A
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	 Draw-off connection. Fire Service Inlet. 	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltrs	5,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	required		·
10	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A

B



	Lift signage.	N/A		
17	Standby Power Supply	11 P. MAY - 11	N/A	N/A
18	Refuge Area	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
10	• Location	N/A	N/A	N/A
19	Fire Control Room.			
502	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 449 dated 14/10/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2021/274 dated 05/10/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

(the en