



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

F.6/DFS/MS/GH/2024/SZ/ 503 No.

Dated: 6/12/2024

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Arch (Guest House) located at A-85, Gali No. 06, Road No. 04, Mahipalpur Extension, New Delhi-110037, comprised of Basement (vacant), Ground Floor (Rec., Office & Hall), First Floor (13 guest rooms), Second & Third Floor (18 guest rooms at each), owned/occupied by M/s Hotel Arch, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 03/12/2024 in the presence of Sh. Ankit Lohia (Proprietor) and that the building/premises is fit for occupancy class "Residential Group A" (Guest House with 49 Guest Rooms) for a period up to 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service Rules, 2010.

Issued on 16 12 2021 at New Delhi by

T. No. 01 23414000

Copy to: -

1. The Joint Commissioner of Police, Licensing Unit, 1st Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. online ID No. 2024112917439 dated 29/11/2024)

2. Authorized Signatory M/s Hotel Arch situated at A-85, Gali No. 06, Road No. 04, Mahipalpur Extension, New Delhi-110037

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The basement shall be used strictly in accordance with Building Bye-Laws

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its

1		ION REPO	KI	No 6	
1.	Name & address of the building	M/s Hotel Arch located at A-85, Gali No. 6, Road No. 4, Mahipalpur Extension, New Delhi-110037			
2.	Type of Occupancy	Residential "Group A" (Guest House)			
3.	Building Comprised of	Basement, Ground & 3 upper floors			
4.	Type of Case	New Case			
5.	Details of previous NOC	Nil			
6.	Fire Safety directives letter No.	NBC/UBBI	L-2016		
7.	Date of inspection	03/12/2024		1 1 1	
8.	Name of Inspecting Officer	ADO (SJ)			
9.	Name and designation of Officer	Sh. Ankit Lohia (Proprietor)			
10.	from building side Year of Construction	Basement (vacant), Gd. Floor (Rec Office & Hall) 1st Floor (13 G/Rooms), 2nd & 3rd Floor (18 Guest rooms each), Total= 49 Guest Rooms]			
	/ Online	ID No. 202	4112917439 dated 29/11/2	.024	
11.	Applicant letter No. / Online	NBC/UBB	Drovided at site	Remarks	
S. No	Minimum standards on fire prevention and fire safety U/R 33	Requiremen		MR/NMF	
1.	Access of building	Daninal	6 mtr	MR	
	Road width	Required -NA-	-NA-	-NA-	
	Gate width	-NA-	-NA-	-NA-	
	 Width of internal road 		.,		
2.	Number, width, Type & Arrangemen	ts of exits			
	a. Number of staircases		03 Nos	MR	
	Upper floors	02 Nos	03 Nos 02 + 1ramp	MR	
	Basements	02 Nos	02 + Hamp	1111	
	b. Width of staircases	Y	1 - 10 0150	MR	
	Upper floors	1.50 mtr	1.5m, 1.3m & 1.52m		
	Basements	1.50 mtr	2 x 1.5m & 3m ramp	MR	
	c. Protection of exits		per clause 7.31 UBBL-20	MR	
	 Fire check door 	Required	Provided -NA-	-NA-	
	Pressurization	-NA-	Provided	MR	
	d. No of continuous staircase to terrace	Required	Provided	MR	
	e. Width of Corridor	Required		MR	
	f. Door Size	Required	1.50m (final exit)	MIK	
3.	Compartmentation			1 NO	
	Fire check door	Required	Provided	MR	
	 Sealing of electrical shafts 	Required	Provided	MR	
	 Fire Rating of shaft door 	-NA-	-NA-	-NA	
	Water Curtain	-NA-	-NA-	-NA-	
	Fire Dampers	-NA-	-NA-	-NA-	
4.	Smoke Managements System	As per clause 7.31 UBBL-2016			
4.	 Basements 	30 ACPH		MR MR	
4.	5005 ATC		Exhaust fans provided	IVIK	
	Upper floors	12 ACPH			
5.	Upper floors Fire Extinguishers		20 Nos	MD	
	Upper floors Fire Extinguishers Total numbers	Required	27 April 2 W. 10 April 2 W. 10 April 2	MR	
	Upper floors Fire Extinguishers Total numbers Types	Required ABC/W.CO	ABC & CO ₂	MR	
5.	Upper floors Fire Extinguishers Total numbers Types ISI marking	Required	ABC & CO ₂	MR	
	Upper floors Fire Extinguishers Total numbers Types ISI marking First-Aid Hose Reels	Required ABC/W.CC ISI marked	ABC & CO ₂ Provided	MR MR	
5.	Upper floors Fire Extinguishers Total numbers Types ISI marking First-Aid Hose Reels	Required ABC/W.CO	ABC & CO ₂	MR	

81

ND

7.	Automatic fire detection and alarming	system (As per cl	lause 7 31 of LIRRI	-2016)
	Type of detector (CO Mo.)	Required	Provided	MR
	Location of Main Panel	Required	Ground floor	MR
	57 C 554-1	-NA-	-NA-	-NA-
	Document of Itopouter Tuner	Required	Provided	MR
	Alternate source of power	-NA-	-NA-	-NA-
	Hooters' Location	35.000.00	10 CONT. 10	365,000
8.	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System			
	Basements	-NA-	-NA-	-NA-
	Upper Floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants			
	 Size of riser/down- comer 	-NA-	-NA-	-NA-
	 Number of hydrants per floor 	-NA-	-NA-	-NA-
	Hose Box	-NA-	-NA-	-NA-
12	Yard Hydrants			
	Total number of hydrants	-NA-	-NA-	-NA-
	Hose Box	-NA-	-NA-	-NA-
13	Pumping Arrangements			
	Ground Level			
	> Discharge of main pump	-NA-	-NA-	-NA-
	> Head of main pump	-NA-	-NA-	-NA-
	> Number of main pumps	-NA-	-NA-	-NA-
	> Jockey pump out put	-NA-	-NA-	-NA-
	Jockey pump head	-NA-	-NA-	-NA-
	Standby Pump out put	-NA-	-NA-	-NA-
	> Standby Pump Head	-NA-	-NA-	-NA-
	> Auto Staring/Manual stopping		-NA-	-NA-
	> Pump House Access	-NA-	-NA-	-NA-
	Terrace level	ž .		4
	Discharge of pump	900 LPM	900 LPM	MR
	➤ Head of the pump	40m	40m	MR
	Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for firefighting			1
	Underground tank capacity	-NA-	30,000 Ltr	-NA-
	> Draw of connection	-NA-	-NA-	-NA-
	> Fire service inlet	-NA-	-NA-	-NA-
	> Access to tank	-NA-	-NA-	-NA-
	Overhead Tank capacity	15,000 Ltr	20,000 Ltr	MR
15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	> Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	> Pressurization of lift lobby	-NA-	-NA-	-NA-
	Communication in lift Car			- 0.42000
	D	-NA-	-NA-	-NA-
	> Fireman's Grounding Switch	-NA-	-NA-	-NA
	➤ Lift Signage	-NA-	-NA-	-NA
17.	Standby Power Supply	Required	Provided	MR
	Refuge Area			
18.			A18-23	2320
18.	> Total area	-NA-	-NA-	-NA

9.	Fire Control Room		374	-NA-
	Detector system panel	-NA-	-NA-	
	 ➢ Flow Switch Panel ➢ PA System Panel ➢ Battery backup ➢ Building Floor Plans 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
			-NA-	-NA-
		-NA-		-NA-
		-NA-	-NA-	
20.	Special Fire Protection Systems for	-NA-	-NA-	-NA-

The fire protection system provided in the building/premises were checked, tested at random and found functional at the time of inspection.

In view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, issuance of fire safety certificate, under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Muler Maky

Cholies Hugh

13/13/12014

Director by

MySi)

Sir

F.T letter is pulnip for your Sing. Pl

16.12.24

18/24