



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/GH/2024/SZ/496

Dated: 13/12/2024

## **FIRE SAFETY CERTIFICATE**

Certified that M/s Hotel Kelvish located at Property No. 3, 86/1, Khasra No. 548, Mahipalpur Extension, New Delhi-110023, comprised of Basement (Vacant), Ground (Reception & office), First to Third Floor (09 G/Rooms each) Total=27 Guest Rooms, owned/occupied by M/s Hotel Kelvish was issued Fire Safety Certificate vide letter No. F.6/DFS/MS/GH/2022/SZ/110 dated 18/02/2022. The premise was re-inspected by the officer concerned of this department on 05/12/2024 in the presence of Sh. Rajeev Dhandhi (Owner) and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said building/premises is fit for occupancy class "Residential & Lodging, Group-A" (Guest House with 27 guest rooms) with effect from \( \frac{13}{12} \) 12 /2024 for a period up to \( \frac{31/03/2027}{2027} \) in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13 12 2024 at New Delhi by

(ATUL GARG)
DIRECTOR
10. 011-23414000

## Copy to: -

1. The Joint Commissioner of Police, Licensing Unit, First Floor, Police Station Defence Colony, New Delhi-110037 (w.r.t. online ID No. 2024100915464 dated 25/11/2024)

2. Sh. Rajeev Dhandhi M/s Hotel Kelvish located at Property No. 3, 86/1, Khasra No. 548, Mahipalpur Extension, New Delhi-110037

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The Basement shall be used as per BBL-1983
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

N-15

	INSPECT	ION REPORT			
1.	Name & address of the building	M/s <b>Hotel Kelvish</b> at Property No. 3, 86/1, Khasra No. 548, Mahipalpur Extension, New Delhi–110037			
2.	Type of Occupancy	Group A "Rooming & Lodging House"			
3.	Building Comprised of	Basement (vacant), Ground & 3 upper floors.			
4.	Type of Case	Renewal			
5.	Details of previous NOC	F.6/DFS/MS/GH/2022/SZ/110 Dt. 18/02/2022			
6.	Fire Safety directives letter No.	Nil			
7.	Date of inspection	05/12/2024			
	Name of Inspecting Officer	ADO (SJ)			
8.	Name and designation of Officer	Sh. Rajeev Dhandhi (Owner)			
9.	from building side				
10.	Year of Construction	2009 1st to 3rd floor (09 Room each), Total =27 G/Room			
11.	Applicant letter No. / Online	ID No. 2024100	915464 dated 25/11	/2024	
S.	Minimum standards on fire	Old NOC	Provided at site	Remarks MR/NMI	
S. No	prevention and fire safety U/R 33	Requirement		MINIMIN	
1.	Access of building			MR	
/#/6	Road width	06 mtr	Provided		
	Gate width	-NA-	-NA-	-NA-	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, Type & Arrangemen	ts of exits			
2.	3.7 1 C-4-1				
	NAC	01 No	Provided	MR	
	Upper floors  Proper floors	02 Nos	1 + 1 ramp	-NA-	
	Basements     Width of staircases				
		1.25 mtr	1.27 mtr	MR	
	Upper floors	1.25 mtr	1.5m & 3m ramp	MR	
	Basements  Particular of critical  Basements	As per cl	ause 7.31 UBBL-20	016	
	c. Protection of exits  • Fire check door	Required	Provided	MK	
	Pressurization	-NA-	-NA-	-NA-	
	d. No of continuous staircase to terrace	One	Provided	MR	
	e. Width of Corridor	-NA-	-NA-	-NA-	
	f. Door Size	1 mtr	1.2m (final exit)	MR	
3.	Compartmentation				
Э.	Fire check door	-NA-	-NA-	-NA-	
	Sealing of electrical shafts	-NA-	-NA-	-NA-	
	Fire Rating of shaft door	-NA-	-NA-	-NA-	
	Water Curtain	-NA-	-NA-	-NA-	
	Fire Dampers	-NA-	-NA-	-NA-	
1	Smoke Managements System	As per cl	ause 7.31 UBBL-20	016	
4	CHILDRE IVIGILIZEDINE DI DECLE	30 ACPH	Provided	MR	
4.	The state of the s	JULICITI		50 VECTOR 1	
4.	Basements	12 ACPH	Provided	MR	
V-80	Basements     Upper floors	8 6 4 5	Provided	MR	
5.	Basements     Upper floors  Fire Extinguishers	12 ACPH	Provided 10 Nos	MR	
V-80	Basements     Upper floors  Fire Extinguishers     Total numbers	12 ACPH 10 Nos	10 Nos		
V-80	Basements     Upper floors  Fire Extinguishers     Total numbers     Types	12 ACPH  10 Nos  ABC/CO <sub>2</sub>	10 Nos ABC Type	MR MR	
5.	Basements     Upper floors  Fire Extinguishers     Total numbers     Types     ISI marking	12 ACPH 10 Nos	10 Nos	MR	
	Basements     Upper floors  Fire Extinguishers     Total numbers     Types     ISI marking  First-Aid Hose Reels	10 Nos ABC/CO <sub>2</sub> ISI marked	10 Nos ABC Type Provided	MR MR MR	
5.	Basements     Upper floors  Fire Extinguishers     Total numbers     Types     ISI marking	12 ACPH  10 Nos  ABC/CO <sub>2</sub>	10 Nos ABC Type	MR MR	



7.	Automatic fire detection and alarming s	Required	Provided	MR
	Type of detector (CO. Mo)  Leasting of Main Penel	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel		-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooters' Location	-NA-		MR
8.	MOEFA	Required	Provided	-NA-
9	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System		D 11 1	MR
	Basements	Required	Provided	-NA-
	Upper Floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-INA-
11	Internal Hydrants	A97500 Rei	N. 4	-NA-
	Size of riser/down- comer	-NA-	-NA-	-NA-
	Number of hydrants per floor	-NA-	-NA-	EAST-
	Hose Box	-NA-	-NA-	-NA-
12	Yard Hydrants			
12	Total number of hydrants	-NA-	-NA-	-NA-
	Hose Box	-NA-	-NA-	-NA-
10	Pumping Arrangements			
13				
	Ground Level     Discharge of main pump	-NA-	-NA-	-NA-
	Head of main pump	-NA-	-NA-	-NA-
	> Number of main pumps	-NA-	-NA-	-NA-
	Jockey pump out put	-NA-	-NA-	-NA-
	> Jockey pump head	-NA-	-NA-	-NA-
	> Standby Pump out put	-NA-	-NA-	-NA-
	<ul><li>Standby Pump Head</li><li>Auto Staring/Manual stopping</li></ul>	-NA-	-NA-	-NA-
	> Auto Staring/Manual stopping > Pump House Access	-NA-	-NA-	-NA-
	W. Name of the second	1177		
	Terrace level     Discharge of pump	900 LPM	Provided	MR
	> Head of the pump	40m	Provided	MR
	> Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14	Captive water Storage for fire fighting			
	Underground tank capacity	-NA-	-NA-	-NA-
	> Draw of connection	-NA-	-NA-	-NA-
	➤ Fire service inlet	-NA-	-NA-	-NA-
	> Access to tank	-NA-	-NA-	-NA-
	Overhead Tank capacity	10,000 Ltr	Provided	MR
15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts	Section St.	, E	
	<ul><li>Pressurization of Lift Shaft</li></ul>	-NA-	-NA-	-NA
	Pressurization of lift lobby	-NA-	-NA-	-NA
	➤ Communication in lift Car	-NA-	-NA-	-NA
	➤ Fireman's Grounding Switch	-NA-	-NA-	-NA
	➤ Lift Signage	-NA-	-NA-	-NA
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area		110 TIGOU	IVIN
	> Total area	-NA-	-NA-	-NA
	- Iounaioa	-IVA-	-INI A	

9.	Fire Control Room  Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
.0.	Special Fire Protection Systems for Protection of Special Risks, if any;	-NA-	-NA-	

The fire protection system provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/GH/2022/SZ/110 dated 18/02/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)

Directar My May 5)

Sir, F.T weger is promp for your sing. pl

Director Jean Mann

8 Juman 12.12.24

V Polonski A