



C-46 75
आज़ादी का
अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/WZ/2024/ 406

Dated: 13/12/2024

FIRE SAFETY CERTIFICATE

Certified that the Tucasa Mazi (A unit of Pragati Toys Pvt Ltd) located at F-85, Shivaji Place Enclave, District Centre, New Delhi-110027, in a building comprised of Basement + Ground + Two Upper Floors. Owned/occupied by Tucasa Mazi (A unit of Pragati Toys Pvt Ltd), was issued fire safety certificate by this department vide letter no. F6/DFS/MS/EH/WZ/2021/332 dated 11/11/2021. The premises was re-inspected by the officer concerned of this department on 04/12/2024 in the presence of Sh. Bhupinder Singh and found that the Fire prevention and fire safety arrangements provided in the building found in good working condition. The premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire service Rules, 2010 and that the building / premises is fit for occupancy class "Assembly" (Group-D) for Ground & Two Upper Floors and valid upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 conditions mentioned below.

Issued on13/12/2024 at New Delhi by.

(Atul Garg)
Director

Copy to: -

1. The owner/ Occupier, Tucasa Mazi (A unit of Pragati Toys Pvt Ltd), F-85, Shivaji Place Enclave, District Centre, New Delhi-110027.
2. The Dy. Health Officer, MCD, West Zone, Vishal Enclave, Rajouri Garden, New Delhi – 110027. dhowestzone@gmail.com
3. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. adlcp.lic-dl@nic.in.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. Basement shall be used as per building bye laws.
7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

117

INSPECTION REPORT

1.	Name & address of the building	Tucasa Mazi (A unit of Pragati Toys Pvt Ltd) located at F-85, Shivaji Place Enclave, District Centre, New Delhi-110027
2.	Type of Occupancy	Assembly (Group-D)
3.	Type of Case	Renewal
4.	Details of previous NOC	F6/DFS/MS/EH/WZ/2021/332 dated 11/11/2021
5.	Fire Safety directives letter No	Nil
6.	Date of inspection	04/12/2024
7.	Name of the Inspecting Officers	Sarabjeet Singh ADO (MN)
8.	Name and designation of officers from the building side	Bhupinder Singh
9.	Year of Construction	2003 (As per MHA portal)
10.	Applicant's letter No.	MHA portal ID- 2023051008563 dated 16/11/2024

The said Restaurant is running at Ground & Two Upper Floor in Building comprised of Basement + Ground + Two Upper Floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	09 mtr	Provided	MR
	• Gate width	4.5 mtr	On Road	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	2	Provided	MR
	• Upper Floors	NA	NA	NA
	• Basements			
	b. Width of staircases			
	• Upper Floors	2 mts & 1.5 mts	Provided	MR
	• Basements	2 mts & 1.5 mts	Provided	MR
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	e. No. of continuous staircases to terrace	02	Provided	MR
	f. Width of Corridor	NA	NA	NA
	g. Door Size	2 m & 1.5 m	Provided	MR
3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	30 a/c per hour	Provided	MR
	• Upper floors	12 a/c per hour	Provided	MR
5	Fire Extinguishers			
	• Total numbers	10 nos.	Provided	MR
	• Types	CO ₂ , ABC type	Provided	MR
	• IS marking	ISI marked	Provided	MR

200

6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30 mtr	Provided	MR
	• Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	Smoke	Provided	MR
	• Location of Main Panel	G.F	Provided	MR
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Near staircase	Provided	MR
8	MOEFA	Required	Provided	NA
		NA	NA	NA
9	Public Address System.			
10	Automatic Sprinkler System.			
	• Basement	Required	Provided	MR
	• Upper Floor	NA	Provided	NA
	• Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants per floor	01	Provided	MR
	• Hose Box	01	Provided	MR
12	Yard Hydrants.			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13	Pumping Arrangements.			
	• Ground Level			
	➤ Discharge of main Pump	2280 lpm	Provided	MR
	➤ Head of Main pump	60 m	Provided	MR
	➤ Number of main pumps	1	Provided	MR
	➤ Jockey Pump out put	180 lpm	Provided	MR
	➤ Jockey pump head	60 m	Provided	MR
	➤ Standby Pump out put	2280 lpm	Provided	MR
	➤ Standby Pump Head	60 m	Provided	MR
	➤ Auto Starting/ Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	450 lpm	Provided	MR
	➤ Head of the pump	40 m	Provided	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	1,00,000 liters	Provided	MR
	➤ Draw-off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	5,000 ltrs	20,000 ltrs Provided	MR
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts.			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	Required	Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	• Lift Signage	Required	Provided	MR
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Battery backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F6/DFS/MS/EH/WZ/2021/332 dated 11/11/2021 renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

(Signature)

(Signature)
05/12/2024

Signature of the Inspecting Officer
Sarabjeet Singh ADO (MN)

(Signature)
8/12/2024

(Signature)
9/12/2024

(Signature)
12/12/24

(Signature) Sir, F.T is put up for your kind perusal & signature p/s.

(Signature)
12/12/2024

(Signature)
Director

Uploaded
13/12/24

CEO: 473 mm
Date: 9/12/2024