

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/BNQT./2024/SZ/ 58

Dated:

20/12/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Green Lounge Premium Banquets running at ground floor and first floor in a building comprised of basement (small office & vacant), ground floor plus two upper floors (second floor is vacant) located at C-97, GF & FF, Mayapuri Industrial Area, Phase-II, New Delhi-110064, owned/occupied by M/s Green Lounge Premium Banquets was issued FSC by this department vide letter no. F.6/DFS/MS/GH/BNQT./2021/SZ/04 dated 10.12.2021. The premises was re-inspected by the officers concerned of this department on 11.12.2024 in the presence of Sh. Bablu Kumar (caretaker) and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (ground and first floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. 20/12/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 20/12/2024 at New Delhi.

ul Garg) Director Delhi Fire Service

Online application Id 2024111916992 dated 19.11.2024.

Copy to: - Executive Engineer (Bldg.), MCD, West Zone, Dr. Sahib Singh Varma Nigam Bhawan, Second Floor, Shivaji Enclave, New Delhi-110027: - for information regarding use of basement.

## Conditions for validity of Fire Safety Certificate: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. Use of the basement will only be allowed after permission from MCD, w.r.t. use and prior

approval of this department from fire safety point of view.

7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

## INSPECTION REPORT

1. Name & address of the building: M/s Green Lounge Premium Banquets, C-97, GF & FF, Mayapuri

Industrial Area, Phase-II, New Delhi-110064

: Basement, ground plus two upper floors (But banquet hall is only at 2. Building is comprised of

ground and first floor only)

: Group 'D' Assembly Building. 3. Type of Occupancy

Renewal Type of Case F.6/DFS/MS/GH/BNQT./2021/SZ/04 dated 10.12.2021 Details of Previous NOC

Fire Safety directives letter No : N/A : 11.12.2024 Date of inspection

: A.D.O. R.K. Yadav 8. Name of Inspecting Officer

9. Name and designation of officers

: Sh. Bablu Kumar (Caretaker) From the building side

: 2015 10. Year of Construction

: Online Id 2024111916992 dated 20.11.2024 11. Applicant's letter No.

S. No.	Minim	oplicant's letter No. : Or um Standards on fire prevention e safety U/R 33	Requirements as per FSC dt. 10.12.2021	Provided at site	Remarks MR/NMR		
1.	Access to building						
-T-60		I of an area and a second	09 m	Provided	M/R		
	•	Road width	05 m	Provided	MR N/A		
	:	Gate width Width of internal road	N/A	N/A	N/A		
2.	Number. Width, Type & Arrangement of Exits						
1	Non	ber of staircases		The second of the second of	M/R		
	a. Num	Upper Floors	Two	Three	5.000		
		Basements	Two	Two	M/R		
	h Wid	th of staircases					
	D. 111G		2.0 & 1.50 m	2.0, 2.18 & 2.18 m	M/R		
		Upper Floor Basements	2.0 & 1.50 m	2.10 & 2.12 m	M/R		
		ection of exits	27/4	N/A	N/A		
	c. Prote	Fire check door	N/A	N/A	N/A		
	•	Pressurization	N/A	IVA			
				Three	M/R		
	d. No.	of continuous staircases to	N/A	TOTAL STREET	M/R		
	terra	ace	1.50 m	Opening in hall	WIN		
	e. Wid	th of Corridor r Size	. 2.0 m	2.65, 2.20 & 2.30 m	MR		
3.	Compa	rtmentation	7	March February 1912			
			N/A	N/A	N/A		
	•	Fire check door Sealing of electrical shafts	N/A	N/A	N/A		
		Fire Rating of shaft door	N/A	N/A	N/A		
		Water Curtain	20100-62	N/A	N/A		
	1000	Fire Dampers	N/A N/A	N/A	N/A		
4.	Smoke Management System						
	A PORT L	and the state of	• Required	Exhaust fans are provided	M/R		
		Basements	Required	Natural Ventilation	MR		
	•	Upper floors	Required	Les es de la de			
5.	Fire Extinguishers						
		Total numbers	15 no.'s	Provided	M/F		
		Types	W/CO <sub>2</sub> / CO <sub>2</sub> type	Provided	M/F		
		IS marking	ISI marked	ISI marked	M/F		

•	First-Aid Hose Reels						
	m I I I I I I I I I I I I I I I I I I I	Two	Two	M/R			
	Total numbers on each floor	30 m	30 m	M/R			
	Length of hose reel hose     Nozzle diameter	5 mm	5 mm	M/R			
•	Automatic fire detection and alarming syste	Smoke/Heat	Provided	M/R			
	Type of detectors	N/A	Ground Floor	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	Required	Provided	M/R			
	Alternate source of power	N/A	At Exits	N/A			
	Hooters' Location	Dland	Provided	M/R			
3.	MOEFA	Required	Provided	M/R			
).	Public Address System	Required	Tiovided				
10.	Automatic Sprinkler System						
		Required	Provided	M/R M/R			
	Basement  Basement hell	Required	Provided	N/A			
	Banquet hall     Sprinkler above false ceiling	N/A	N/A	1071			
1	Internal Hydrants			1 1/2			
11.	222-1 337	100 mm	100 mm	M/R M/R			
	Size of riser/down-comer  Classification per floor	Two	Two	M/R			
	Number of hydrants per floor     Hose Box	Two	Two	1,21			
12.	Vord Hydrants						
	- 1 Los of hydrants	N/A	Three	MR MR			
	Total number of flydrants     Hose Box	N/A	Three	IVIA			
13.	Pumping Arrangements						
	Ground Level	N/A	Provided	M/R			
	Discharge of main Pump	N/A	55 m	M/R			
	> Head of Main pump	N/A	One	M/R			
	> Number of main pumps	N/A	Provided	M/R			
	<ul><li>Jockey Pump out put</li><li>Jockey pump head</li></ul>	N/A	55 m	M/R			
	> Jockey pump nead > Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	> Auto Starting/Manual Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			
	➤ Pump House Access  • Terrace level		000 I DM	M/R			
	> Discharge of pump	900 LPM	900 LPM 40 M	M/R			
	> Head of the pump	40 M	Provided	M/R			
	> Power Supply	Required Required	Provided	M/R			
	000 MA-2000 300-3000 10						
14.	Captive Water Storage for fire fighting	N/A	70,000 Ltrs	MR			
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	Required	Provided	M/R			
	➤ Fire service inlet ➤ Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	20,000 Ltrs.	20,000 Ltrs.	M/R			
	1 500						
			Provided	M/R			

7		4					
6.	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
7.	Standby power supply	Required	Provided	M/R			
8.	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19.	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Battery backup     Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings issued by this department vide Letter No. F6/DFS/MS/Banquet/2024/SZ/97 dated 14.08.2024.

Note: - Banquet Hall running at ground and first floor only of a building comprised of Basement (one-part small office and one part is vacant), ground, first floor (Banquet Hall) and Second floor (Vacant)

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/GH/BNQT./2021/SZ/04 dated 10.12.2021, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name: - R.K. Yadav Designation: - ADO(JKP)

DO (South West)

× 125

1/6/11/4

Directory My Mrs 100) M