GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 No.F6/DFS/MS/GH/NDZ/2024/505 Dated: 18 12/2024

FIRE SAFETY CERTIFICATE

Certified that the Mayur Guest House located at 51, Arakashan Road, Pahar Ganj, New Delhi comprised of Basement + Ground + Stilt + 03 Upper floors, Basement (storage), stilt floor (parking), Ground floor (reception + lobby), 1st floor to 3rd floor (08 guest rooms at each floor), total 24 guest rooms was earlier granted FSC by this department vide letter No F6/DFS/MS/GH/NDZ/2021/235 dated 19/07/21. Now, the premises was re-inspected by the officers concerned of this department on 11/12/24 in the presence of Sh. Bilavar Ali, care taker and found that the said guest house, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, stilt floor (parking), Ground floor (reception + lobby), 1st floor to 3rd floor (08 guest rooms at each floor), total 24 guest rooms up to third floor only, and valid up to three year from the date of in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 18 12 2024 at New Delhi by.

DIRECTOR Delhi Fire Service

Copy to:-

 The Commissioner, North MCD, Civic Centre, New Delhi: to ensure the occupancy as detailed and not to use any floor above third floor

 The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Online ID No. 2024112017049 dated 20/11/24

3. The Manager, Mayur Guest House 51, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 This FSC is valid for guest house ground to third floor only.
- Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned. Further, basement & stilt floor shall strictly be used as stipulated in BBL concerned.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape such as staircase, exits, corridor, etc shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building

Mayur Guest House at 51, Arakashan Road,

Pahar Ganj, New Delhi

2. Type of occupancy:-

Residential, Sub Division-A-1

B+ Gr. + Stilt + 03 Upper floors (total 24 Guest rooms) Basement (storage), stilt floor (parking), Ground floor (restaurant), 1st floor to 3rd floor (08 guest

rooms at each floor)

3. Type of case:-

Renewal

4. Details of previous FSC:-

No. F6/DFS/MS/GH/NDZ/2021/235 dated 19/07/21.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

11/12/24.

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO CC) Sh. Rajinder Atwal (DO/CD)

8. Name & designation of officer From the building side:-

Sh. Bilaver ali, Care taker

9. Year of construction:-

2009-10

10 Applicant's Las

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	N/A	NI/A	
	2) Gate width	N/A	N/A	N/A N/A	
	3)Width of internal road	N/A	(- 1.20 (- 1.50)		
2.	Number, Width Type & Arr	ongoment of F	N/A	N/A	
	A. Number of staircases	ats			
	1. Upper floors	01 No.	01 No.	100	
	2. Basements	02 Nos.	01 No.	MR	
	B. Width of staircase	02 1103.	UZ NOS.	MR	
5	1. Upper floors	1.40 mtr.	1.40 mtr.	MR	
	2. Basements	1 mtr.	1.35 & 1.10 mtr.	MR	
	C. Protection of exits		The artifulation of the state o	IVIK	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	01 Nos.	01 Nos.	MR	
	E. Width of corridor	01 mtr.	1.28 mtr.	MR	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation		_	IVIIC	
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	12 ACPH	Mechanical	MR	
	2) Upper floors	Required	provided	MR	
5.	Fire Extinguishers		JI J		
	1) Total numbers	10 Nos.	12 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	

N/39

	Vi	Required	Provided	MR 🌗
	3) ISI marking	Required	110.110	
6.	First-Aid Hose Reel	101	Provided	MR
0.	1) Total number of eachfloor	r 01	30 mtr.	MR
	2) Length of hose reel hose	30 mtr.	05 mm	MR
	3) Nozzle diameter	05 mm		IVAC
7.	Automatic Fire Detection &	& Alarming Sys	stem	MR
	1) Type of detectors CO type	Required	Provided	MR
	2) Location of main panel	Ground floo		N/A
	3) Location of repeater panel	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Ground floor		MR
0	MOEFA	Required	Provided	MR
8.	Public Address System	Required	Provided	MR
9.				
10.	Automatic Sprinkler System	Required	Provided	MR
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	IN/A		
2012	ceiling			
11.	Internal Hydrants	100 mm	100 mm	MR
	1) Size of riser/down-comer	01	Provided	MR
	2) Number of hydrants per	UI	1101100	
	floor	01	01	MR
	3) Hose box	01	101	
12.	Yard Hydrants	N/A	N/A	N/A
	1) Total number of hydrants	N/A N/A	N/A	N/A
	2) Hose box	IN/A	13/71	
13.	Pumping Arrangement	N/A	N/A	N/A
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	IN/A	
	pump	N/A	N/A	N/A
	b) Head of main pump		N/A	N/A
	c) Number of main pump	N/A N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	IVA	1977	
	stopping 2) Terrace level		1	_
	a) Discharge of pump	900 LPM	900 LPM /	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
<i>y</i> -	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fighting			
	Under ground tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
			N/A	N/A
	-/		N/A	N/A
	Very and the control of the control	12-140-140-140-1	10,000 ltr.	MR
15.		Required	Provided	MR

16.	Provision of Lifts.			
	Pressurization of lift shaft	N/A	N/A	N/A
	 b) Pressurization of lift lobby 	N/A	N/A	N/A
	 c) Communication in lift car 	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	N/A		

The above fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, restaurant at ground floor has been closed and photo along with under taking of the same is enclosed on file.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2021/235 dated 19/07/21, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is prepared and put up for kind perusal/approval please.

Signature of the Inspecting Officer

Name :- Rajinder Attwal Designation :- DO (CD)

Signature of the Inspecting Officer

Name :- Ravinder Singh Designation :- ADO (CC)

Dycho Loros

13/15/21

Director

Police

anatum Please, son putub for kno per

16/17/4