

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

ग्रिक आज़ादी वा अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2024/1240

Dated: 30 12 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Kalawati Public School located at B-98/27, Jaitpur, Near Gyan Mandir Road, Badarpur, New Delhi-44, comprised of Ground + 02 upper floors was granted Fire Safety Certificate by this department vide letter no.- F6/DFS/MS/School/2017/SZ/1027 dated 13.07.2017. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 23.12.2024 in the presence of Mrs. Prabha Chauhan (Manager) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the building/premises (Ground + 02 upper floors) is fit for occupancy of Group B "Educational Building" with effect from [30] [12] [24] [13] for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on. 30.1.2.24.....at New Delhi by

Delhi Fire Service

Copy to:-

- 1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
- 2. The Principal, M/s Kalawati Public School located at B-98/27, Jaitpur, Near Gyan Mandir Road, Badarpur, New Delhi-44.

Conditions for the validity of Fire Safety Certificate

- 1. The means of escape shall be kept unobstructed/unlocked for unhindered evacuation in case of an emergency.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

	LAT		PECTION REPORT				
1	Na	me & address of the building	M/s Kalawati Public School located at B-98/27, Jaitpur, Near Gyan Mandir Road, Badarpur, New Delhi-44.				
_	D.	ilding is some ' 1 C					
2	_	ilding is comprised of	Ground + 02 upper				
3	_	pe of occupancy	Group B- Education	Building (School)			
4		pe of case	Renewal				
5	_	tails of previous FSC	The second of expression and accompanies	2017/SZ/1027 dated 13	STATE SEALS		
6	rıı	e safety direction letter no.	F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated				
-	Do	ia aCinanastian	01.03.2011 23.12.2024				
7		te of inspection me of the inspecting officers	Rajesh Kumar Shukl	ADO (M. Poed)			
9	_	me of the designation of					
9		icer from the building side	Mrs. Pradna Chaunai	(Ivialiagei)			
10	_	ar of construction	2005 & 2013				
11	O-comp	plicant's letter no.	Outdoor diary no. 50	70 dated 08.08.2024			
S.No	-	nimum standard of fire	Requirement as	Provided at site	Remarks		
3.110	prevention and fire safety U/R		**************************************		MR/NMR		
	33	evention and fire safety Con-	por zemoso (y				
1		cess to Building:			1.97as		
•	A	Road width	Accessible	Accessible	MR		
	В	Gate width	NA	NA	NA NA		
	C	Width of internal road	NA	NA	INA		
2	Nu	mber, Width, Type and Arra	ngement of Exits:				
	A	Number of staircases		02 nos.	MR		
		a Upper floor	02 nos.	NA	NA		
		b Basement	NA	TV-			
	B	Width of staircases	1 staircase of 1.5 mtrs	1.25 m & 0.90 m (GF	MR		
		a Upper floor	or if main staircase	to FF) 1.10 m & 0.90 m (FF			
			width is < 1.5 mtrs an additional staircase of	1.10 m & 0.90 m (F1 to SF)			
			0.75 mtrrs width is	10 01)			
			required		NIA		
		b Basement .	NA	NA	NA		
	C	Protection of exits		NA	NA		
		a Fire check door	NA	NA NA	NA		
		b Pressurization	NA 01 no.	01 no.	MR		
	D	No. of continuous	VI no.				
	_	staircases to terrace Width of corridor	1.50 m	Provided	MR		
	E	Door size	1.0 mtrs. (for class	Provided	MR		
	F	Door size	rooms)				
3	Co	mpartmentation:		1274	NA		
,	A	Fire check door	NA	NA NA	NA		
	B	Sealing of electrical shafts	NA	NA NA	NA		
ŀ	C	Fire rating of shaft door	NA	NA NA	NA		
	D	Water curtain.	NA	NA	NA		
	E	Fire dampers	NA				
4	Sm	oke Management System:	NA	NA	NA		
	A	Basement	NA	NA	NA		
	B	Upper floor					
i.	Fire	Extinguisher:	04	06 nos.	MR		
-	A	Total numbers	06 nos.	CO ₂ & ABC	MR		
-	В	Types	CO ₂ & ABC	Provided Provided	MR		
+	C	ISI marking	ISI Marked	FIOVIDED	ALMILES, 56		
	Fine	t-Aid-Hose Reel:		01	MR		
	A	Total numbers of each floor	01 no.	01 no. 30 mtrs.	MR		
	B	Length of hose reel hose	30 mtrs.		MR		
1	C	Nozzle diameter	05 mm	05 mm	A.L.		

	A	Type of detectors	NA	NA	NA			
	В		NA	NA	NA			
	C		ŅA	NA	NA			
	D	Alternate source of power	NA	NA	NA			
	E		NA	NA	NA			
8	M	OEFA:	NA	NA	NA			
9	_	ablic Address System:	NA	NA	NA			
10		utomatic Sprinkler System:	34,434	Sept City				
	A	Basement	NA	NA	NA			
	В	Upper floor	NA	NA	NA			
		50.01.02.05 PE-280.00	NA NA	NA	NA			
_	C	Sprinkler above false ceiling	INA	INA				
11								
	A	Size of riser/down-comer	NA	NA	NA NA			
	В	Number of hydrants per floor	NA	NA	NA NA			
	C	Hose box	ΝA	NA	NA			
2	Ya	rd Hydrants:			1374			
	A	Total number of hydrants	NA	NA	NA			
	В	Hose box	NA	NA	NA			
3	3.3	mping Arrangements:	4					
		round level						
k .		Discharge of main pump	NA	NA	NA			
	a)		NA	NA	NA			
	b)	Head of main pump	NA NA	NA	NA			
	c)	Number of main pumps		NA NA	NA			
	d)	Jockey pump out put	NA	NA NA	NA			
	e)	Jockey pump head	NA	NA NA	NA			
	f)	Standby pump out put	NA	E - 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	NA			
t	g)	Standby pump head	NA	NA	NA NA			
	h)	Auto starting /manual stopping	NA	NA	NA NA			
ŀ	i)	Pump house access	NA	NA	INA			
+	Ter	race Level						
			450 LPM	450 LPM	MR			
	a)	Discharge of pump	40 mrts	40 m	MR			
	b)	Head of the pump	Required	Provided	MR			
	c)	Power supply	Required	Provided	MR			
1	d)	Auto starting of pump	•					
_	<u> </u>	tive Water Storage for Fire F	ighting:	1 2 2 2 1 2 1	N/A			
-		Underground tank capacity	NA	10,000 ltrs	NA			
_	A	Underground tank capacity	NA	NA	NA			
	В	Draw-off connection	NA	NA	NA			
_		Fire service inlet	NA	NA	NA			
	D	Access to tank	10,000 ltrs	10,000 ltrs	MR			
	E	Overhead tank capacity	Required	Provided	MR			
]	Exit	Signage:						
1	Prov	ision of Lifts:	NA	NA	NA			
-		Dressurization of lift shaft	NA NA	NA	NA			
$\overline{}$		Dressurization of III lobby	NA NA	NA	NA			
_		Communication in lift car	NA NA	NA	NA			
Ì	1	Firemen's grounding switch	NA NA	NA	NA			
-	2 1	iff signage	NA NA	NA	NA			
	tone	lby Power Supply:	INA					
6	Tant	ge Area:		NA	NA			
S		C /Al Ca.	NA					
S	7	Total area Location Frublic School located at B-98/27, Ja	- N	NA	NA			

19	M/s Kalawati Public School located at B-98/27, Jaitpur, Near Gyan Mandir Road, Badarpur, I Fire Control Room:					
	A	Detector system panel	NA	NA	NA	
	В	Flow switch panel	NA	NA	NA	
	C	PA system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plans	NA	NA	NA	
20	Special Fire Protection systems for protection of special Risks, if any:		NA		NA	

LEGENDS:- Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

The shortcoming issued to the building by this department vide letter no. F6/DFS/MS/School/SZ/2024/184 dated 23.04.2024 has been rectified by the school management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education circular no. 3298 to 3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2017/SZ/1027 dated 13.07.2017 is recommended to be renewed.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (Sp) Amules 26/10/

Director /

my