

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 424

Dated: 27/12/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Sambookas at shop no 2530, Ground floor, Hudson lane, Delhi 110009 in the building comprised of Basement, Ground plus three upper floor owned/occupied by Ms. Shrilly Chawla was issued FSC by this department vide letter F6/DFS/MS/2021/EH/388 31/12/2021. The restaurant premise was re-inspected by the officers concerned of this department on 16/12/2024 in the presence of Ms. Shrilly Chawla and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class-D "Assembly Building" and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27/12/2024 at New Delhi by

Copy to: -

1. The Addl. Commissioner of Police (Lic. /Branch), 1st Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MCD Portal ID 2024112817393 dated 28/11/2024)

2. The Public Health Department, MCD (Civil Line Zone), 16, Rajpura Road, New Delhi 110054.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

NIS

| | N/> | | 7/ | | |
|--------|---|--|---------------------------|-------------------|--|
| | INSPECTION REPORT | | आज़ादी का असन महोत्सून | | |
| | Name & Address of the Building | M/s Sambookas at shop no 2530, Ground floor Hudson lane, Delhi 110009 | | | |
| | Type of Occupancy | Group-D Assembly Building. | | | |
| | Building Comprised of | Basement, Ground Plus three upper floor (Restaurant running at ground floor only) | | | |
| 4 | Type of Case | Renewal | | | |
| 5 | Details of Previous NOC | | /EH/388 dated 31/12 | 72021 | |
| 6 | Fire Safety Directives Letter No | UBBL-2016 / NB | C Part-IV | P. 1 | |
| 7 | Date of Inspection | 16/12/2024 | | | |
| 8 | Name of the Inspecting Officers | ADO (BCP) | U-, III | | |
| 9 | Name & Designation of Officers from the building side | Ms. Shrilly Chawla | | | |
| 10 | Year of construction | 1975 | - SW 171 M2 19 | 20/11/0004 | |
| 11 | Applicant letter No. | | 024112817393 dated | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | UBBL/NBC Requirement | Provided at Site | Remarks MR/NMR | |
| 1 | Access to Building. | | 12 mtr | MR | |
| | Road width | 06 mtr | N/A | N/A | |
| | Gate width | N/A | | N/A | |
| | Width of internal road | N/A | N/A | IVA | |
| 2 | Number, width, type & arrangement of ex | its. | e soulski 6- | | |
| | a) Number of Staircase | Trips: | But Lack to | 27/4 | |
| | > Upper floors. | N/A | N/A | N/A | |
| | > Basement floor. | N/A | N/A | N/A | |
| | b) Width of Staircase | 112 a | protection to | | |
| | > Upper floors | N/A | N/A | N/A | |
| | > Basement floor | N/A | N/A | N/A | |
| | c) Protection of exits | The state of the s | | <u> </u> | |
| | > Fire check door | N/A | N/A | N/A | |
| | > Pressurization | N/A | N/A | N/A | |
| | d) No. of continuous staircase to terrace | Required | One | MR | |
| | e) Width of corridor | N/A | N/A | N/A | |
| | f) Door size | 1.50 mtr each | 2m, 1.50 mtr & 1.30 m | MR | |
| 3 | Compartmentation. | | | | |
| | Fire check door. | N/A | N/A | N/A | |
| | Sealing of electrical shafts. | N/A | N/A | N/A | |
| | Fire rating of shaft door. | N/A | N/A | N/A | |
| | Water curtain | N/A | N/A | N/A | |
| | Fire dampers. | N/A | N/A | N/A | |
| 4 | Smoke Management system. | 145,1 | du Come | no. | |
| | Basement | 30 ACPH | N/A | N/A | |
| | Upper floors | 12 ACPH | N/A | N/A | |
| 5 | Fire Extinguishers. | W-2017 | | | |
| | Total numbers | 03 Nos | 03 Nos | MR | |
| | Types | ABC/CO ₂ | ABC & CO ₂ | MR | |
| | ISI Marking | ISI marked | Provided | MR | |
| | First Aid Hose Reels. | | Wales and | | |
| 6 | First Aid Hose Reeis. | | | T | |
| 6 | Total numbers on each floor. | One | Provided | MR | |
| 6 | Total numbers on each floor. | One 30m | Provided Provided | 1000000000 | |
| 6 | | | TO SERVING A CONTROL OF | MR MR MR | |



| | | | | 1 |
|------|--|-----------------|----------|------------|
| | Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooter's location | N/A | N/A | N/A |
| 8 | MOEFA | Required | Provided | MR |
| 9 | Public Address System | N/A | NA | N/A |
| 10 | Automatic Sprinkler System | | | |
| | Basement | N/A | N/A | N/A |
| - | Ground floor. | N/A | Provided | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11 | Internal Hydrants. | | 11172 | 7 T |
| | Size of Riser/Down-comer | 100 mm | Provided | MR |
| | Number of Hydrant per floor | One | Provided | MR |
| | Hose box. | One | Provided | MR |
| 12 | Yard Hydrants. | | T | |
| | Total number of hydrants. | N/A | N/A | N/A |
| | Hose box. | N/A | N/A | N/A |
| 13 | Pumping arrangements. | | | |
| | Ground Level | | | |
| | Discharge of main pump. | N/A | N/A | N/A |
| | ➤ Head of main pump. | N/A | N/A | N/A |
| - 1 | Number of main pumps. | N/A | N/A | N/A |
| | Jockey Pump output. | N/A | N/A | N/A |
| | Jockey Pump head. | N/A | N/A | N/A |
| | > Standby Pump output. | N/A | N/A | N/A |
| 2.21 | > Standby Pump head. | N/A | N/A | N/A |
| | Auto Starting/Manual Stopping.Pump house access. | N/A | N/A | N/A |
| - | | IVA | IV/A | N/A |
| - 1 | Terrace Level Discharge of pump. | 450 LPM | Provided | / M |
| 1.1 | Head of pump. | 430 LPM 40 m | Provided | MR |
| - | Power supply. | | | MR |
| | > Auto starting of pump. | Required | Provided | MR |
| 14 | | Required | Provided | MR |
| 14 | Captive water storage for fire fighting. | NT/A | 27/4 | 27/4 |
| - | Underground tank capacity. Draw-off connection. | N/A | N/A | N/A |
| | Fire Service Inlet. | N/A | N/A | N/A |
| 1. 6 | Access to tank. | N/A | N/A | N/A |
| . 1 | Overhead tank capacity. | N/A | N/A | N/A |
| 15 | | 20,000 Ltrs | Provided | MR |
| | Exit Signage. | Required | Provided | MR |
| 10 | Provision of Lifts. | | | 1 |
| | Pressurization of lift shaft. | N/A | N/A | N/A |
| | Pressurization of lift lobby. | N/A | N/A | N/A |
| | Communication in lift car. Fireman's switch. | N/A | N/A | N/A |
| | Fireman's switch. Lift signage. | N/A | N/A | N/A |
| 17 | Standby Power Supply | N/A | N/A | N/A |
| | Refuge Area | N/A | N/A | N/A |
| | | i iv | | 107 |
| | Total area | N/A | N/A | N/A |
| 10 | • Location | N/A | N/A | N/A |
| 19 | Fire Control Room. | | | |
| | Detector system panel. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |

with the



| | Flow switch panel. PA system panel. Battery backup. Building floor plan. | N/A | N/A | N/A |
|----|---|-----|-----|-----|
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 20 | Special Fire Protection System for the Protection of special Risk, if any. | N/A | N/A | N/A |

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2021/EH/388 dated 31/12/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

20/12/2024